

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	SOMPO INSURAN	CE SINGAPORE PL	F	Ref:	CS3/SMO20014748/GUqf3e2	
	50 DAEEL 50 DL 40	NE #00.00	_		-1	
	50 RAFFLES PLAC SINGAPORE LANI	DE #03-03 DITOWERSINGAPORE 048623	L	Date:	09/06/2021	
			(	Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	FBN 7912A	Veh. Inspected		SLQ 7175B	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2003843/AGC	Excess (\$)		0.00	
	Assign From	AGNES CHAN SHU HUI	Assign Date		05/05/2021	
2. Vehicle Particulars & Condition						
	Make & Model	KIA FORTE K3 1.6A	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	KNAFJ411MH5717988	Colour		BLUE	
	Odometer	112926 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	BRIDGESTONE		5 mm	
	L/H Front Tyre	195/65 R15	BRIDGESTONE		5 mm	
	R/H Rear Tyre	195/65 R15	BRIDGESTONE		5 mm	
	L/H Rear Tyre	195/65 R15	BRIDGESTONE		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	22/12/2020	Inspection Date	!	06/01/2021	
	Survey held at	AUTO BULLOX PTE LTD				
	53 UBI AVENUE 1 #01-19 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				