

REF: C72/21005555/KV f3

ASSIGNMENT

Date: _____
/ TP RES / OD RES / EVA / INV / MV
Vehicle No: _____
M/Vs: Thiru Hey Heta

Veh No: Sms 80486 Yr Regn: 03, 20
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or (A)
Make: Toy Corolla Hybrid 1798
Colour: M.P. White A/C: Insured / Std / NI / NA
Sp. Reading: 49893 T/Radio: Insured / Std / NI / NA

SMT 7566P 066P
DMPCSNW00165392000
SNM21D202573/C2/IRENE

Eng/No: _____
C/No: JTNK93BE6003003429
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD A/Rim or

Excess: _____
rd) _____

Tyre Size: F: _____
R: 205/55R16
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

on) _____
had commenced its
at the time of inspection.
ue: _____
ort: _____ Consistent? : Yes or No
_____ Consistent? : Yes or No
_____ days Res.: Yes or No
_____ % 3 Val.: Yes or No

N/S	O/S

Front _____ Rear _____
R/Bal. 8 mm R/Bal. 8 mm
L/Bal. 8 mm L/Bal. 8 mm
D.O.A. 2/5/21 D.O.I. 5/5/2021
Survey held at _____

EP. / 24 HRS
Vehicle: IN / OUT
Person Contacted: _____

Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Action / Instruction
EST not ready
23/8/21 LS 4200 confirmed via whatsapp (Red 9598.75,69%)

: Prell. Report
 : Final Report

Days Of Repair: 3
Resurvey No. of Trip: 2

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:

Transport/Trc:	_____
S - RS: SI	_____
Partos	_____
Others	_____
TOTAL	_____

23/8/21-Typist
LS 4200