

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 06/05/2021

To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION

Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTHCVE000218

Accident Date : 01/05/2021

Vehicle No : GBJ-9147-A

Make & Model : ISUZU NHR87AUE4AA 1.9 G (M) EURO 6

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
List Item			
1	FRONT BUMPER <i>de</i>	1,434.00	
1	FRONT BUMPER BRACKET RH <i>bt</i>	298.00	
1	HEADLAMP RH <i>cm</i>	1,344.00	
1	SIDE LAMP RH <i>cm</i>	362.00	
1	FRONT DOOR RH	RESTORE	
1	FRONT CORNER PANEL RH	RESTORE	
	Sub Total	3438.00	
	Discount 15% On Parts	(515.70)	
Special Nett Item			
1	FRONT DOOR ADVERTISEMENT <i>nm</i>	150.00	

Date : 06/05/2021

To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTHCVE000218 Accident Date : 01/05/2021

Vehicle No : GBJ-9147-A Make & Model : ISUZU NHR87AUE4AA 1.9 G (M) EURO 6

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	ROC STICKER <i>see</i>	20.00	
	Sub Total	170.00	
Labour & Misc			
	LABOUR TO FACILITATE REPAIR	600.00	<i>300</i>
	TO RESPRAY AFFECTED AREAS	600.00	<i>300</i>
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	
	Sub Total	1230.00	

4,322.30

Remarks:

4 days / part by part / Resny before print

SUB TOTAL

GST 7.0 % 302.56

TOTAL 4,624.86

Surveyor's name:

RASUL - Hp 90010068

Principal's name: ETHOZ Group Ltd

Survey Date & Time: *06/05/21 @ 1535*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

PAGE : 2

Signature:

Date: