

ASS. REC. BY:

REF:

CS/SMR/21005571/Kuf3

C

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

SMG 2184Z

at Workshop m/s

1 Key Yp Sy

of

Insured:

SHB 469B

Policy No.

Claims No.

TAX/05/21/2003

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMG 2184Z

Yr Regn:

12, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy

Pier 9

G.C.C

1896

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

157501

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

M14FZ 28143900060331

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Kspn

185/60R15

R: APHJ

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

9

mm

L/Bal.

6

mm

L/Bal.

9

mm

D.O.A.

2/15/21

D.O.I.

7/5/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear ch

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 EST not ready

22/6 11:00 am 30501

Confirmed

5 repair days.

(RED \$8861; 74%)

Date/Time, File Pass to?



: Prel. Report

1) 5/7 TYPIST



: Final Report

Date/Time, File Return to?

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format :

TP

Lump Sum / L.B. (\$

\$3050

Ku

# AERO GARAGE PTE LTD

Blk 160, Sin Ming Drive, #08-07 Sin Ming AutoCity, Singapore 575722

Tel : 6266 9511 Fax : 6266 9512

Vehicle No : SMG2184Z  
Vehicle Model : Toyota Sienta

Not Authorized

11 Sep 8 3050h  
Resurvey After Paint

5 days

## Estimate Repair Cost

No.	Qty	Parts List Items	
1	1	Rear bumper (LH+CENTRE+RH)	\$ 807.10 ✓
2	2	Rear bumper retainers	\$ 85.30 X
3	2	Rear bumper brackets	\$ 110.20 X
4	2	Rear bumper reflectors	\$ 106.90 Lt
5	1 set	Rear bumper clips	\$ 40.00 ✓
6	1	Rear tailgate	\$ 1,040.40 ✓
7	1	Rear tailgate centre logo	\$ 45.90 ✓
8	1	Rear tailgate outer chrome handle	\$ 108.30 X
9	1	Rear tailgate lock	\$ 359.50 X
10	2	Rear tailgate hinges	\$ 133.60 X
11	2	Rear tailgate dampers	\$ 209.10 X
12	1	Rear tailgate weatherstrip	\$ 168.50 ✓
13	1	Rear tailgate "G" emblem	\$ 43.20 ✓
14	1	Rear tailgate "SIENTA" emblem	\$ 78.10 ✓
15	1	Rear tailgate wiper arm	\$ 201.90 X
16	1	Tail lamp (outer)	\$ 350.90 X
17	1	Tail lamp (inner)	\$ 241.10 X
18	1	Rear end panel	\$ 617.40 ✓
19	1	Rear end panel top garnish	\$ 219.90 X
20	1	Rear floor panel	\$ 706.30 X
21	1	Rear spare tyre top board	\$ 599.40 X
22	1	Rear exhaust silencer	\$ 1,012.10 X
23	1	Rear exhaust silencer mounting	\$ 85.90 X
258 Total			\$ 7,371.00

## Parts Special Nett Items

24	1	Rear number plate	\$ 60.00 X
25	1 set	Reverse sensor	\$ 300.00 200sm
26	1	Reverse camera	\$ 250.00 X
			\$ 610.00
Total Parts			\$ 7,981.00

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Labour

1	Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	\$ 1,500.00	60¢
2	To putty and respray painting on affected areas.	\$ 1,200.00	60¢
3	To remove, replace rear tailgate fittings to facilitate repair.	\$ 350.00	60¢
4	To remove, replace rear windscreen glass.	\$ 200.00	12¢
5	To remove, replace reverse camera.	\$ <del>nn</del> 200.00	X
6	To remove, replace reverse sensor.	\$ 150.00	5¢
7	To remove, replace rear exhaust silencer.	\$ <del>nn</del> 250.00	X
8	To check wiring and lightings.	\$ 80.00	2¢

Total Labour	<u>\$ 3,930.00</u>
--------------	--------------------

Total Parts and Labour	<u>\$ 11,911.00</u>
------------------------	---------------------

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GlA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	03/05/2021 17:16 (SGT)
Date of Accident	02/05/2021 17:20 (SGT)
Exact Location of Accident	Victoria St, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMG2184Z
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	COSMO AUTOMOBILES RENTAL PTE LTD
Company Reg No	2XXXXX129M
Email Address	andrew@cosmoautomobiles.com.sg
Mobile Phone No	(Phone) +65-90990920
Alternative Phone No	+65-90990920

#### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Sienta
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1500

#### INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	SPMF1000000426
Cover Note Number	-

#### DRIVER

Name of Driver	HENG BOON PIN
NRIC No	SXXXX869A

Date Of Birth	17/09/1979
Occupation	Outdoor
Date Of Driving Pass	04/12/2000
Driving experience	20 YEARS AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-81576008
Alt. Phone Number	-
Email Address	bpheng@gmail.com
Address	BLK 677A JURONG WEST ST 64 #09-273
Address complement	-
Postcode	641677
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO POLICE REPORT.

NOTE: VEHICLRE REPAIR AT OWNER'S PREFERRED W/SHOP.

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB469B
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

# INJURED PERSONS DETAILS

## INJURED 1

Name of injured person	HENG BOON PIN
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SMG2184Z
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	-

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


(a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")


- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature / Date & Time

 3/5/21  
Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel

### Sketch Plan







## Describe Circumstances of the Accident

Refer to police report

(1 page)

## Declaration

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature / Date & Time  
  
Driver's Signature (if driver is not the policyholder) / Date & Time  
3/5/21  
Witnessed by Reporting Centre Personnel