



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/05/2021

User ID : BoonChewTay

Section A - Accident Details

Registration Number	SG1754P
Case Reference Number	BUS05/21/1001
Registration Date	23/5/2018
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22 MAN E6
Name of Driver	Yap Chiew Kung
Type of Accident	Side Swipe
Accident Date and Time	2/5/2021 11:08 AM
Accident Reported Date and Time	5/5/2021 11:47 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG1754P-LEFT REAR PORTION SBP1186C (TP) INSURED WITH
Prepared Date and Time	5/5/2021 1:07 PM
Chassis Number	WMAA22ZZ0JF006863
Message	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00
Total Spray Cost	\$772.00	\$0.00
Total Spare Part Cost	\$6,346.78	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$8,708.78	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	4 days
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	05/05/2021 1:26 PM	
Signature		☒
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Steve (LKK)

P/P

6/5/21, 12 mp

My BL Sy

4 days

Wm PL



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757107
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/05/2021

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	\$1,590.00	1325
total Labour	\$1,590.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$772.00	602
total Spray Painting & Panel Beating	\$772.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
010004	BODY LH	A01001-CW560	PANEL, SIDE L10, W FRAME, FOR MAN A22 BUS	1.00	\$980.40	10.00	\$882.36	Replace	XR
010005	BODY LH	A01001-CW561	PANEL, SIDE L11, FOR MAN A22 BUS	1.00	\$1,092.50	10.00	\$983.25	Replace	XR
013424	Body	155-2-2-009008	N/S FRP REAR LAMP COVER	1.00	\$975.00	10.00	\$877.50	Replace	XR
010002	BODY LH	A01001-CW558	PANEL, SIDE L8, FOR MAN A22 BUS	1.00	\$330.70	10.00	\$297.63	Replace	XR
010317	Body	4000F06-HING732	HINGE, LH, SIDE FLAP, FOR MAN A22 BUS	2.00	\$181.20	10.00	\$326.16	Replace	XR
010318	Body	4000F06-HING733	HINGE, RH, SIDE FLAP, FOR MAN A22 BUS	2.00	\$181.20	10.00	\$326.16	Replace	OT
010411			GAS SPRING 22N	1.00	\$94.90	10.00	\$341.64	Replace	OT
010314	BODY LH	S06006-CW571	PANEL, FRAME SIDE L10, FOR MAN A22 BUS	1.00	\$266.00	10.00	\$239.40	Replace	XR
010315	BODY LH	S06006-CW576	PANEL, FRAME SIDE L11, FOR MAN A22 BUS	1.00	\$1,610.00	10.00	\$1,449.00	Replace	XR
021335	CONSUMABLE	Sikaflex-265	SEALANT, SIKATACK-MOVE TRANSPORTATION	2.00	\$37.00	0.00	\$74.00	Replace	X N/A
012270		68122080	LATCH, LEVER SEALED, NON-LOCKING, FOR ADL	4.00	\$137.42	0.00	\$549.68	Replace	CHT
total					\$5,886.32		\$6,346.78		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third-party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: