

ASS. REC. BY: FormREF: CS/CT121005609/R19f3

144B

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV


To Inspect Vehicle No: SLF 797Kat Workshop m/s WAH HONG MOTORof 38, JOH GUAN RD EAST #01-36Insured: CTIPolicy No. DMPCSNW00189692000Claims No. SNM21D202647C2

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 62K

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLF 797K Yr Regn: 2016 / Anh

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda MOBILIO SV 1.5 CVT c.c. 1497Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 040132 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MRHDD48706P000234

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orMod: Nil / SIRM / STD AIR / orTyre Size: F: 185/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or . \_\_\_\_\_

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 06/05/21

Survey held at

WAH HONG

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 12/05/21Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair limit - 20K

20/05/21 @ 5.27pm revised to Irene Tay via Merimen

29/06/21 @ 11.24am Rasul finalised with Melvin LS \$2350. 5 days. (Red \$1957.40. 45%)

Date/Time, File Pass to?



: Prel. Report

1) 29/06 Typist



: Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Quisrs

TOTAL

Add Fee:



Site Insp (\$ \_\_\_\_\_)



Interview (\$ \_\_\_\_\_)



Tech. Invs (\$ \_\_\_\_\_)



Weekend (\$ \_\_\_\_\_)

Report Format: MER-TPLump Sum / T.B.R. : 2350





# Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SLF797K HONDA MOBILIO SV 1.5 CVT

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
	<b><u>PARTS (LIST ITEMS)</u></b>			
1	Boot lid <i>bt</i> ✓		887.00	
1	Boot lid lock <i>X</i>		190.00	
1	Boot lid weatherstrip <i>re</i> ✓		97.00	
1	Rear windscreen moulding <i>re</i> ✓		150.00	
1	Boot lid emblem "Mobilio" <i>re</i> ✓		36.00	
1	Boot lid emblem "RS" <i>re</i> ✓		35.00	
1	Boot lid emblem "i-vtec" <i>re</i> ✓		29.00	
1	Boot lid logo badge <i>X</i>		28.00	
1	Rear bumper <i>de</i> ✓		464.00	
2	Rear bumper side retainer LH/RH @2*\$46 <i>X</i>		92.00	
1	Rear bumper center outer chrome <i>re</i> ✓		223.00	
1	Rear bumper sponge LH/RH @2*\$66 <i>?</i>		132.00	
1	End panel <i>repair</i>		315.00	
		Part Items	2678.00	
		Total:	-20% -535.60	
			2142.40	
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	Rear bumper clips <i>re</i> ✓		35.00 ✓	
1	End panel sealant <i>X</i>		60.00 <i>X</i>	
		SN Items Total:	95.00	
		Total Parts	2237.40	



# Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SLF797K HONDA MOBILIO SV 1.5 CVT

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
1	<b>LABOUR</b> To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	<del>800.00</del>	500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	<del>800.00</del>	600
3	To remove/refix/replace wiring system at accident damaged area and check for all electrical proper function	60.00	X
4	To perform anti-rust treatment on affected areas	<del>60.00</del>	40
5	To remove and refit/replace rear compartment fitting, trimmings, garnish and etc	<del>100.00</del>	60
6	To remove and refix/replace boot lid fitting, trimmings, garnish and lock mechanism	<del>100.00</del>	60
7	To remove and replace rear windscreen	<del>150.00</del>	120
Labour Total :		2070.00	
TOTAL (PARTS & LABOUR):		4307.40	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rahul

Hp 900 1006 8

5 days

4s

12/05/21 @ 1000

Resy after repair



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	07/05/2021 12:07 (SGT)
Date of Accident	06/05/2021 16:35 (SGT)
Exact Location of Accident	Near 54 Mas Kuning Terrace, Singapore 126885
Additional Location Information	ALONG CLEMENTI AVE 2 TOWARDS WEST COAST ROAD
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SLF797K

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	WUN YOKE CHAN
NRIC No	SXXXX144B
Email Address	YCWUN@YAHOO.COM
Mobile Phone No	(Phone) +65-93866557
Alternative Phone No	(Home) +65-93866557

#### VEHICLE PARTICULARS

Manufacturer	Honda
Model	Mobilio
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1496

#### INSURANCE COMPANY

Name of Insurance Company	Direct Asia Insurance (Singapore) Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	MT/00824575
Cover Note Number	-

#### DRIVER

Name of Driver	WUN YOKE CHAN
NRIC No	SXXXX144B



Date Of Birth ..... 20/06/1960  
 Occupation ..... Indoor  
 Date Of Driving Pass ..... 29/09/2008  
 Driving experience ..... 12 YEARS AND 8 MONTHS  
 Gender ..... Female  
 Mobile Number ..... (Phone) +65-93866557  
 Alt. Phone Number ..... (Home) +65-93866557  
 Email Address ..... YCWUN@YAHOO.COM  
 Address ..... BLK 510, JURONG WEST ST 52  
 Address complement ..... #09-110  
 Postcode ..... 640510  
 Is the driver the policyholder? ..... Yes  
 If No, Relationship of the Driver with the Insured ..... -  
 Does Driver Own Other Vehicles? ..... No  
 Vehicle Registration Number of Other Vehicle Owned by Driver ..... -  
 Insurance Company of Other Vehicle Owned by Driver ..... -

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident ..... Collision - Head to Rear  
 Weather Conditions ..... Clear  
 Road Surface ..... Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? ..... No  
 Number of vehicles involved in the accident ..... 2  
 Was anybody injured in the Accident? ..... No  
 Was any injured conveyed to hospital by ambulance? ..... -  
 Was any other material or property damaged? ..... Yes  
 Number of Passengers (Including Driver) ..... 3  
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? ..... No

#### PASSENGER 1

Name ..... SIN SAU FONG  
 Gender ..... Female

#### PASSENGER 2

Name ..... WUN KENG MUM  
 Gender ..... Male

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? ..... No  
 Was notice of intended Prosecution given? ..... No  
 If yes, against whom? ..... -

#### CIRCUMSTANCES OF ACCIDENT

ON 6/5/2021 @ ABOUT 1635HRS, MY VEHICLE A SLF797K WAS STATIONARY AT THE TRAFFIC JUNCTION ALONG CLEMENTI AVE 2 TOWARDS WEST COAST ROAD LP49. WHEN TRAFFIC LIGHT TURNS GREEN, VEHICLES IN FRONT OF ME STARTED TO MOVE OFF SLOWLY, WHILE I WAS ABOUT TO PROCEED.

SUDDENLY, I FELT A HUGE IMPACT FROM THE REAR. I WAS SHOCKED AND ALIGHTED TO CHECK AND SAW THAT VEHICLE B SLP7980K FRONT HAD COLLIDED ONTO THE REAR OF MY VEHICLE A SLF797K.

WE THEN TOOK SOME SCENE PHOTO WITHOUT SWIFTING AWAY AND EXCHANGED PARTICULARS FOR INSURANCE CLAIM.

#### ATTACHMENT(S)

Are accident photos available for attachment? ..... Yes  
 Was there any video captured by Car Camera? ..... No

Was there any audio recorded? ..... No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number .....	SKP7980K
Vehicle Manufacturer .....	-
Vehicle Model .....	-
Vehicle Variant .....	-
Vehicle Colour .....	-
Vehicle Category .....	Private car
Name of Driver .....	JOSHUA TAN JIA XUAN
Contact Number .....	(Phone) +65-97573439
Address .....	-
Address complement .....	-
Postcode .....	-
Insurance Company Name .....	China Taiping Insurance (Singapore) Pte. Ltd.
Nature Of Damage .....	-
Details of property damaged in accident .....	-
No. Of Passenger (Including Driver) .....	-



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time  
7/5/21 11:23 am

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

CLEMENTI AVE 2	→
_____	→
_____	→
B <input checked="" type="checkbox"/> A <input checked="" type="checkbox"/>	↙

WEST COAST RD

A - SLF 797K

B - SKP 7980K



Describe Circumstances of the Accident

On 6/5/2021 @ 1635 HRS, my vehicle A (SLF 797K) was stationary at traffic junction along Clementi Ave 2 towards West Coast Road (LP49). When traffic <sup>light</sup> turns green, vehicles in front of me <sup>proceed,</sup> ~~stop to move on~~ <sup>slowly</sup> while I was about to <sup>proceed,</sup> suddenly I felt a huge impact from the rear. I was shocked and attempted to check and saw that Vehicle B (SRP 7980K) had collided onto the rear <sup>then took some scene</sup> of my vehicle A (SLF 797K). We <sup>then took some scene</sup> exchanged photos without swifling away and particulars for insurance claim.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

7/5/21 11.23am

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel





## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	144B

### Vehicle Details

Vehicle No.:	SLF797K
Vehicle to be Exported:	No
Intended Deregistration Date:	08 May 2021
Vehicle Make:	HONDA
Vehicle Model:	MOBILIO SV 1.5 CVT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	L15Z12872823
Chassis No.:	MRHDD4870GP000234
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$18,849.00
Original Registration Date:	12 Aug 2016
First Registration Date:	12 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$18,849.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Aug 2026
PARF Rebate Amount:	\$14,136.00

### Intended COE Rebate Details

COE Expiry Date:	11 Aug 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,301.00
COE Rebate Amount:	\$27,500.00
<b>Total Rebate Amount:</b>	<b>\$41,636.00</b>

The information contained herein is correct as at 07 May 2021

OK



# Honda Mobilio 1.5A RS i-VTEC Luxe

## Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**Price****\$62,800****Depreciation** ?

\$10,240 /yr

[View models with similar depre](#)**Reg Date**

02-Aug-2016

(5yrs 2mths 15days COE left)

**Mileage**

82,000 km (17.1k /yr)

**Manufactured** ?

2016

**Road Tax** ?

\$684 /yr

**Transmission**

Auto

**Dereg Value** ?

\$41,391 as of today (change)

**OMV** ?

\$18,849

**COE** ?

\$52,301

**ARF** ?

\$18,849

**Engine Cap**

1,497 cc

**Power**

88.0 kW (118 bhp)

**Curb Weight** ?

1,160 kg

**No. of Owners** ?

2

**Type of Vehicle**

MPV