

INS. CASE OWNER:

Chee Heng

CC 4/AIG1702

0351, R2/2011

LKK:

IDAC:

Surveyor:

Rahul

DOI:

ASSIGNMENT

Date / Time:

24/10/11

Registered in Merimen:

24/10/11

Pre-assign / CCU / FTE



Insured Vehicle No. :

SF 9321C

Name of Insured :

JUTHAR SINGH

Insured Tel No. :

HP:

Claim No. :

1965709510 SG

Policy No. :

Make / Model :

AUDI A6 2.0 TFSI MU

Place of Accident :

AYE SLIP RD TO LONER
DELTA RD

Excess Sec II : \$

D.O.A. :

14/10/11

Is driver the owner?

(YES ☒ NO)

Nature of Accident :

If NO, Driver Name / Age: MEENAKSHI SINGH

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No. : 9125 0050

(V/ ☒ YES / NO)

Insured Liability :

%

Final ? Yes / No

SKD 18785

INSRS:
WSP:
Tel:
Liability:
RMKS:2A
AutomobileINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SKD 18785 - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(

Agreed / Assessed) BOLA S/N No. : 17.

If NO or B 28, Ass. Lia:

Repair Cost:

\$

Loss of Rental (LOR):

\$

(

days)

Loss of Use (LOU):

\$

(\$

x

days)

Loss of Income (LOI):

\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$

Medical:

\$

Disbursement:

\$

(e.g. Tow/ Independent)

Legal Cost

\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

\$

Global Sum \$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$

Name 1:

Payee 2: (Strike if N.A.)

\$

Name 2:

Payee 3: (Strike if N.A.)

\$

Name 3:

79m

REF: AIG

62760

ASSIGNMENT

From: Date: 24/10/17

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKD 1838 S

at Workshop m/s 3A Automobile

of 120, Lower Delta Rd #02-15, 169208

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: 20. % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKD 1838S Yr Regn: 2011 / MOV

Type: M / Car / M / Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA COROLLA MTX 1.6L 1598

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: 120032 TiRadio: Insured / Std / NI / NA

Eng/No:

C/No: MR053 REE 104125818

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S / STD A/Rim or

Tyre Size: F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WETLAKG

Front: Rear

R/Bal: S mm R/Bal: S mm

L/Bal: S mm L/Bal: S mm

D.O.A. 19/10/17 D.O.I. 24/10/17

Survey held at 3A Automobile

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

UIC A 2000 (Red) # 1252-40 / 474.

Date/Time: File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time: File Return to?

Survey Fee:

Transportation:

2)

Add Fee: ☐ : Site Insp (\$)

☐ : S + RS \$

☐ : Interview (\$)

Photos

☐ : Tech Invs (\$)

Others

☐ : Weekend (\$)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CC4/AIG17020351/R1pb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120			Date : 24-10-2017	
			Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKF 9321C	Veh. Inspected	SKD 1838S	
Policy No.		Coverage (%)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	24/10/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	19/10/2017	Inspection Date	24/10/2017	
Survey held at	3A AUTOMOBILE PTE LTD BLK 120 LOWER DELTA ROAD #02-15 SINGAPORE 169208			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

3A Automobile Pte Ltd

No 120 Lower Delta Road #02-15 Cendex Centre Singapore 169208 Tel: 6223 1122 Fax: 6738 6666

Estimate Report

Date: 19-Oct-2017

Policy Number: 999995236 / 100754333-000001

Vehicles Number: SKD1838 S

AMERICAN INTERNATIONAL GROUP

Make and Model: Toyota Corolla Altis 1.6 Auto

78 Amoy Street

Date Of Accident: 19-Oct-2017

Singapore 069897

Tel: 64191000

Attn: Motor Claim Department

(Claim Officer)

Fig. 68357416

Unit	List Items	Units	Price	Prices
1	pc Rear Boot		\$290.00	\$290.00
2	pc Rear Boot Hinges		\$15.00	\$30.00
1	pc Rear Weatherstrip		\$45.00	\$45.00
1	pc Rear Boot Top Lock		\$40.00	\$40.00
1	pc Rear Boot Bottom Lock		\$10.00	\$10.00
1	pc Rear Boot Toyota Logo		\$25.00	\$25.00
	pc Rear Boot Wording		\$20.00	\$20.00
1	pc Rear Bumper		\$175.00	\$175.00
1	pc Rear Bumper Side Retainer L/R		\$25.00	\$50.00
8	pc Rear Bumper Clips		\$1.50	\$12.00
2	pc Rear Bumper Reflector L/R		\$18.00	\$36.00
1	pc Rear Bumper Foam		\$50.00	\$50.00
1	pc Rear Bumper Rear End Panel		\$180.00	\$180.00
1	pc Rear LHS Tailamp Assy		\$110.00	\$110.00
1	pc Rear LHS Fender Shield		\$16.00	\$16.00
8	pc Rear LHS Fender Shield Clips		\$1.50	\$12.00
1	pc Rear Panel Top Covering		\$75.00	\$75.00

\$1176.00

Mark up

15%

\$176.40

\$200.00

\$1,552.40

Labour Charges

		To Remove & Replace the Damaged Parts as Listed Above, including Reinstatements of necessary Attachments & Fittings to Facilitate Repairs, Jack, Panel Beat & Reshape the Affected Parts & Components, Correct & Realign the Necessary Parts				\$1,200.00
		To Provide Skill Labour & Material to do Surface Treatment / Epoxy Treatment and to Respray with 2K Paint on Front Right Hand Side Door & Right Side Bottom Side Skirt with Oven Spray Booth Facilities				\$1,000.00
Total						\$3,752.40

Yours faithfully,

3A Automobile Pte Ltd

Person to contact : Dennis

Mobilephone: 97868677

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date:

805

800

RASUL

Hp 90010068

8 days

L/S

24/10/17 @1230

Recovery after repair



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG17020351/R1pb3

01 NOV 2017

JUJHAR SINGH
9 NATHAN ROAD
#22-04
SINGAPORE 248730

Dear Sir/Madam,

ACCIDENT INVOLVING SKF 9321C & SKD 1838S ON 19/10/2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from SKD 1838S against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG
Case Handler
DID: 6742 3197
FAX: 6741 4108
Email: chewht@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Tuesday, 20 November 2018 5:24 PM
To: 'winnie.fan@bkw.sg'
Cc: Rasul (LKKAuto)
Subject: Your ref: SKD 1838S *Our Ref: CC4/AIG17020351/R1pb3 [ACCIDENT INVOLVING SKF 9321C(AIG) & SKD 1838S ON 19/10/2018]

Your ref: **SKD 1838S** **WITHOUT PREJUDICE**
Our Ref: CC4/AIG17020351/R1pb3

Dear Sir/Madam,

ACCIDENT INVOLVING SKF 9321C(AIG) & SKD 1838S ON 19/10/2018

We refer to the above matter.

For COR, we propose L/sum \$2,000.00(before GST) with 8 repair days.

Kindly confirm.

*** Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Friday, 29 March 2019 10:30 AM
To: 'Loh, Chee-Heng'
Cc: Admin A
Subject: RE: 1965709510SG // LKK REF: CC4/AIG17020351/R1pb3

Hi Chee Heng,

Contents noted.

We will proceed to temporarily close this outstanding claim file and submit our wp report to your good-office.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Loh, Chee-Heng <Chee-Heng.Loh@aig.com>
Sent: Wednesday, 27 March 2019 7:20 PM
To: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Subject: RE: 1965709510SG

Dear Hsiao Tong,

Kindly proceed to submit report for closure within the next 2 weeks since no activity.

Thank you.

Best regards,

Loh Chee Heng

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1881

Chee-Heng.Loh@aig.com | www.aig.sg



Celebrating 100 Years:
Visit 100.aig to learn more.

Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Loh, Chee-Heng
Sent: Friday, 25 January 2019 3:50 PM
To: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Subject: RE: 1965709510SG

Dear Hsiao Tong,

Kindly let us have an update on the case.

Thank you.

Best regards,
Loh Chee Heng
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way #08-16 Singapore(079120)
Tel +(65) 6419 1881
Chee-Heng.Loh@aig.com | www.aig.sg



Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Admin-D (LKKAUTO) [<mailto:admin-d@lkkauto.com>]
Sent: Friday, November 23, 2018 5:23 PM
To: Loh, Chee-Heng; Hsiao Tong (LKKAUTO)
Cc: Admin A; assignments
Subject: RE: 1965709510SG

Dear Mr Loh,

Thank you for your email.

Dear Hsiao Tong,

Kindly assist. Our Ref: CC4/AIG17020351/R1pb3

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Loh, Chee-Heng [<mailto:Chee-Heng.Loh@aig.com>]

Sent: Friday, 23 November, 2018 5:03 PM

To: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>

Subject: 1965709510SG

Dear Sirs,

Kindly let us have an update on the case.

If there is no activity for more than 12 months, kindly upload report for closure.

Thank you.

Best regards,

Loh Chee Heng

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1881 | Fax +(65) 6835 7416

Chee-Heng.Loh@aig.com | www.aig.com.sg

Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and

any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement






































CLAIM SUBFOLDER TRACKING











Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Oct 2017 Edit Reg		24 Oct 2017 00:00 Edit Adj Rpt	\$S\$2,000.00 Edit Estimates	\$S\$2,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	JUJHAR SINGH , ID: 57468662A								
Main Claimant:	BKW Rent A Car Pte Ltd , Co. Reg. No.: 200106276D								
Vehicle Reg. No.:	SKD1838S	Date of Loss:	19/10/2017 00:00 - :59 [71 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1965709510SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SKF9321C	Policy No. (Claimant):	999995236/100754333-00000						
		Excess:							
Repairer:	3A Automobile Pte Ltd (HQ) 120 Lower Delta Road, #02-15, Cendex Centre, 169208 Tiong Bahru - Tel: 62231122								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 02/11/2017]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (25/10/2017): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKD1838S (1965709510SG)
[SKF9321C]
TP
BKW Rent A Car Pte Ltd
Oct 19 2017 12:00AM
[JUJHAR SINGH]
3A Automobile Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	17/03/18 15:49	Odometer Reading								 Load JPG	<input checked="" type="checkbox"/>
2	17/03/18 15:49	Chassis Number								 Load JPG	<input checked="" type="checkbox"/>
3	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
4	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
5	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
6	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
7	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
8	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
9	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
10	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
11	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
12	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
13	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
14	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
15	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
16	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
17	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
18	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
19	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
20	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
21	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
22	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
23	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
24	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
25	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
26	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
27	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
28	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
29	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
30	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
31	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
32	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
33	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
34	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
35	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
36	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>
37	17/03/18 15:49	General View								 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	17/03/18 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
39	17/03/18 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
40	17/03/18 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
41	17/03/18 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
42	17/03/18 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
43	17/03/18 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
44	17/03/18 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
45	17/03/18 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
46	17/03/18 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
47	17/03/18 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
48	17/03/18 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
49	17/03/18 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
50	17/03/18 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
51	17/03/18 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
52	17/03/18 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
53	17/03/18 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
54	17/03/18 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
55	17/03/18 15:49	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/10/17 16:42	EMAIL FROM AIG DD 23102017	 Load PDF	
2	24/10/17 16:42	WKSP NOTICE	 Load PDF	
3	26/10/17 18:15	TP ESTIMATE- MARKED	 Load PDF	
4	26/10/17 18:15	TP GIA REPORT	 Load PDF	
5	29/03/19 10:35	Email to AIG dd 290319	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	25/10/17 10:37	OI GIA report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG17020351/R1PB3Q2

Date: 03/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SKD1838S

Insured Vehicle No : SKF9321C

Date of Loss: 19/10/2017

Nature of Claim: TP

Claim No: 1965709510SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKD1838S**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: HIDDEN

Reg. Date: 01/11/2011 (Man. Year: 2011)

Chassis No: MR053REE104125818

Colour: Grey

Odometer: 120032 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 5 mm

Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,552.40	929.00	623.40	40.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,600.00	600.00	27.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,752.40	2,529.00	1,223.40	32.60
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	3,752.40	2,000.00	1,752.40	46.70
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 24/10/2017

Date Inspected: 24/10/2017 Inspected At:

 3A Automobile Pte Ltd (HQ)
 120 Lower Delta Road, #02-15, Cendex
 Centre
 Singapore 169208

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	290.00 F	*290.00 FL
2	2		*REAR BOOT HINGES	Not Necessary	30.00 F	*- FL
3	1		*REAR WEATHERSTRIP	Necessary	45.00 F	*45.00 FL
4	1		*REAR BOOT TOP LOCK	Bent	40.00 F	*40.00 FL
5	1		*REAR BOOT BOTTOM LOCK	Bent	10.00 F	*10.00 FL
6	1		*REAR BOOT TOYOTA LOGO	Necessary	25.00 F	*25.00 FL
7	1		*REAR BOOT WORDING	Necessary	20.00 F	*20.00 FL
8	1		*REAR BUMPER	Deformed	175.00 F	*175.00 FL
9	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	50.00 F	*50.00 FL
10	8		*REAR BUMPER CLIPS	Necessary	12.00 F	*12.00 FL
11	2		*REAR BUMPER REFLECTOR L/R	Not Necessary	36.00 F	*- FL
12	1		*REAR BUMPER FOAM	Cut	50.00 F	*50.00 FL
13	1		*REAR BUMPER REAR END PANEL	Bent	180.00 F	*180.00 FL
14	1		*REAR LHS TAILLAMP ASSY	Not Necessary	110.00 F	*- FL
15	1		*REAR LHS FENDER SHIELD	Not Necessary	16.00 F	*- FL
16	8		*REAR LHS FENDER SHIELD CLIPS	Not Necessary	12.00 F	*- FL
17	1		*REAR PANEL TOP COVERING	Cracked	75.00 F	*75.00 FL
18	1		*SET REAR REVERSE SENSOR	Not Working	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,376.00	1,172.00
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	243.00
+ Margin on L,N Items 15.00/0.00% (\$\$)	176.40	0.00
Total Parts (\$\$)	1,552.40	929.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REPLACE THE DAMAGED PARTS AS LISTED ABOVE ,INCLUDING REINSTATEMENTS OF NECESSARY ATTACHMENTS & FITTINGS TO FACILITATE REPAIRS ,JACK,PANEL BEAT & RESHAPE THE AFFECTED PARTS & COMPONENTS ,CORRECT & REALIGN THE NECESSARY PARTS	New	1,200.00	800.00
2	TO PROVIDE SKILL LABOUR & MATERIAL TO DO SURFACE TREATMENT/EPOXY TREATMENT AND TO RESPRAY WITH 2K PAINT ON FRONT RIGHT HAND SIDE DOOR & RIGHT SIDE BOTTOM SIDE SKIRT WITH OVEN SPRAY BOOTH FACILITATE	New	1,000.00	800.00
Gross Labour Cost (S\$)			2,200.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >