



# Service Request Details

Claim

S1M039NZ

Reference

CC4/ASM21005619/Aps3 

Loss Date

6 May 2021

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

7 May 2021 3:07:39 PM

Request Date

7 May 2021

Due Date

10 May 2022

Services

Standard workshop survey

## Actions

---

Next Step

Finish the work

More ▾

## Vehicle Information

---

Incident Vehicle Registration #

SLS716B

Make

TPVD UNKNOWN

Model

## Service Address

---

51 Ubi Avenue 1, #01-25, , 408933

## Primary Contact/Insured

---

COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE, 575717, Singapore  
65551188

## Claim Handler

---

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

workshop PRS

Messages

Invoices

History

Documents

Assessment

Metrics

Notes



Document SubType

[+ Upload Documents](#)**Already Attached**

NAME	<a href="#">TP SLS716B (1ST) SAS RPT.pdf.pdf</a>
TYPE	Reports & Statement
SUBTYPE	GIA Report
AUTHOR	ANG Richard
DATE UPLOADED	12 May 2021

NAME	<a href="#">SJ04215B0004-SHC3572K.pdf.pdf</a>
TYPE	Reports & Statement
SUBTYPE	Accident statement
AUTHOR	ILHAM Luqman Hakim
DATE UPLOADED	11 May 2021

NAME	<a href="#">EMAIL TP REG.pdf.pdf</a>
TYPE	Letters and Correspondence
SUBTYPE	Workshop
AUTHOR	VISHNU BATHAM Shekhar
DATE UPLOADED	7 May 2021

NAME	<a href="#">EMAIL TP REG.msg.msg</a>
TYPE	Letters and Correspondence
SUBTYPE	Workshop
AUTHOR	VISHNU BATHAM Shekhar
DATE UPLOADED	7 May 2021

SUBTYPE	Workshop
AUTHOR	VISHNU BATHAM Shekhar
DATE UPLOADED	7 May 2021

---