



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CYNTHIA		Ref: CC4/ASM21005619/Aps3q2 Date: 19/01/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 3572K	Veh. Inspected	SLS 716B
Policy No.	P2419138	Coverage (\$)	0.00
Claim No.	S1M039NZ	Excess (\$)	0.00
Assign From		Assign Date	10/05/2021
2. Vehicle Particulars & Condition			
Make & Model	CITROEN DS4 CROSSBACK	c.c	1560
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	VF7NXBHZTGY551718	Colour	WHITE
Odometer	136031 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55 R17	MICHELIN	6 mm
L/H Front Tyre	215/55 R17	MICHELIN	6 mm
R/H Rear Tyre	215/55 R17	MICHELIN	6 mm
L/H Rear Tyre	215/55 R17	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	06/05/2021	Inspection Date	10/05/2021
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	