

(08/11/13) wef
ASS. REC. BY: Marcus

REF:

C 5/ AIG 21005637/49f3

ASSIGNMENT

From: Date: Veh No: JSY 485 Yr Regn: 15/8/18
Estimated Cost: Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV Truck / Trailer or
To Inspect Vehicle No: JSY 485 Make: Yamaha FZ150i c.c. 150
at Workshop m/s Evoft 11am Colour: Grey / Blue A/C: Insured / Std / NI / NA
of 01-b7 Sp. Reading: 42424 T/Radio: Insured / Std / NI / NA
Insured: EN 7887D Eng/No:
Policy No. C/No: PMYRG3410 J0015330
Claims No. Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess: Steering: In order / Jammed / Leaked / Burnt or
(Client's Record) Brake: In order / Jammed / Leaked / Burnt or
Make of Veh: Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition) Tyre Size: F: 90 / 80 - 17
R: 110 / 70 - 17 P.
Remark: The veh had commenced its BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection. TOYO / YOKO or netroler
Bal. or Market Value: RM 85k. Front: 6 Rear: 6
IDAC Accident Rpt: Consistent?: Yes or No R/Bal. mm
GIA / PR Seen: Consistent?: Yes or No L/Bal. mm
Est. Repairs: days Res.: Yes or No D.O.A. 26/4/21 D.O.I. 21/5/21
Lum Sum: % 3 Val.: Yes or No Survey held at
CA / REV / REP. / 24 HRS 9 715 4509 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT
Date: Person Contacted: AH Chuan The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Date / Time Action / Instruction
Sum insured RM 66000

Date/Time, File Pass to? ☐ : Preli. Report
1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format :
Lump Sum / I.B.I. (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

)

TOTAL