

NAZ

Alg

LOKE

PI

From: _____ Date: _____

Veh No: SHC 1909L Yr Regn: 8 OCT / 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry Taxi Prime Mover /

Truck / Trailer or

Make: HYUNDAI IONIQ G2 (c.c) 1,580

Colour: BLUE A/C: Insured Std / NI / NA

Sp. Reading 415 590 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHC851CVKH4761

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

N/S	O/S
LHS	RHS

Tyre Size: F: 195/65 R15
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or WEITLAKE

Front Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. 4 mm L/Bal. 4 mm

D.O.A. 7/5/2021 D.O.I. 10/5/2021

Survey held at CDCE LOYANG

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
-------------	----------------------

☐ : Prell. Report

Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$) \$ + RS. \$☐ : Interview (\$) Photos

Lump Sum / I.B.I: (\$)

	: Tech. Invs (\$) Others
--	------------------	----------

Weekend (\$	
-------------	--

TOTAL