



AIG - OD (REVERT)
SURVEY: 10/05/21
LK/L - STEVE

VEHICLE NO : SME 5919 L

MODEL : MIT/ATRAGE 1.2 CVT

WIP : 10891

Material	:	\$	<u>4,486.09</u>
Labour	:	\$	<u>2,735.00</u>
Sub-Total	:	\$	<u>7,221.09</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>7,221.09</u>
GST 7%	:	\$	<u>505.48</u>
Grand Total	:	\$	<u>7,726.57</u>
Finalise By/Date : <u>Amey on 31/05/21</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 07 WORKING DAYS + 2 days (weekend)



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 12/05/2021	Cust No/Name	/TAN LAY CHEO
	Reg No/Reg Date	SME5919L / 08/10/2018
	Date In/Mileage	12/05/2021/ 60331
	Chassis/Package	MMBSTA13AJH003683 /CS5P
	Engine No	3A92UHH5805
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	P01 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	31/05/2021/ 11:00	BLE	884 / Lauro Songcuan	10891		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							675.00 ✓
RENEW FRONT BUMPER, BODY KIT & RH FRONT FENDER							
E PNT98000							1050.00 ✓
SPRAY PAINT FRONT BUMPER, FRONT BUMPER BODY KIT & RH FRONT FENDER							
A 54900099							30.00 ✓
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							120.00 ✓
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
M SUNDRY							40.00 ✓
APPLY ANTI CORROSION ON AFFECTED AREAS							
M SUNDRY							20.00 ✓
SUNRIES							
E PNT88000							450.00 ✓
REPLACE FRONT SUPPORT PANEL → <i>Supp.</i>							
E PNT98000							350.00 ✓
SPRAY PAINT FRONT SUPPORT PANEL → <i>Supp.</i>							
X	FACE,FR BUMPER ✓			1.00	706.00	23.00	543.62 ✓
X	COVER,FR BUMPER ✓			1.00	13.00	23.00	10.01 ✓
X	GRILLE,FR UNDER ?			1.00	165.00	23.00	127.05 ✓
X	BRACKET,FR BUMPER,RH ✓			1.00	13.00	23.00	10.01 ✓
X	GARNISH,FR BUMPER,RH ✓			1.00	127.00	23.00	97.79 ✓
X	CLIP,FR BUMPER ✓			5.00	4.00	23.00	15.40 ✓
X	GRILLE,RADIATOR ?			1.00	557.00	23.00	428.89 ✓
X	FENDER,FR RH ✓			1.00	500.00	23.00	385.00 ✓
X	SHIELD,FR WHEELHOUSE,RH ✓			1.00	98.00	23.00	75.46 ✓
X	CLIP,INNERSHIELD ✓			6.00	4.00	23.00	18.48 ✓
X	PANEL ASSY,FR END ?			1.00	1055.00	23.00	812.35 ✓
X	PANEL,AIR GUIDE,RH ?			1.00	11.00	23.00	8.47 ✓
X	HEADLAMP ASSY,RH ✓			1.00	663.00	23.00	510.51 ✓
X	TANK,WINDSHIELD WASHER ✓			1.00	75.00	23.00	57.75 ✓
X	EMBLEM ECO ✓			1.00	17.00	00.00	17.00 ✓
X	UNPAINTED BODYKITS ✓			1.00	1643.00	20.00	1314.40 ✓

This is not an official tax invoice.
This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 12/05/2021	<table> <tr> <td>Cust No/Name</td><td>/TAN LAY CHEO</td></tr> <tr> <td>Reg No/Reg Date</td><td>SME5919L / 08/10/2018</td></tr> <tr> <td>Date In/Mileage</td><td>12/05/2021/ 60331</td></tr> <tr> <td>Chassis/Package</td><td>MMBSTA13AJH003683 /CS5P</td></tr> <tr> <td>Engine No</td><td>3A92UHH5805</td></tr> <tr> <td>Make/Model</td><td>MIT/18MY ATTRAGE 1.2 CVT</td></tr> <tr> <td>Colour/Trim</td><td>P01 RED METALLIC / BK BLACK</td></tr> </table>	Cust No/Name	/TAN LAY CHEO	Reg No/Reg Date	SME5919L / 08/10/2018	Date In/Mileage	12/05/2021/ 60331	Chassis/Package	MMBSTA13AJH003683 /CS5P	Engine No	3A92UHH5805	Make/Model	MIT/18MY ATTRAGE 1.2 CVT	Colour/Trim	P01 RED METALLIC / BK BLACK
Cust No/Name	/TAN LAY CHEO														
Reg No/Reg Date	SME5919L / 08/10/2018														
Date In/Mileage	12/05/2021/ 60331														
Chassis/Package	MMBSTA13AJH003683 /CS5P														
Engine No	3A92UHH5805														
Make/Model	MIT/18MY ATTRAGE 1.2 CVT														
Colour/Trim	P01 RED METALLIC / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	31/05/2021/ 11:00	BLE	884 / Lauro Songcuan	10891

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X MARK, THREE-DIA ? Z TEXT AIG OD CLAIM - REVERT SURVEY: STEVE (LKK) 10.05.2021 DOA: 08.05.2021 07 DAYS	1.00	70.00	23.00	53.90 ?
Pro Forma				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	4,486.09		Nett	7,221.09
Labour	2,675.00	7% GST on	7221.09	505.48
Standard Menu	0.00			
Specialist Job	0.00		Total Payable	7,726.57
Diagnostics Job	0.00			
Sundry/Others	60.00			
Total(w/o GST)	7,221.09			

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SME 5919 L

	<u>Labour</u>	<u>Cost \$</u>
1	Replace Front Support Panel	450.00 ✓
2	Spray Paint Front Support Panel	350.00 ✓
		<u>800.00</u>
	7% GST	56.00
	Total	<u>856.00</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SME 5919LWIP: 10891

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	SUPPORT part	② SUPP		✓ DD	✓ 5-2568865
2	Air Duct RH	? / SUPP		✓ QR	✓ 6379A474
3	HLWR Grille	? / SUPP		✓ CR	✓ 6402A268
4		? / SUPP			Steve
5		? / SUPP			
6	Renew Support part	? / SUPP			17/5/21
7	respray support part	? / SUPP			
8	repair working Day - 7 days	? / SUPP			
9		? / SUPP			
10	MARK THREE - DIA	② SUPP		✓ ne	
11	GRILLIE, RADIATOR	② SUPP		✓ CR	} Steve 21/5/21
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	21/5/21	Steve
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: ATRAGESURVEYOR: STEVE

All DTCs

Re: 34FE5919L
Before any further work to check all the find

2021.05.22

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MP/IGDI/IESEL	KOSOSS_99880010		No DTCs	
AT/CVT/A-MT/C-SST	KOSOSS_99880010		No DTCs	
4WS/Electric Power Steering	KOSOSS_99880010		No DTCs	
ABS/ASC/ASTC/WSS	KOSOSS_99880010		No DTCs	
SRS-AIR BAG	KOSOSS_99880010		No DTCs	
Air Conditioner	KOSOSS_99880010		No DTCs	
ETACS	KOSOSS_99880010	B1707	Flasher open	Active
Meter	KOSOSS_99880010		No DTCs	
Steering Angle Sensor	KOSOSS_99880010		Non-target System	
KOS/OSS/MMO/Keyless (with KOS)	KOSOSS_99880010		No DTCs	

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW21031-00
V.C.I. Version	B179
Vehicle Information	A13A 2018MY

All DTCS

Page 101, 04/15/19

After very short test unit to Base all the

Send
the test Send
OK

2021.05.22

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	KOSOSS_99880010		No DTCS	
AT/CVT/A-MT/TTC-SST	KOSOSS_99880010		No DTCS	
4WS/Electric Power Steering	KOSOSS_99880010		No DTCS	
ABS/ASC/ASTC/WSS	KOSOSS_99880010		No DTCS	
SRS-AIR BAG	KOSOSS_99880010		No DTCS	
Air Conditioner	KOSOSS_99880010		No DTCS	
ETACS	KOSOSS_99880010		No DTCS	
Meter	KOSOSS_99880010		No DTCS	
Steering Angle Sensor	KOSOSS_99880010		Non-target System	
KOS/OSS/IMMO/Keyless (with KOS)	KOSOSS_99880010		No DTCS	

Setting	
Item	Information
M.U.T.-3 Version	SEW21031-00
V.C.I. Version	B179
Vehicle Information	A13A 2018MY