

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508989
Fax: 6546 8156

Our Job Ref No : 305468089
Date : 18/05/21

FINALIZATION FORM

To : LKK
Attn : NAZ
Vehicle Reg No. : SHC3309E

Fax :

08/05/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


- Z The repair job shall bill to: TOKIO SLM6453B
2. The finalized amount shall be:
- | | |
|---|-------------------|
| (a) Spare Parts after List discount | <u>\$486.68</u> |
| (b) Labour Charges | <u>\$701.00</u> |
| Total for Part-By-Part Repair Cost | <u>\$1,187.68</u> |
| (c) Lumpsum Repair (if applicable) | |
| Total for Lumpsum repair cost after Less: | |
| Final Lumpsum Repair cost | |


3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : CHIANG
Tel : 62148314
Fax : 65468156

Signature : 
Name : NAZ LKK
Date : 21/6/2021

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TOWING FEES.	New	60.00
Gross Labour Cost (\$)			60.00

ComfortDelGro Engineering Pte Ltd/SHC3309E/18/05/2021 15:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199508048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

(SUPPLEMENTARY)

TP INSURER: **Tokio Marine Insurance Singapore Ltd (HQ)**
LION CITY RENTALS PTE. LTD.

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	MM000073	Date of Loss:	08/05/2021
Vehicle Reg. No.:	SHC3309E	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)	Vehicle Reg. Date:	07/11/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU402404	Chassis No:	KMHC851CVLU188107
Odometer:	520532 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	0.00
Miscellaneous Items	0.00
Labour	60.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	60.00
+ GST 7.00% (S\$)	4.20
Nett Amount (S\$)	64.20
+ Previous Estimates (S\$)	3,080.87
Claim Total (S\$)	3,145.07

Generated using Merimen e-Claims Internet Estimation & Adjusting System

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Wk 7obine

Date: 12.05.2021
Time: 09:18:12
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305468089
REGN NO : SHC3309E
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 07.11.2019
DATE/TIME IN : 08.05.2021 19:36
ACCIDENT DATE : 08.05.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2533-G MOULDING ASSY-RR BUMPER C 1 451.25 20.00 361.00 / CLK

0002 04-01-0104-2544-G CAP-RR HOOK 1 94.60 20.00 75.68 / SQ

0003 04-01-0104-1150-A PROTECTOR MAT 1 50.00 2.00- 50.00 / NE

SUB-TOTAL : 486.68 /

JOB NATURE

0000 L MERIMEN FEE 11.00

0001 PB PANEL BEATING 350.00 /

0002 SP SPRAYPAINT CHARGE 250.00 /

0003 20-22 REMOVE/REFIX REVERSE SENSOR 30.00 /

0004 23-01 TOWING FEE 60.00 /

SUB-TOTAL : 701.00 /

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	08/05/2021
Vehicle Reg. No.:	SHC3309E	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)	Vehicle Reg. Date:	07/11/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU402404	Chassis No:	KMHC851CVLU188107
Odometer:	520532 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,538.32
Miscellaneous Items	11.00
Labour	1,330.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,879.32
+ GST 7.00% (S\$)	201.55
Nett Amount (S\$)	3,080.87

This claim is handled by: CHIANG LIAT CHOON

Generated using Merlmen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 May 2021)

Parts: 143 HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHC3309E/10/05/2021 15:27

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER	20.00	0.00	*459.40 FL XR
2	1		*REAR BUMPER MOULDING	20.00	0.00	*451.25 FL CRK
3	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	*394.80 FL ?XSVL
4	1		*REAR BUMPER REINFORCEMENT STAY LH	20.00	0.00	*138.10 FL ?XSVL
5	1		*REAR BUMPER TOW COVER	20.00	0.00	*94.60 FL SCR
6	1		*REAR BUMPER BRACKET LH	20.00	0.00	*55.80 FL ?XSVL
7	1		*REAR REVERSE SENSOR	0	0.00	*180.00 FS XSVL
8	1		*REAR BUMPER MAT	0	0.00	*50.00 FS /NGL
9	1		*REAR BUMPER REFLECTOR LH	20.00	0.00	*41.45 FL XSVL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)

1,865.40

- List Item Discount on L Items (S\$)

327.08

Total Parts (S\$)

1,538.32

ComfortDelGro Engineering Pte Ltd/SHC3309E/10/05/2021 15:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Miscellaneous Items

1 1 OD/TP Case (Insurer)

Amount

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Labour Items

1 PANEL BEATING

2 SPRAY PAINTING

3 REMOVE/REFIX REVERSE SENSOR

4 CHECK WIRING AND LIGHTING

5 TUFF COATING

Lab.Type

Amount

New

700.00 300

New

450.00 250

New

60.00 30

New

60.00 xN/N

New

60.00 xN/N

Gross Labour Cost (S\$)

1,330.00

ComfortDelGro Engineering Pte Ltd/SHC3309E/10/05/2021 15:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

NAZ LKK

10/5/2021 1530

PIP

2 DAYS

AFTER PAINT PH REPAIR PHOTOS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

WORKSHOP



GAO

Express Towing Services

You Call, We Tow - Fast . Secured . Reliable



2105
2105
2125
2135
2225

47 Jalan Pemimpin Halcyon 2 #C01-02 Singapore 577200 Co. Reg. No. 53152603L HP: 900 900 92 Email: jim.koh@hotmail.com Website: http://www.gaoexpresstowing.sg

CASH SALE/WORK ORDER

No. 197781

Date: 8/5/21

寶號
Messrs: COMFORT

車號
Vehicle No: SHC 3309 E Model No: H / IONIQ

時間(日/夜)
Time (day/night): Contact No: 9620 4778

由
Location: SHELL @ BD

到
To: COMFORT LY

Cash \$: 35 Others:


經手人
Authorised By: Jw Tow Truck Driver Name: Jimmy YL72325

注意本公司對所拖之車輛,在進行中如有任何損失或破壞,一概由車主自行負責。
Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

- ☐ Jump Start/Changing of battery
- ☐ Tyre Replacement
- ☒ Accident/Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☐ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo
- ☐ Woodlands and Tuas Checkpoint

Fuel Level : F 1/4 1/2 3/4 E

- ☐ OK
- ☐ Faulty
- ☐ Not tested



: Cracked X : Dented
/ : Scratched O : Missing

Signature of Customer

Job Attended

2. Tow Truck / Recovery Van : ☐ VRS ☐ QA ☒ GAO ☐ OTHERS
Name of Driver : Jimmy
Vehicle No. : YL72325
Time Dispatch : 2105
Time of Arrival : 2125
Time Completed : 2225

Cash Invoice Details (if applicable)

Cash Invoice No. :

Customer Acknowledgement

I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.
I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.
Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

Date

Time

Signature of Customer

WORKSHOP

Name of Attending Staff/Guard

Date & Time of Arrival

Signature of Attending Staff/Guard

WORKSHOP COPY