

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : **SJW 6943 A**
Model : Proton Exora
Year : _____
Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front bumper	1	\$ 955.80	\$ X Ry 955.80
2	Front bumper side retanier RH	1	\$ 84.00	\$ X 84.00
3	Front fender RH	1	\$ 1,105.00	\$ Ry 1,105.00
4	Front fender inner cowling RH	1	\$ 344.00	\$ X 344.00
5	Front door RH	1	\$ 1,178.00	\$ bt 1,178.00
6	Front door black tape RH	1	\$ 58.00	\$ na 58.00
7	Front door inner trimboard RH	1	\$ 897.60	\$ X 897.60
8	Rear door RH	1	\$ 1,065.00	\$ bt 1,065.00
9	Rear door black tape RH	1	\$ 58.00	\$ na 58.00
10	Rear door inner trimboard RH	1	\$ 797.60	\$ X 797.60
11	Rear fender RH	1	\$ 1,268.50	\$ Ry 1,268.50
12	Rear fender inner cowling RH	1	\$ 166.00	\$ X 166.00
13	Rear fender side glass moulding	1	\$ 738.00	\$ X 738.00
14	Rear bumper	1	\$ 897.30	\$ Ry 897.30
15	Rear bumper side retanier	2	\$ 62.50	\$ X 125.00
16	Front knuckle arm RH	1	\$ 398.00	\$ X 398.00
17	Front knuckle arm bearing RH	1	\$ 245.50	\$ X bb 245.50
18	Front shock absorber RH	1	\$ 364.00	\$ X 364.00
19	Front lower arm RH	1	\$ 535.25	\$ X 535.25
20	Rear axle	1	\$ 948.00	\$ X 948.00
21	Rear knuckle arm bearing RH	1	\$ 135.00	\$ X ac 135.00
22	Rear shock absorber RH	1	\$ 319.60	\$ X 319.60

Parts Sub Total : \$ 12,683.15

Discount 10% : \$ 1,268.32

PARTS TOTAL : \$ 11,414.84

Nos.	SPECIAL NETT ITEMS	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ X 80.00
2	Front bumper clips	1	\$ 50.00	\$ X 50.00
3	Front fender sealant	1	\$ 100.00	\$ X 100.00
4	Front fender inner cowling clips	1	\$ 50.00	\$ X 50.00
5	Front door sealant	1	\$ 100.00	\$ X 100.00
6	Front door inner trimboard clips	1	\$ 50.00	\$ X 50.00
7	Rear door sealant	1	\$ 100.00	\$ X 100.00
8	Rear door inner trimboard clips	1	\$ 50.00	\$ X 50.00
9	Rear fender sealant	1	\$ 100.00	\$ X 100.00
10	Rear fender inner cowling clips	1	\$ 50.00	\$ X 50.00
11	Rear fender side glass sealant	1	\$ 100.00	\$ X 100.00
12	Rear fender side glass inner seal	1	\$ 60.00	\$ X 60.00
13	Rear fender side glass primer and cleaner	1	\$ 80.00	\$ X 80.00
14	Rear bumper clips	1	\$ 50.00	\$ X 50.00
15	Front & rear alloy rim RH	1	\$ 980.00	\$ aut✓ 980.00
16	Front & rear tyre RH	1	\$ 380.00	\$ X 380.00
SPECIAL NETT TOTAL :				\$ 2,380.00

Nos.	LABOUR	S\$
1	R&R front door component	\$ 60 150.00
2	R&R rear door component	\$ 60 150.00
3	R&R rear side glass	\$ X 250.00
4	R&R rear bumper reverse sensor	\$ 30 100.00
5	R&R front & rear undercarriage parts.	\$ 200 300.00
6	R&R front & rear tyre and balancing	\$ X 60. 100.00
7	Wheel alignment	\$ 80✓ 150.00
8	Diagnostic reset fault code	\$ X 300.00
9	Conduct water leak test	\$ X 120.00
10	Upholstery	\$ X 300.00
11	Check wiring	\$ 30 100.00
12	Panel beating	700 \$ 600 1,600.00
13	Rust proofing	\$ 30 200.00
14	Spray painting	\$ 1200 1,600.00
LABOUR TOTAL :		\$ 5,420.00

Taufik 97495449
'wp' 12/5/21

L/S Resurvey after repair

Taufik @ Khanting
06 days

PARTS TOTAL : \$ 11,414.84
SPECIAL NETT TOTAL : \$ 2,380.00
LABOUR TOTAL : \$ 5,420.00
GRAND TOTAL : \$ 19,214.84

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Proton : Exora : 2009-
Thrust Line Alignment

Front : Left

Actual	Before	Specified Range
-0°15'	-0°15'	-0°30' -0°06'
5°10'	5°10'	3°06' 3°30'
-0°04'	-0°04'	-0°03' 0°00'
12°51'	12°51'	
12°36'	12°36'	

Front : Right

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Actual	Before	Specified Range
-2°30'	-2°30'	-0°30' -0°06'
5°15'	5°15'	3°06' 3°30'
-0°22'	-0°22'	-0°03' 0°00'
15°15'	15°15'	
12°45'	12°45'	

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
2°15'	2°15'	-0°30' 0°30'
-0°06'	-0°06'	-0°30' 0°30'
-2°23'	-2°24'	
-0°26'	-0°26'	-0°06' 0°00'

Rear : Left

Actual	Before	Specified Range
-1°36'	-1°36'	-1°36' -1°12'
-0°04'	-0°04'	0°00' 0°03'

Rear : Right

Camber
Toe

Actual	Before	Specified Range
-2°48'	-2°48'	-1°36' -1°12'
0°01'	0°01'	0°00' 0°03'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
1°12'	1°12'	-0°30' 0°30'
-0°03'	-0°04'	0°00' 0°06'
-0°03'	-0°02'	