

ASS. REC. BY: Steve 1 REPT AIG


**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD /  TP /  WS /  TP RES /  OD RES /  EVA /  INV /  MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. 1800092507-02  
 Claims No. 0768200084SG  
 Sum Insured: \_\_\_\_\_ Excess: 800  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: GBH 6076B Yr Regn: 3/8/18  
 Type: M. Car / M. Cycle / Bus / Van / (Lorry) / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: KIA K2500 c.c. 2497  
 Colour: White A/C: Insured / Std / Nil / N  
 Sp. Reading: 68973 T/Radio: Insured / Std / Nil / N  
 Eng/No: \_\_\_\_\_  
 C/No: KNCSTX 76LH719456  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD AIRIM or  
 Tyre Size: F: 195R15C  
 R: 11  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or A Plus  

Front	Rear
R/Bal. <u>5</u> mm	R/Bal. <u>5</u> mm
L/Bal. <u>5</u> mm	L/Bal. <u>5</u> mm
D.O.A. <u>16/4/21</u>	D.O.A. <u>11/5/21</u>

 Survey held at cycle & carriage  
 Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision



(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Sent: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 5 days Res.: Yes or No  
 Cum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Date / Time	Action / Instruction
	<u>RAV-SOK</u>
<u>11/05/21 @ 4.13pm</u>	<u>revert to AIG via Merimen.</u>
<u>18/05/21 @ 9.29am</u>	<u>Kok Chong informed C/A via Merimen.</u>
<u>18/05/21 @ 12.31pm</u>	<u>Edwin informed owner cancel the OD claim &amp; will change to reporting only.</u>
<u>20/05/21</u>	<u>Submit Preli. report. - Owner withdraw OD claim.</u>
	<u>We have not authorise repair.</u>

Date/Time, File, Pass Wrt.  : **Prel. Report**  
 20/05 Typist  : **Final Report**

Days Of Repair: 5  
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_ )  
 : Interview (\$ \_\_\_\_\_ )  
 : Tech. Invs (\$ \_\_\_\_\_ )  
 : Weekend (\$ \_\_\_\_\_ )

Survey Fee:	_____
Transportation:	_____
\$ + RS. SI	_____
Phone	_____
Others	_____
TOTAL	_____

Date/Time, File Return to? \_\_\_\_\_  
 Date/Time, File Return to? \_\_\_\_\_



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name / KENDA (S) PTE LTD Reg No/Reg Date GBH6076B / 03/08/201 Date In/Mileage / 0 Chassis No KNCSJX76LH7194556 Engine No D4CBH321575 Make/Model KIACV/K2500 BSP EURO 6 Colour/Trim UD CLEAR WHITE / GW GREY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	11/05/2021/ 11:55	BLE	261 / Edwin Caina	33254

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M SUNDRY RESERVOIR ASSY-RADIATOR (Spare tank) ✓ CR4 (no price) KS254314E013				1000 2000.00
E PNT88000 RENEW FRT BUMPER & BONNET 2.5 x 400 REPAIR FRT PNL (inner)				700.00 ✓
E PNT98000 RESPRAY FRT PANEL & BONNET				7 200.00
A 25000001 RENEW AIRCON PIPE				7 80.00
A 25000001 TOP UP AIRCON GAS				7 200.00
A 25000001 RENEW AIRCON BLOWER ASSY				7 400.00
A 25000001 REMOVE & REFIT DASHBOARD ASSY				30.00 ✓
A 54900099 CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM				60.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				50.00 ✓
M SUNDRY SUPPLY FRT NUMBER PLATE WITH CASING ✓ CR4				40 80.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				20.00 ✓
M SUNDRY Sundries				
M COVER-FR BUMPER ✓ 00	1.00	365.00	20.00	292.00
M MESH-FRONT BUMPER CENTER,UPR 1	1.00	42.00	20.00	33.60
M MESH-FRONT BUMPER CENTER,LWR	1.00	42.00	20.00	33.60
M MOULDING-FRT BPR LICENSE PLATE ✓ BR	1.00	26.00	20.00	20.80
M GARNISH-HOOD 1	1.00	203.00	20.00	162.40
M RAIL ASSY-FR BUMPER 1	1.00	329.00	20.00	263.20

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Table with 2 columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance Pte. Ltd. and vehicle information for KENDA (S) PTE LTD.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Includes account details for LAX00000 and operator Edwin Caina.

Main items table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various car parts like BRACKET ASSY-FR BUMPER SIDE, COVER-BLANKING, etc.

Estimate

SURVEYOR NAME: Steve (LKK) 11/5/21, 3-00pm
SURVEYOR SIGNATURE: OO-MM AL
DATE: Experi-?
REMARKS: P/P, My Bel SW 5 days

Summary table with columns: Confirm & accepted by, Net, 7% GST on, Total Payable. Shows a total payable of 9,016.27.

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.

Your NCD will be affected due to late reporting

SC0N21570002 / Cycle & Carriage Eulon Motor Dealer Pte Ltd  
ENTRY DATE & TIME: 08/05/2021 08:38 (SGT)  
SUBMITTED BY: Mars Lim Yeong Cheong  
VERSION: 1 (08/05/2021 08:38 (SGT))

# SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 08/05/2021 08:38 (SGT)  
 Date of Accident ..... 16/04/2021 15:00 (SGT)  
 Exact Location of Accident ..... Near 348 Tampines Street 33, Block 348, Singapore 520348  
 Additional Location Information ..... Upper Changl Rd E  
 Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... GBH6076B

INSURED/POLICYHOLDER

Is company? ..... Yes  
 Name Of Registered Owner ..... KENDRA (S) PTE LTD  
 Company Reg No ..... 1XXXXX740k  
 Email Address ..... Colleen@kenda.net  
 Mobile Phone No ..... (Phone) +65-98502802  
 Alternative Phone No ..... (Office) +65-65431183

### VEHICLE PARTICULARS

Manufacturer ..... Kia  
 Model ..... K2500 EURO 6  
 Variant ..... -  
 Exact purpose for which vehicle was being used at time of accident ..... Employment  
 Are you claiming under your own insurance policy for repair to your vehicle? ..... Yes  
 Vehicle Category ..... Commercial vehicle  
 Transmission ..... Manual  
 CC ..... 2500

### INSURANCE COMPANY

Name of Insurance Company ..... AIG Asia Pacific Insurance Pte. Ltd.  
 Type of Coverage ..... Comprehensive  
 Fleet Policy ..... No  
 Policy Number ..... 1800092507-02  
 Cover Note Number ..... -

### DRIVER

Name of Driver ..... LIU XIAOLIANG  
 Passport No/FIN ..... GXXXX712Q

Date Of Birth	07/12/1981
Occupation	Outdoor
Date Of Driving Pass	28/08/2020
Driving experience	8 MONTHS
Gender	Male
Mobile Number	(Phone) +65-88914139
Alt. Phone Number	-
Email Address	164807823@qq.com
Address	2 LOYANG VIEW
Address complement	SINGAPORE
Postcode	507268
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS TRAVELLING ALONG UPPER CHANGI ROAD E TOWARDS LOYANG WAY, I WAS TURNED MY HEAD RIGHT TO VIEW ONCOMING TRAFFIC BEFORE I JOINT INTO UPPER CHANGI RD EAST MAIN ROAD, WHEN I TURNED BACK MY HEAD TO FRONT, THE TRUCK INFRONT OF ME GBK8018R OUT OF SUDDEN STOPPED, I CANNOT REACT AND CANNOT STOP MY VEHICLE AND ACCIDENTALLY HIT INTO FRONT TRUCK.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

**!! DETAILS OF OTHER VEHICLE PROPERTY !!**

Vehicle Registration Number	GBK8018R
Vehicle Manufacturer	Toyota
Vehicle Model	Dyna
Vehicle Variant	-
Vehicle Colour	White
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-

Pass complement  
Passenger  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Liu Xiao Liang


7/5/2021

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

Refer to Attachment

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

SU Xiaozhang 7/5/2021  
Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature]



Witnessed by Reporting Centre Personnel

I WAS TRAVELLING ALONG UPPER CHANGI <sup>ROAD</sup> EAST E  
TOWARDS LOYANG WAY , I WAS TURNED MY <sup>HEAD</sup> NECK RIGHT TO  
VIEW ONCOMING TRAFFIC BEFORE I JOINT INTO UPPER  
CHANGI RD EAST MAIN ROAD , WHEN I TURNED BACK MY  
<sup>HEAD</sup> NECK TO FRONT, THE TRUCK IN FRONT OF ME GBK8018R OUT  
OF SUDDEN STOPPED , I CANNOT REACT AND CANNOT STOP  
MY VEHICLE AND ACCIDENTALLY HIT INTO FRONT TRUCK .



215 Xiao Jiang

G88367128

7/5/21



# CERTIFICATE OF INSURANCE

## CYCLE & CARRIAGE COMMERCIAL AUTO PROTECTOR COMMERCIAL VEHICLE

<b>Name of Policyholder</b>	: Kenda (S) Pte Ltd	<b>Vehicle No.</b>	: GBH8076B
<b>Period of Insurance</b>	: 03 Aug 2020 To 02 Aug 2021	<b>Policy No.</b>	: 1800092507-02
<b>Engine No.</b>	: D4CBH321676	<b>Endorsement No.</b>	:
<b>Chassis No.</b>	: KNCSJX76LI17194550	<b>Issued Date</b>	: 09 Jul 2020

**ABOUT THE COVER**

<b>Make/Model</b>	: KIA K2600	<b>Sum Insured</b>	: Market Value	<b>First Year of Registration</b>	: 2018
<b>Engine Capacity/Tonnage</b>	: 1.6 Tonnage	<b>Off Peak Car</b>	: No	<b>Insuring with COE/PAF</b>	: Yes
<b>Driver Restriction</b>	: NA				

**Person or Classes of Persons Entitled to Drive\***:

a) Any person who is driving on the Policyholder's order or with their permission.  
b) This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years driving experience.

**Age Condition** : All Age Condition  
**Limitation as to use\*** :

1) Use in connection with the Policyholder's business.  
2) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.  
3) Use for social, domestic or pleasure purposes. This Policy does not cover a) use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, and b) use whilst towing a trailer except the towing of anyone disabled using a mechanically propelled vehicle. c) use for any purpose in connection with Motor Trade.

\* Limitations rendered Inoperative by Section 8 of the Motor Vehicles (Third-Party Risk and Compensation) Act (Cap. 189), Section 06 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

**EXCESS**

**Section 1**  
Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

**Section 2**  
Property Damage - \$0

**Windscreen** : \$100

**Named Driver and Excess** (where applicable)

**APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)**

- Cycle & Carriage Authorized Service Centre (For accident reporting & windscreen claim only) Add: 000 Bin Ming Ave Singapore 676733 69128000
- Cycle & Carriage Authorized Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64708000
- Cycle & Carriage Authorized Service Centre (For accident reporting & windscreen claim only) Add: 20 Leng Kee Rd Singapore 159054 64708333
- Cycle & Carriage Authorized Service Centre (For accident reporting & windscreen claim only) Add: 20 Leng Kee Rd Singapore 159054 64708330
- Cycle & Carriage Authorized Service Centre (For accident reporting & windscreen claim only) Add: 230 Ubi Rd 3 Singapore 408653 67461000
- Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609330 65684501

For other Approved Reporting Centres/AIO Authorized Repairers, please contact our 24-hour accident emergency hotline at +65 6336 6200. Alternatively, you may refer to AIG website [www.aig.sg](http://www.aig.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

**IMPORTANT NOTES**

**Hire Purchase Company/Employer's Loan:** Daimler Financial Services Africa & Asia Pacific Ltd

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risk and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risk) Rules, 1954 (Malaysia).

0500710050  
C&C FULCO-CORP SALES  
72 UBI ROAD 4 FULCO BUILDING  
SINGAPORE 408617 ANSP - MOTOR  
Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

**AIG Asia Pacific Insurance Pte. Ltd.**  
This computer generated document does not require a signature.

830007