

ASS. REC. BY:

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKA2206A. Yr Regn: 2011 / Jan.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit Lancer c.c. 1499

Colour: Grey. A/C: Insured / Std / NI / NA

Sp. Reading: 110938 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMYSRCY2AAU-001865

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R18.

R: 225/45R18.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Windforce.

Front / Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 12/05/21.

Survey held at KT Motorwaska

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AIG

COE Expiry: 31/12/30.

MV:

PV:

Nett:

Date/Time, File Pass to?

: Preli. Report

1)

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee:

Transportation:

____ \$ + RS. ____ \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.J: (\$ _____)

CITY TYREAUTO PTE LTD
 219 KAKI BUKIT AVE 1
 SHUN LI INDUSTRIAL PARK
 SINGAPORE 416044
 TEL: 67466688
 H/P: 85153676

Work Order: R003387
 License: SKA2206A
 Date: 11.5.21 17:55

Factory Japan 2020.0.1 : Mitsubishi : Lancer EX / VAN : CS Series : CS2A Two Wheel Drive

| Front : Left | | |
|--------------|--------|-----------------|
| Actual | Before | Specified Range |
| -0°39' | -0°39' | -0°30' 0°30' |
| 2°50' | 2°50' | 2°20' 3°20' |
| 1°08' | 1°08' | -0°03' 0°09' |
| 1°09' | 1°09' | 11°50' 13°20' |
| 0°30' | 0°30' | 11°20' 13°50' |

| Front : Right | | |
|---------------|--------|-----------------|
| Actual | Before | Specified Range |
| 2°24' | 2°24' | -0°30' 0°30' |
| 2°50' | 2°50' | 2°20' 3°20' |
| 1°07' | 1°07' | -0°03' 0°09' |
| -1°54' | -1°54' | 11°50' 13°20' |
| 0°30' | 0°30' | 11°20' 13°50' |

| Front | | | |
|------------------|--------|--------|-----------------|
| | Actual | Before | Specified Range |
| Cross Camber | -3°03' | -3°03' | -0°30' 0°30' |
| Cross Caster | 0°00' | 0°00' | -0°30' 0°30' |
| Cross SAI | 3°03' | 3°03' | |
| Total Toe | 2°15' | 2°15' | -0°06' 0°17' |
| Cross Turn Diff. | | | |

| Rear : Left | | |
|-------------|--------|-----------------|
| Actual | Before | Specified Range |
| 0°55' | 0°55' | -1°10' 0°10' |
| 0°00' | 0°00' | 0°03' 0°14' |

| Rear : Right | | |
|--------------|--------|-----------------|
| Actual | Before | Specified Range |
| -0°59' | -0°59' | -1°10' 0°10' |
| 0°00' | 0°00' | 0°03' 0°14' |

| Rear | | | |
|--------------|--------|--------|-----------------|
| | Actual | Before | Specified Range |
| Cross Camber | 0°05' | 0°05' | -0°30' 0°30' |
| Total Toe | 0°00' | 0°00' | 0°06' 0°29' |
| Thrust Angle | 0°00' | 0°00' | |
| Axle Offset | 0mm | 0mm | |