

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	UNITED OVERSEA	AS INSURANCE LTD	Ref:	CS/UOI21005771/Avf3e2	
	3 ANSON ROAD # SPRINGLEAF TOV	28-01 VER SINGAPORE 079909	Date:	04/08/2021	
			Code:	UOI2	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKJ 23B	Veh. Inspected	XD 6848B	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	M12D15652105	Excess (\$)	0.00	
	Assign From	JOSEPHINE WONG	Assign Date	12/05/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	MAN TGS 26	c.c	10518	
	Engine No.	HIDDEN	Year of Reg.	2013	
	Chassis No.	WMA26SZZ9CP038846	Colour	WHITE	
	Odometer	586028 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	295/80 R22.5	HILO	8 mm	
	L/H Front Tyre	295/80 R22.5	HILO	8 mm	
	R/H Rear Tyre	295/80 R22.5	AMBERSTONE	8 mm	
	L/H Rear Tyre	295/80 R22.5	AMBERSTONE	8 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	30/04/2021	Inspection Date	19/05/2021	
	Survey held at XIN HUA WORKSHOP PTE LTD				
	23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				