

☐ Third Party Report

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 12/05/2021	Cust No/Name	/FOO JIEMING
	Reg No/Reg Date	SMQ8777X / 03/01/2020
	Date In/Mileage	12/05/2021/ 16503
	Chassis/Package	KNAF5416ML5059941 /KC17P
	Engine No	G4FGKH739793
	Make/Model	KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim	KLK STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	08/06/2021/ 09:12	BLE	881 / Jojo Cheng	33308		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE RHR QTR PANEL & RR BUMPER, REPAIR ON AFFECTED AREAS							-1400.00
E PNT88000 REMOVE & INSTALL RR WINDSCREEN GLASS TO FACILITATE REPAIR							-240.00
M SUNDRY SUPPLY WINDSCREEN SEALANT							80.00
E PNT88000 REMOVE & INSTALL RHR QTR GLASS TO FACILITATE REPAIR							80.00
E PNT98000 SPARY PAINT RHR QTR , RR BUMPER & AFFECTED AREAS							700.00
M SUNDRY SUPPLY BODY PANEL SEALANT							40.00
M SUNDRY TO PERFORM RUST PREVENTION							40.00
A 54900099 CHECK ON WIRING & CHASSIS ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
S SPECIALISTJOB SUPPLY RHR DOOR QUARTER GLASS FILM							80.00
X EXC EXCESS							-300.00
E PNT88000 REMOVE & INSTALL REAR SEAT & REAR COMPONENT - SUPP							120.00
X PANEL ASSY-QUARTER OUTER,RH				1.00	1349.00	20.00	-1079.20
X COVER-RR BUMPER				1.00	651.00	20.00	-520.80
X RETAINER				4.00	2.00	20.00	-6.40
X GUARD-REAR WHEEL,RH				1.00	75.00	20.00	-60.00
X GLASS & MOULDING ASSY-QUARTER				1.00	252.00	20.00	-201.60
X PAD-WINDSHIELD GLASS				10.00	2.00	20.00	-16.00
X STOPPER-GLASS				2.00	4.00	20.00	-6.40

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 12/05/2021	Cust No/Name	/FOO JIEMING
	Reg No/Reg Date	SMQ8777X / 03/01/2020
	Date In/Mileage	12/05/2021/ 16503
	Chassis/Package	KNAF5416ML5059941 /KC17P
	Engine No	G4FGKH739793
	Make/Model	KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim	KLK STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	08/06/2021/ 09:12	BLE	881 / Jojo Cheng	33308

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z TEXT OD CLAIM - AIG DOA: 11/05/2021 SURVEYOR : STEVE LKK 12/05/2021 - 07 DAYS Pro Forma <i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>				

Parts	1,890.40		Nett	4,520.40
Labour	2,690.00	7% GST on	4520.40	316.43
Standard Menu	0.00			
Specialist Job	80.00		Total Payable	4,836.83
Diagnostics Job	0.00			
Sundry/Others	-140.00			
Total(w/o GST)	4,520.40			

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

SUPPLEMENTARY

INSURANCE CO : AIG ASIA PACIFIC INSURANCE PTE LTD

REGISTRATION NO : SMQ8777X

S/N	Description	Qty	Unit Price	Disc%	Amount
<u>LABOUR</u>					
1	REMOVE & INSTALL REAR SEAT & REAR COMPONENT	1.00	120.00	0.00	120.00
2	REPLACE QUARTER PANEL	1.00	120.00	0.00	120.00
Total					<u>240.00</u>
7 % GST					<u>16.80</u>
Grand Total					<u><u>256.80</u></u>

Thank You.

Yours faithfully

CYCLE & CARRIAGE KIA PTE LTD

JoJo Cheng

Customer Service

Tel : +65 6568 4554

CAR NO: SM88777XWIP: 33308

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	R/I Rear Seat & Rear Compartment	? / SUPP	120	Rec	Steve 18/5/21
2	For Replace Quarter Panel	? / SUPP	120	Rec	
3		? / SUPP			
4		? / SUPP			
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT	18/5/21	Steve
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: CERATOSURVEYOR: STEVE



HOME

Online



CERATO/FORTE../2020/G 1.6 MPI..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



ICU



CLU



WPC

12/12

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.

M-E-K-01-00-0246

VCI Ver.

02.54

ECU Ver.

M-E-K-01-00-0187

OS Ver.

Android 10