



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/05/2021

User ID : BoonChewTay

Section A - Accident Details

Registration Number	SMB1334R
Case Reference Number	BUS/05/21/1010
Registration Date	25/3/2013
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Khoo Kay Huat
Type of Accident	Side Swipe
Accident Date and Time	10/5/2021 7:07 PM
Accident Reported Date and Time	10/5/2021 8:15 PM
Is Surveyor Required?	No
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1334R-LEFT FRONT WINDSCREEN CRACKED AND BODY SCRATCHED SLK9010L (TP) INSURED WITH
Prepared Date and Time	12/5/2021 10:38 AM
Chassis Number	WMAA22Z28D7001778
Address	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
total Labour Cost	\$2,120.00	\$0.00
total Spray Cost	\$786.00	\$0.00
total Spare Part Cost	\$9,273.51	\$0.00
total Other Cost	\$0.00	\$0.00
TOTAL COST	\$12,179.51	\$0.00
ump Sum Total	\$12,200.00	\$0.00
Number of Repair Days	50	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	12/05/2021 10:47 AM	
Signature		
Remarks		

12/5/21, 4.11pm

Store (LKK)
W/L AL

4 dys

L/S

by AL sy

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 751105
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 12/05/2021

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	\$2,120.00	1590
Total Labour	\$2,120.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$786.00	616
Total Spray Painting & Panel Beating	\$786.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
010148	GLASS	4001X01-GLASS5171	WINDSCREEN, FRONT: FOR MAN A22 BUS	1.00	\$5,031.80	10.00	\$4,528.62	Replace	✓ OR
006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	✓ IPC
006314	CONSUMABLE		ADHESIVE: DIRECT GLAZING	10.00	\$37.00	0.00	\$370.00	Replace	✓ IPC
006315	CONSUMABLE		ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	✓ IPC
010154	Body	F01001-CW263	FLAP, FRONT: FOR MAN A22 BUS	1.00	\$1,868.80	10.00	\$1,681.92	Replace	X NM
010153	Body	F01001-CW264	COVER, HEADLAMP: FRT LH, FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	X R
010151	Body	F01001-CE265	BUMPER, FRONT: CENT RE, FOR MAN A22 BUS	1.00	\$1,868.80	10.00	\$1,681.92	Replace	X R
010304	VE	8-25101-6539	HEADLAMP, LH (MAN BUS)	1.00	\$1,603.60	10.00	\$1,443.24	Replace	? X NM
010306	VE	81-25320-6111	FLASHER, AUX HEADLAMP, LH (MAN BUS)	1.00	\$904.40	10.00	\$813.96	Replace	? X NM
000917			IU BRACKET	1.00	\$35.00	0.00	\$35.00	Replace	✓ IPC
Total					\$12,484.10		\$11,591.89		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									