ISS REU, DIE IL MAZE	05866 RIV-13 6795
ASS. REC. BIT	SIGNMENT
Date	Veh No: \$3099987 Yr Regn: 2020 1549
From: Date:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Estimated Cost:	Truck / Trailer or
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Make: B.M.W 2181 MSPT LED VI C.C 1497
To Inspect Vehicle No: S3D 9998	1 (a 1 d 1 C4d 1 NII 1 N A
at Workshop m/s DCREGRAMUG	COIOUI
of 363 prexamples RD Rusin	Sp. Keading 00100
Insured: CT	Eng/No:
Policy No.	C/No: WRA 12MC 040 74 26336
Claims No.	Gen. Cond: Good /Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorde / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Norder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / SiRim / STD A/Rim or
	Tyre Size: F: 228 YOR18
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or
Bal. or Market Value:	Front Rear
Dal. Of Warket Value.	R/Bal. R/Bal. mm
IDAO Accident root.	L/Bal. ( mm L/Bal. 6 mm
Dear Vee or No.	D.O.A. 13/0 21 D.O.I. 68/06/21</td
Est. Repairs: days Res.: Yes or No	0.00. (7)05 01
Lum Sum: % 3 Val.: Yes or No	
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / O	UT RGMR 6 Structure affected due to collision
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	
Reparlinit-71K	
Repar linit-71K	
ate/Time, File Pass to? : Preli. Report	Days Of Repair:
ate/Time, File Pass to?  : Preli. Report : Final Report	Days Of Repair: Resurvey No. of Trip: Survey Fee:
ate/Time, File Pass to?  : Preli. Report : Final Report Date/Time, File Return to?	Days Of Repair:  Resurvey No. of Trip:  Survey Fee:  Transportation:
ate/Time, File Pass to? : Preli. Report	Days Of Repair:  Resurvey No. of Trip:  Survey Fee:  Transportation:  Site Insp (\$ )S+RSSI
Repar limit - 71K  ate/Time, File Pass to?  : Preli. Report  : Final Report  Date/Time, File Return to?  Add 1	Days Of Repair:  Resurvey No. of Trip:  Survey Fee:  Transportation:  Fee:  Site Insp (\$ )S+RSSI  Interview (\$ ) Photos
ate/Time, File Pass to?  : Preli. Report : Final Report Date/Time, File Return to?	Days Of Repair:  Resurvey No. of Trip:  Survey Fee:  Transportation:  Fee: : Site Insp (\$ )S+RSSI
Repair   Cinif - 7 K  ste/Time, File Pass to?   : Preli. Report   : Final Report   oate/Time, File Return to?	Days Of Repair:  Resurvey No. of Trip:  Survey Fee:  Transportation:  Site Insp (\$ )S+RSSI  Interview (\$ ) Photos

Estimate No.

### **Performance Motors Limited**

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770

: b1

58415

280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773 315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 (AfterSales) 64796624 (Motorrad)



5,608.99

Page No. : 1 of 4

GST REG. NO: M2 - 0020081 - X

ESTIMATE

Date Estimated 14/05/2021 Prepared By Joseph Yaguel ESTIMATE REPAIR FOR -ACCOUNT 135 Tan Kay Siam China Taiping Insurance (S) Pte Ltd 3 Anson Road 63 Almond Crescent #16-00 Springleaf Tower Singapore 079909 Singapore 677817 MILEAGE REGN. DATE MODEL REGN. NO. CHASSIS NO. 23 SJD9998Y WBA12AK0407G26336 28/09/2020 218i Gran Coupe VALUE 1.275.00 To replace rear bumper panel and right rear tail panel LKK Auto Consultants hence notify the Repairer of the following: 1,038.00 · To resurvey before/after spray painting To respray rear bumper To display damaged part(s) during resurvey · Parts prices are subject to confirmation To check electrical wiring system and lighting at the • Third party survey is on a "Without Prejudice" basis rear section for proper function. No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and 80.00 Sundries. is subject to final approval from Insurance Company Acknowledged by Repairer Total Labour 1: 2,570.00 Signature: Date: YTO PRIC VALUE DESCRIPTION 460.40 460.40 REAR BUMPER CARRIER 250.20 250.20 REAR BUMPER BOTTOM TRIM PANEL (M) 1 73.95 RH SIDE GUIDE FOR BUMPER (MSP) 7 73.95 45.90 45.90 REAR BUMPER RH TRIM (MSP) REAR BUMPER PANEL PRIMED (MSP/PDC/Pde/ 1,313.35 1,313.35 61.65 61.65 REAR CENTRE GUIDE 446.00 REAR RH LIGHT IN THE SIDE PANEL 446.00 20.60 DECOUPLING RINGDMORD Party / Uninsured losses / Direct Settlement 5.15 2,672.05 Regn No. Total Parts Claim No. 06/21 @ 1055 Date & Time 09 Excess S\$ Surveyor's Name Sign 2,570.00 Labour 1 Authorised Date Time 2,672.05 Parts RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / Labour 2 0.00 Surveyor's E-mail 0.00 Excess 366.94 No. of Working Days Recommend Total GST @ 7%

Grand Total

<sup>\*\*</sup> THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

<sup>\*\*</sup> PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

DATE & TIME: 14/05/2021 13:37 (SGT) ON: 1 (14/05/2021 13:37 (SGT))



## SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report correctly the details of the accident to speed up the claims process.

- 1. Freast to the completed by the Policyholder and/or the Authorised Driver
  2. This Form must be completed by the Policyholder and/or the Authorised Driver
  3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

  5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

Date of Submission 14/05/2021 13:37 (SGT) Date of Accident 13/05/2021 14:00 (SGT) Exact Location of Accident Almond Cres, Singapore Additional Location Information Country/State of Loss Singapore

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number SJD9998Y

#### INSURED/POLICYHOLDER

Is company? Name Of Registered Owner TAN KAY SIAM SXXXX679J NRIC No ..... KANTANKS@YAHOO.COM.SG Email Address (Phone) +65-94506052 Mobile Phone No +65-94506052 Alternative Phone No

#### VEHICLE PARTICULARS

**BMW** 218i Variant Exact purpose for which vehicle was being used at time of Private use Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Private car Vehicle Category Transmission Auto 1499

#### INSURANCE COMPANY

Liberty Insurance Pte Ltd Name of Insurance Company ..... Comprehensive Type of Coverage Fleet Policy Policy Number SD20V11822/VPC2/R00 Cover Note Number

#### DRIVER

Name of Driver TAN KAY SIAM SXXXX679J

Birth	
ation	02/05/1971
Of Driving Pass	Indoor
ing experience	02/06/1990
inder	30 YEARS AND 11 MONTHS
bile Number	Male
Phone Number	(Phone) +65-94506052
Email Address	+65-94506052
Address	KANTANKS@YAHOO.COM.SG 63 ALMOND CRESCENT
Address complement	-
Postcode	677817
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	<u> 1</u>
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	
Insurance Company of Other Vehicle Owned by Driver	•
To your vernicle owned by Driver	•
GENERAL INFORMATION OF THE ACCIDENT	
GENERAL INFORMATION OF THE ACCIDENT	
The of Andrews	
Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?	NI <sub>2</sub>
Number of vehicles involved in the accident	No 2
Was anybody injured in the Accident?	Z No
Was any injured conveyed to hospital by ambulance?	INO
Was any other material or property damaged?	-
Number of Descenders (Including Driver)	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s)	NI <sub>2</sub>
soliciting/offering accident claims assistance?	No
DETAILS OF POLICE ACTION	
Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	
CIRCUMSTANCES OF ACCIDENT	
The state of Acological	
REFER TO ATTACH.	X
ATTACHMENT(S)	
Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	1.55
	Yes
Was there any audio recorded?	No
DETAILS OF OTHER	R VEHICLE PROPERTY 1
Vehicle Registration Number	GBG1433S
Vehicle Manufacturer	-
Vehicle Model	
	· ·
V.11.1.0.1	-
Vehicle Category	Goods vehicle
Name of Driver	TAY KIM SENG ERIC
NRIC No	SXXXX294C
Contact Number	(Phone) +65-98791110
( NAME - 33	

complement	•
nce Company Name	China Taiping Insurance (Singapore) Pte. Ltd.
of Damage of property damaged in accident	REAR
Passenger (Including Driver)	24.07

#### WITNESS DETAILS

WITNESS 1

Name TERRY
Phone (Phone) +65-97611780
Email

#### SKETCH PLAN

### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed.
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

1 EOC NOM 1 1

Driver's Signature
(If driver is not the policyholder)

Date & Time:

Reporting Contre Payannel's Signature

erformance Motors Limited

Sime Darby Performance Centre Singapore 159941 Almord Occard

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

<del>'' 3</del>	141	950	17252		en car st	one of	12.	
litness	NE 70	अर्थ	informed	I no the	incident	and	other	
erto	We Ev	$D_{j}$	to Laci	Scere	e exche	ype p	articulous	۲.
C	1	Secretary and			and the state of the	71 ,	5	
-			1 2					_
				11.4 · · · · · · · · · · · · · · · · · · ·				
		-						
				440			are a second	
					117			
					1 / 42			
				A A				
			- A - A - A - A - A - A - A - A - A - A	9.				
					ton-ton-to-		The second secon	
					NAMES OF THE OWNER, WHEN THE PARTY OF THE OWNER, WHEN THE OWNE		4 2 1000	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: / LAN

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Septime aggret's Signature
Performance Motors Limited
NAIC/803 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

# > Back to OneMotoring

# Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	679)
V. D. J. J. S.	And the second s
Vehicle No.:	SJD9998Y
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Jun 2021
Vehicle Make:	B.M.W.
Vehicle Model:	218I MSPT LED HL, LED FL
Primary Colour:	Grey
Manufacturing Year:	2020
Engine No.	42816105B38A15A
Chassis No.:	WBA12AK0407G26336
Maximum Power Output:	=103.0 kW (138 bhp)
Open Market Value:	\$38,049.00
Original Registration Date:	28 Sep 2020
First Registration Date:	28 Sep 2020
Transfer Count:	0
Actual ARF Paid:	\$42,469.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Sep 2030
PARF Rebate Amount:	\$31,851.00
PAN Repate Allount.	\$31,03100
COE Expiry Date:	27 Sep 2030
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$40,989.00
COE Rebate Amount:	\$38,119.00
Total Rebate Amount:	\$69,970.00

The information contained herein is correct as at 09 Jun 2021

# BMW 2 Series 218i Gran Coupe Luxury

Overview

**Financial** 

Accessories

Similar

Research

**Photos** 

Map















Price \$143,800

\$12,980 /yr View models with similar depre Reg Date

27-Nov-2020 (9yrs 5mths 17days COE left)

Mileage

3,800 km

Manufactured (?) 2020

Road Tax ?

Depreciation ?

\$684 /yr

\$62,471 as of today (change)

**Transmission** 

Auto

Dereg Value (?)

\$39,500

1,499 cc

ARF (7)

OMV (?)

\$41,765

103.0 kW (138 bhp)

\$35,546

**Engine Cap** 

COE ?

**Power** 

Curb Weight ? 1,375 kg No. of Owners