

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub

2 Kaki Bukit Ave 2, #01-17

Singapore 417921

Tel No. : +65 6744 0510 / 6842 0051 Fax No. : +65 6741 0510

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

Our Ref: **SMY 3114 A**

Your ref: **SHA 1581 H**

17 May 2021

## **AXA INSURANCE PTE LTD**

8 SHENTON WAY

#24-01 AXA TOWER

SINGAPORE 068811

Attn: Motor Claims Department

BY EMAIL motor.survey@axa.com.sg ONLY

Dear Sir/Madam,

**DATE OF ACCIDENT : 25 Feb 2021**

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS**

**PURSUANT TO PARAGRAPH 2.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES**

We are instructed by **MIKKI CH'NG MAY KHEE** to notify you of a road traffic accident on **25 Feb 2021** at about **07:00 HRS** along **OPEN SPACE CARPARK OF BLK 406 TAMPINES ST 41 LOT 272** involving our client's vehicle **SMY 3114 A & SHA 1581 H** driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be inform that we don't excess to Merimen System and kindly reply to us by Email / Fax.

Yours faithfully,



.....  
**TwinCar Automotive Pte Ltd**