



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21005901/Uuf3e2	
			Date: 07/06/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 6334G	Veh. Inspected	SMY 1281M
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/05/21/2037	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	18/05/2021
2. Vehicle Particulars & Condition				
	Make & Model	AUDI A4 S-LINE (A)	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	WAUZZZ8K5AA035293	Colour	GREY
	Odometer	127972 KM	Steering	AFFECTED
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/40Z R18	MICHELIN	4 mm
	L/H Front Tyre	245/40Z R18	MICHELIN	4 mm
	R/H Rear Tyre	245/40Z R18	MICHELIN	4 mm
	L/H Rear Tyre	245/40Z R18	MICHELIN	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S, O/S BODY AND N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	14/05/2021	Inspection Date	18/05/2021
	Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days	