

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

**AUTOMOBILE INSPECTION REPORT** 



AUTOMOBILE INSPECTION REPORT						
NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC21005903/R1uce2						
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	15-07-2021 INC4		
4		Delieu Destieulese				
1.	Policy Particulars :- THIRD PARTY CLAIM  Insured Veh. SHC 6917E Veh. Inspected SHF 351K					
	Insured Veh.	SHC 6917E		· •	SHF 351K	
	Policy No.	MT/4404000 000	Cover		0.00	
	Claim No.	MT/1131638-002	Exces		0.00	
-	Assign From		Assign		17/05/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA PRIUS	C.C		1798	
	Engine No.	HIDDEN	Year o		2019	
	Chassis No.	JTDKB3FU303089284	Colou	<u> </u>	MAROON	
	Odometer	188422	Steerii		IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	ATREZ	ZO	6 mm	
	L/H Front Tyre	195/65 R15	ATREZ	ZO	6 mm	
	R/H Rear Tyre	195/65 R15	ATREZ	ZO	6 mm	
	L/H Rear Tyre	195/65 R15	ATREZ	ZO	6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	13/05/2021	Inspec	tion Date	17/05/2021	
	Survey held at SMRT AUTOMOTIVE SERVICES PTE LTD					
	60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705					
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					