

|   |   |          |   |   |   |   |        |   |   |             |
|---|---|----------|---|---|---|---|--------|---|---|-------------|
| ⏪ | < | 1 of 2 ? | > | ⏩ | ↺ | ↻ | 100% ▼ | 📄 | 🖨 | Find   Next |
|---|---|----------|---|---|---|---|--------|---|---|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                  |                                                                        |                          |            |  |
|--------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------|--------------------------|------------|--|
| AIG ASIA PACIFIC INSURANCE PTE LTD                                                                                 |                                                                        | Ref: CS/AIG21005909/Evf3 |            |  |
| 78 SHENTON WAY #09-16                                                                                              |                                                                        | Date: 18/05/2021         |            |  |
| AIG BUILDING                                                                                                       |                                                                        |                          |            |  |
| SINGAPORE 079120                                                                                                   |                                                                        | Code: AIG                |            |  |
| <b>1. Policy Particulars :- OWN DAMAGE</b>                                                                         |                                                                        |                          |            |  |
| Insured Veh.                                                                                                       | Veh. Inspected                                                         |                          | SKV 7558R  |  |
| Policy No. 1900099056                                                                                              | Coverage (\$)                                                          |                          | 0.00       |  |
| Claim No.                                                                                                          | Excess (\$)                                                            |                          | 0.00       |  |
| Assign From                                                                                                        | Assign Date                                                            |                          | 18/05/2021 |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                      |                                                                        |                          |            |  |
| Make & Model                                                                                                       | c.c                                                                    |                          | 0          |  |
| Engine No. HIDDEN                                                                                                  | Year of Reg.                                                           |                          |            |  |
| Chassis No.                                                                                                        | Colour                                                                 |                          |            |  |
| Odometer -                                                                                                         | Steering                                                               |                          |            |  |
| Brakes                                                                                                             | Modification                                                           |                          |            |  |
| General                                                                                                            |                                                                        |                          |            |  |
| <b>3. Conditions of Tyres</b>                                                                                      |                                                                        |                          |            |  |
|                                                                                                                    | Size                                                                   | Make                     | Balance    |  |
| R/H Front Tyre                                                                                                     |                                                                        |                          | mm         |  |
| L/H Front Tyre                                                                                                     |                                                                        |                          | mm         |  |
| R/H Rear Tyre                                                                                                      |                                                                        |                          | mm         |  |
| L/H Rear Tyre                                                                                                      |                                                                        |                          | mm         |  |
| <b>4. Description of Damages</b>                                                                                   |                                                                        |                          |            |  |
|                                                                                                                    |                                                                        |                          |            |  |
| <b>5. General Information</b>                                                                                      |                                                                        |                          |            |  |
| Accident Date                                                                                                      | 15/05/2021                                                             | Inspection Date          | 18/05/2021 |  |
| Survey held at                                                                                                     | CYCLE & CARRIAGE KIA PTE LTD<br>209 PANDAN GARDENS<br>SINGAPORE 609339 |                          |            |  |
| <b>5a. Remarks</b>                                                                                                 |                                                                        |                          |            |  |
| A)THE MARKET VALUE IS S\$------(EST. AVERAGE)<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS. |                                                                        |                          |            |  |