

08/11/13 wef
ASS. REC. BY: *marcus*

REF: *CC4/FC121005912/4e93*

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: *SLF 4865X*
at Workshop m/s *1 k lee*
of _____
Insured: *SKW935SR*
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: *SLF4865X* Yr Regn: *27/8/16*
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or *CA/*
Make: *Nissan Dashgqi* c.c. *1197*
Colour: *Red* A/C: Insured / Std / NI / NA
Sp. Reading: *48121* T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: *SJNFEAJI/11714762*
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: *215/60R17 nexen*
R: *64*

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *854k.*
IDAC Accident Rpt: Consistent?: Yes or No
GIA / PR Seen: Consistent?: Yes or No
Est. Repairs: *2* days Res.: Yes or No
Lum Sum: *20* % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS *L7A #38467*
Vehicle: IN / OUT
Date: _____ Person Contacted: *Ryok*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front _____ Rear _____
R/Bal. *6* mm R/Bal. *6* mm
L/Bal. *6* mm L/Bal. *6* mm
D.O.A. *12/5/21* D.O.I. *18/5/21*
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
20/5/21 4/5 #1400 Confirmed with AH hai

Date/Time, File Pass to? : Preli. Report
 : Final Report

1) _____
Date/Time, File Return to?
2) _____

Report Format : _____
Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
Transportation: _____
_____) S + RS _____ SI
_____) Photos
_____) Others
TOTAL

Empty box for additional notes or calculations.

T K LEE AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47
 AQT0BAY SINGAPORE 417883
 Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.
FIRST CAPITAL INSURANCE LTD
 NO.1 NORTH BRIDGE ROAD
 #08-01 HIGH STREET CENTRE
 SINGAPORE 179094
SKW9355R

ESTIMATE

DATE : 14/05/2021
 VEHICLE NO : SLF4865X
 MAKE/MODEL : NISSAN QASHQAI
 ACC DATE : 12/05/2021

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
NETT PRICE			
1	1 REAR BUMPER <i>DO/DE</i>	\$ 876.40	\$ 876.40 ✓
2	1 REAR BUMPER FOAM <i>ru</i>	\$ 155.80	\$ 155.80 X
3	1 REAR BUMPER REINFORCEMENT <i>ru</i>	\$ 691.50	\$ 691.50 X
4	2 REAR BUMPER SIDE RETAINER RH / LH <i>ru</i>	\$ 42.00	\$ 84.00 X
5	1 REAR TAILGATE EMBLEM 'NISSAN' <i>ru</i>	\$ 65.00	\$ 65.00 X
6	1 REAR TAILGATE EMBLEM 'QASHQAI' <i>ru</i>	\$ 94.40	\$ 94.40 ✓
			\$ 1,967.10
		LESS - 10%	\$ 196.71
		TOTAL	\$ 1,770.39

SPECIAL NETT ITEMS			
1	1SET REAR BUMPER REVERSE SENSOR <i>should</i>	\$ 280.00	200
2	1SET REAR BUMPER CLIPS <i>ru</i>	\$ 35.00	✓
		\$ 315.00	

LABOUR CHARGES :			
1	TO KNOCK OUT DENT AND REPLACE ACCIDENT PARTS	280	400.00
2	TO SPRAY PAINTING ON ACCIDENT PARTS	400	500.00
3	TO REMOVE, REPLACE REVERSE SENSOR	50	80.00
			980.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL :

3,065.39

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

not returned here
18/5/21
take photos after 2 days
1/5 \$ 1400

2,970.80