

ASS. REC. BY:

Steve

CC4/LPC 21905915/993

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	X
X	X

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rport: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: XO 2552E Yr Regn: 27/5/2008  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: NISSAN CR 45 CLR/HUB cc 13,974  
 Colour: White A/C: Insured / Std / NI / NA  
 Sp Reading: 71733 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: GK84CLB00251  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modl: Nil / S/Rim / STD A Rim or  
 Tyre Size: F: 295/89R225  
 R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front		Rear
R/Bal. <u>5</u> mm		R/Bal. <u>5</u> mm
L/Bal. <u>5</u> mm		L/Bal. <u>5</u> mm
D.O.A. <u>15/5/21</u>		D.O.I. <u>28/5/21</u>
Survey held at <u>ASM Automotive</u>		
Des. of Damages: Frt / <u>Rear</u> / O/S / N/S / U/C / Rooftop or		
The U/C / Chassis frame / Body Structure affected due to collision.		

Date / Time	Action / Instruction
	Prime mover MV-\$20K - \$8327 = 11,673
	Trailer MV- 7,000

Data/Time, File Pass to?  : Prell. Report  
 : Final Report

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Insp (\$ \_\_\_\_\_)  
 : A/S&I (\$ \_\_\_\_\_)

Survey Fee:	
Transportation:	
\$ + RS. \$ SI	
Photos	
Other:	
TOTAL	

Report Format: \_\_\_\_\_  
 Lumpy: \_\_\_\_\_