

WTS Engineering Pte Ltd

8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163
Company Registration Number: 200505706E

5MKT

Quotation

DATE: 17/05/21
VEHICLE NO: PC6183K
DRIVER: LEE SWEE BOON
ATTENTION TO:
PREPARED BY: Chan Soo Lye

LOCATION: Gul Workshop
Q REF No: Q21/05/1209
DEPARTMENT: WTS Bus Department
ACCIDENT DATE: 11/05/21
REF No: JW-0521-201

S/N	Description	Qty	Cost per Unit	Amount S\$
Labour Costs				
1	TO REPAIR KNOCK RHS REAR CORNER PILLAR.	1	600	480 600.00
Spray Paint				
1	Spray Painting	1	650	500 650.00
	TO PUTTY AND SPRAY PAINTING RHS REAR CORNER PILLAR.			
TOTAL:				1,250.00
Total Amount				SGD 1,250.00

Remarks:

980
3 days

17/5/21

Signature of Workshop Dpt

17/5/21
Self cum

Signature of Department Head

Signature of Claim Department

Ramu
Hp 90010068
3 days
19/05/21 @ 1010
Reg after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: