

IV (P/P)

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 17.05.2021

Time: 10:15:14

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305468957
REGN NO : SHC1722H
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 12.07.2018
DATE/TIME IN : 17.05.2021 09:45
ACCIDENT DATE : 14.05.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2534-G	COVER-FR BUMPER#	1	430.90	20.00	344.72	CRK
0002 04-01-0101-0111-G	BUMPER COVER CLIP	10 L	22.00	20.00	17.60	NEC
0003 04-01-0104-2361-G	MOULDING-FRONT BUMPER CTR	1	368.50	20.00	294.80	SCR
0004 04-01-0104-2971-G	BRACKET-FR BUMPER SIDE SU	1	35.00	20.00	28.00	SVL
0005 04-01-0104-0633-G	MOULDING-FRONT BUMPER RH	1	186.90	20.00	149.52	SCR
0006 04-01-0104-2915-G	LAMP ASSY-HEAD RH#	1	1,993.65	20.00	1,594.92	SCR

SUB-TOTAL : 2,429.56

JOB NATURE

0000 PB	PANEL BEATING	400.00	350
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 17-01	CHECK ALL LIGHTING	50.00	30

MERIMEN \$11 ✓

SUB-TOTAL : 750.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 17.05.2021

Time: 10:15:14

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305468957
REGN NO : SHC1722H
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 12.07.2018
DATE/TIME IN : 17.05.2021 09:4
ACCIDENT DATE : 14.05.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,179.56

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

NA2 CLK
18/5/2021 1530
PIP
2 DAYS
BY PAINT PHOTO

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 17.05.2021 10:06

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order:

JC NO.: 305468957

OWNER

AS COMFORT TRANSPORTATION PTE LTD

OWNER NO. 7010045

RESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

OUNT CARD NO.

REGN NO.:

SHC1722H

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

DATE/TIME IN 17.05.2021 09:45

YR OF MANU.

12.07.2018

TARGET DATE

CHASSIS CODE

KMHC851CVJU103557


COMPLETION DATE/TIME:

ccident Date: 14.05.2021

ATURE: 3P 14.05.2021

JOB DESCRIPTION

/NO LABOR CODE DESCRIPTION



OKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Vo.: SHC1722H

JU

Vehicle No.:

SHC1722H

f Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard