


ASS. REG. BY: Steve CS/AIG 21005955/Evf3

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
☒ TP/WS/TP RES/OD-RES/EVA/INV/MV  
 To inspect Vehicle Mtr \_\_\_\_\_  
 at Workshop mtr \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. 2070117021  
 Claims No. 9045845540SG  
 Sum Insured: \_\_\_\_\_ Excess: 300  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Rat. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 SIA / PR Seat: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repair: \_\_\_\_\_ days Res.: Yes or No  
 Cum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SKB 838J Yr Regn: 11/8/20  
 Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Mitsubishi Outlander c.c. 1998  
 Colour: White A/C: Insured / Std / Nil / N  
 Sp. Reading: N/A T/Radio: Insured / Std / Nil / N  
 Eng/No: \_\_\_\_\_  
 C/No: GF7W 0700447  
 Gen. Cond: Good / Fair / Poor / Burt  
 Steering: In order / Jammed / Locked / Burnt or  
 Brake: In order / Jammed / Locked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 225/55R18  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / ☒ FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. 5 mm R/Bal. 5 mm  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 18/5/21 D.O.L. 19/5/21  
 Survey held at Cycle & Callery  
 Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>MV-11FK</u>
29/7/21	Final fig \$33,413.55 confirmed by email (Red 10.127.78.23%)

Time, File, Pass etc. ☐ : Prel. Report  
☐ : Final Report

29/7/21-Typist

Merimen  
 \$33,413.55

Days Of Repair: 19

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Inve (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation

\$ + RS. \$1

Phone

Others

TOTAL



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15836/KOH YONG BOON Reg No/Reg Date SKB838J / 11/08/202 Date In/Mileage / 18577 Chassis No GF7W0700447 Engine No 4J11CK9724 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN ( Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	19/05/2021/ 12:11	BLE	261 / Edwin Caina	11123		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT <sup>1</sup> BUMPER , FRT BUMPER BODY KIT , FRT SUPPORT PNL , BONNET , LHF <sup>1</sup> FENDER & RHF <sup>1</sup> FENDER REPAIR LHF DOOR , RHF DOOR & FRT CHASSIS				2 5 X 450	2750		4500.00
E PNT98000 RESPRAY FRT <sup>1</sup> BUMPER , FRT BUMPER BODY KIT , FRT SUPPORT <sup>1</sup> PNL , BONNET LHF <sup>1</sup> FENDER , LHF WHEELHOUSE , RHF <sup>1</sup> FENDER , RHF WHEELHOUSE , LHF <sup>1</sup> DOOR RHF <sup>1</sup> DOOR , FRT CHASSIS & FRT A PILLAR LH/RH				7 X 350	2450		4550.00
E PNT88000 RENEW AC CONDENSER & RADIATOR							100.00
A 25000001 TOP UP AIRCON GAS							80.00
A 11900199 REMOVE & REFIT ENGINE ASSY TO FACILITATE REPAIR							? 900.00
A 54900099 REMOVE & REFIT DASHBOARD ASSY INCLUDING CENTRE CLUSTER, RADIO & INSTRUMENT PNL					450		675.00
A 54900099 RENEW DRIVER AIRBAG , KNEE AIRBAG , PASSENGER AIRBAG , AIRBAG SENSOR , CLOCK SPRING & AIRBAG ECU					450		900.00
A 54900099 RENEW FRT SAFETY BELT LH / RH , RR SAFETY BELT LH / RH & SAFETY BELT CATCH					225		450.00
A 15900099 TO RENEW FRT INTAKE MANIFOLD							? 675.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM					30		50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
E PNT88000 CONDUCT CHASSIS ALIGNMENT-CELETTE BENCH							? 1000.00
A WHEELALIGNMENTBP							120.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15836/KOH YONG BOON Reg No/Reg Date SKB838J / 11/08/202 Date In/Mileage / 18577 Chassis No GF7W0700447 Engine No 4J11CK9724 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN ( ) Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	19/05/2021/ 12:11	BLE	261 / Edwin Caina	11123			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
To Conduct Computerize Full Wheel Alignment								50.00
M SUNDRY								
SUPPLY FRT NUMBER PLATE WITH CASING								40 120.00
M SUNDRY								
APPLY ANTI CORROSION ON AFFECTED AREAS								40 80.00
M SUNDRY								
SUPPLY BODY PNL SEALANT								30.00
M SUNDRY								
Sundries					1.00	863.00	23.00	664.51
M FACE,FR BUMPER	GR				1.00	517.00	23.00	398.09
M EXTENSION,FR BUMPER	GR				1.00	48.00	23.00	36.96
M GARNISH,FR BUMPER,LH	GR				1.00	48.00	23.00	36.96
M GARNISH,FR BUMPER,RH	GR				1.00	18.00	23.00	13.86
M BRACKET,FR BUMPER SIDE,LH	GR				1.00	18.00	23.00	13.86
M BRACKET,FR BUMPER SIDE,RH	GR				1.00	361.00	23.00	277.97
M COVER,FR BUMPER	CUT (Silver)				1.00	48.00	23.00	36.96
M GARNISH,FR BUMPER SIDE	GR				1.00	48.00	23.00	36.96
M GARNISH,FR BUMPER SIDE	GR				1.00	220.00	23.00	169.40
M GARNISH,FR BUMPER SIDE	GR				1.00	220.00	23.00	169.40
M GARNISH,FR BUMPER SIDE	GR				1.00	112.00	23.00	86.24
M GARNISH,FR BUMPER SIDE	GR				1.00	112.00	23.00	86.24
M REINFORCEMENT,FR BUMPER	BT				1.00	493.00	23.00	379.61
M BAR,FR BUMPER GUARD	BT				1.00	130.00	23.00	100.10
M REINFORCEMENT,FR BUMPER	BT (metal)				1.00	135.00	23.00	103.95
M REINF,FR BUMPER SIDE,LH	BT (metal)				1.00	60.00	23.00	46.20
M REINF,FR BUMPER SIDE,RH	BT (metal)				1.00	69.00	23.00	53.13
M REINFORCEMENT,FR BUMPR SIDE	BT				1.00	22.00	23.00	16.94
M MOULDING,FR BUMPER,LH	MIS (fig krp)				1.00	116.00	23.00	89.32
M MOULDING,FR BUMPER,RH	MIS				1.00	116.00	23.00	89.32
M LAMP ASSY,FOG,FR LH					1.00	350.00	23.00	269.50
M LAMP ASSY,FOG,FR RH					1.00	348.00	23.00	267.96
M COVER,HEADLAMP SUPT PANEL	MIS				1.00	50.00	23.00	38.50

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



## ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15836/KOH YONG BOON Reg No/Reg Date SKB838J / 11/08/202 Date In/Mileage / 18577 Chassis No GF7W0700447 Engine No 4J11CK9724 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN ( Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	19/05/2021/ 12:11	BLE	261 / Edwin Caina	11123			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M COVER,FR BUMPER	/ MIS				1.00	25.00	23.00	19.25
M GRILLE ASSY,RADIATOR	/ MIS				1.00	550.00	23.00	423.50
M BRACKET,RADIATOR GRILLE,LH	/ MIS				1.00	13.00	23.00	10.01
M BRACKET,RADIATOR GRILLE,RH	/ MIS				1.00	17.00	23.00	13.09
M HEADLAMP ASSY,LH	/ BR				1.00	1948.00	23.00	1499.96
M HEADLAMP ASSY,RH	/ BR				1.00	1948.00	23.00	1499.96
M HOOD	/ DD				1.00	980.00	23.00	754.60
M HINGE,HOOD,LH	/ ?				1.00	68.00	23.00	52.36
M HINGE,HOOD,RH	/ ?				1.00	68.00	23.00	52.36
M INSULATOR,HOOD	/ ?				1.00	133.00	23.00	102.41
M CLIP,HOOD INSULATOR	/ ?				8.00	3.00	23.00	18.48
M WEATHERSTRIP,HOOD	/ ?				1.00	41.00	23.00	31.57
M WEATHERSTRIP,HOOD	/ ?				1.00	40.00	23.00	30.80
M TAPE,BONNET	/ APC				4.00	4.00	23.00	12.32
M LATCH,HOOD	/ BT				1.00	76.00	23.00	58.52
M CABLE,HOOD LOCK RELEASE	/ ?				1.00	36.00	23.00	27.72
M PNL,HEADLAMP SUPT,UPR LH	/ BT				1.00	58.00	23.00	44.66
M PNL,HEADLAMP SUPT,UPR RH	/ BT				1.00	58.00	23.00	44.66
M PANEL,HEADLAMP SUPPORT,UPR	/ BT				1.00	183.00	23.00	140.91
M PANEL,HEADLAMP SUPPORT,LWR	/ ?				1.00	107.00	23.00	82.39
M FENDER,FR LH	/ DD				1.00	622.00	23.00	478.94
M FENDER,FR RH	/ DD				1.00	622.00	23.00	478.94
M INSULATOR,FR FENDER,LH	/ ?				1.00	60.00	23.00	46.20
M INSULATOR,FR FENDER,RH	/ ?				1.00	60.00	23.00	46.20
M SHIELD,FR WHEELHOUSE,LH	/ TAN				1.00	164.00	23.00	126.28
M SHIELD,FR WHEELHOUSE,RH	/ TAN				1.00	164.00	23.00	126.28
M MOULDING,FR WHEEL ARCH,LH	/ APC				1.00	160.00	23.00	123.20
M MOULDING,FR WHEEL ARCH,RH	/ APC				1.00	160.00	23.00	123.20
M RADIATOR ASSY	/ BR				1.00	1096.00	23.00	843.92
M TANK ASSY,RADIATOR COND	/ CRU				1.00	103.00	23.00	79.31
M FAN,COOLING,LH	/ ?				1.00	78.00	23.00	60.06
M FAN,COOLING,RH	/ ?				1.00	78.00	23.00	60.06
M SHROUD,COOLING FAN	/ ?				1.00	260.00	23.00	200.20

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15836/KOH YONG BOON Reg No/Reg Date SKB838J / 11/08/202 Date In/Mileage / 18577 Chassis No GF7W0700447 Engine No 4J11CK9724 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN ( ) Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	19/05/2021/ 12:11	BLE	261 / Edwin Caina	11123
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M MOTOR, COOLING FAN, LH(120W)		1.00	479.00	23.00	368.83
M MOTOR, COOLING FAN, RH(120W)		1.00	479.00	23.00	368.83
M CONDENSER ASSY, A/C REFRIGE		1.00	861.00	23.00	662.97
M PIPE, A/C CONDENSER OUTLET		1.00	262.00	23.00	201.74
M HOSE, A/C COMPR DISCHARGE		1.00	191.00	23.00	147.07
M HOSE, A/C COMPR SUCTION		1.00	235.00	23.00	180.95
M MANIFOLD, INLET		1.00	932.00	23.00	717.64
M BRACKET, ENG FR MOUNTING		1.00	292.00	23.00	224.84
M ROD ASSY, ENG ROLL STOPPER		1.00	155.00	23.00	119.35
M STAY, ENG MOUNTING		1.00	26.00	23.00	20.02
M BRACKET, T/M MOUNTING		1.00	258.00	23.00	198.66
M TANK, WINDSHIELD WASHER		1.00	87.00	23.00	66.99
M GROMMET, WINDSHIELD WASHER		1.00	5.00	23.00	3.85
M HOSE, W/SHLD WSHR TANK FLR		1.00	23.00	23.00	17.71
M HOSE, W/SHLD WSHR TANK FLR		1.00	9.00	23.00	6.93
M CAP, WASHER TANK FILLER		1.00	7.00	23.00	5.39
M SENSOR, W/SHLD WASHER TANK		1.00	114.00	23.00	87.78
M MOTOR, WINDSHIELD WASHER(*)		1.00	156.00	23.00	120.12
M SPRING, AIR BAG SENSOR		1.00	335.00	23.00	257.95
M SENSOR, AIR BAG, LH		1.00	293.00	23.00	225.61
M SENSOR, AIR BAG, RH		1.00	293.00	23.00	225.61
M CONT UNIT, SRS DIAGNOSIS		1.00	1123.00	23.00	864.71
M MODULE, AIR BAG		1.00	1087.00	23.00	836.99
M PANEL, INSTRUMENT		1.00	1123.00	23.00	864.71
M MODULE, PASSENGER AIR BAG		1.00	2349.00	23.00	1808.73
M MODULE, DRIVER KNEE AIR BAG		1.00	1065.00	23.00	820.05
M S/BELT, FR PRE-TENSIO, OTR L		1.00	703.00	23.00	541.31
M S/BELT, FR PRE-TENSIO, OTR R		1.00	703.00	23.00	541.31
M BODY ASSY, AIR CLEANER		1.00	146.00	23.00	112.42
M COVER, AIR CLEANER		1.00	156.00	23.00	120.12
M DUCT, A/CLNR TO THROT BODY		1.00	161.00	23.00	123.97
M DUCT, A/CLNR INTAKE		1.00	187.00	23.00	143.99
M HARNESS, FOG LAMP		1.00	130.00	23.00	100.10

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV15836/KOH YONG BOON Reg No/Reg Date SK8838J / 11/08/202 Date In/Mileage / 18577 Chassis No GF7W0700447 Engine No 4J11CK9724 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN ( Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	19/05/2021/ 12:11	BLE	261 / Edwin Caina	11123

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M COVER, RELAY BOX / <i>OR</i>	1.00	52.00	23.00	40.04
M BOX ASSY, RELAY / <i>OR</i>	1.00	409.00	23.00	314.93
M COVER ASSY, ENG, UPR / <i>OR</i>	1.00	136.00	23.00	104.72
M SEAT BELT, FR SEAT, INR RH / <i>James (H-)</i>	1.00	101.00	23.00	77.77
M SEAT BELT, FR SEAT, INR LH / <i>James (H-)</i>	1.00	101.00	23.00	77.77
M ADJUSTER, FR S/BELT ANCH, LH / <i>James (H-)</i>	1.00	67.00	23.00	51.59
M ADJUSTER, FR S/BELT ANCH, LH / <i>James (H-)</i>	1.00	67.00	23.00	51.59
M S/BELT, #2 PRE-TENSIO, OTR R / <i>James (H-)</i>	1.00	472.00	23.00	363.44
M S/BELT, #2 PRE-TENSIO, OTR L / <i>James (H-)</i>	1.00	472.00	23.00	363.44

Estimate

SURVEYOR NAME: Steve (LKK)  
 SURVEYOR SIGNATURE: 19/5/21, 5:00pm  
 DATE: P/P  
 REMARKS: By B-L SM  
00- ALI AL

EXPIRY: ?  
16 dys

Nett 38,146.80  
 7% GST on 38146.80 2670.28  
 Total Payable 40,817.08

LKK Authorized &amp; accepted by the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Subsequent repairs are at customer's cost

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	18/05/2021 17:01 (SGT)
Date of Accident	18/05/2021 14:50 (SGT)
Exact Location of Accident	Still Rd S, Singapore
Additional Location Information	STILL ROAD SOUTH
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKB838J
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	KOH YONG BOON
NRIC No	SXXXX488E
Email Address	YONGBOONKOH@GMAIL.COM
Mobile Phone No	(Phone) +65-97686180
Alternative Phone No	+65-97686180

### VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Outlander
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1998

### INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2070117021
Cover Note Number	-

### DRIVER

Name of Driver	KOH YONG BOON
NRIC No	SXXXX488E

Date Of Birth  
Occupation  
Date Of Driving Pass  
Driving experience  
Gender  
Mobile Number  
Alt. Phone Number  
Email Address  
Address  
Address complement  
Postcode  
Is the driver the policyholder?  
If No, Relationship of the Driver with the Insured  
Does Driver Own Other Vehicles?  
Vehicle Registration Number of Other Vehicle Owned by Driver  
Insurance Company of Other Vehicle Owned by Driver

23/03/1966  
Indoor  
21/07/1988  
32 YEARS AND 10 MONTHS  
Male  
(Phone) +65-97686180  
+65-97686180  
YONGBOONKOH@GMAIL.COM  
3 JALAN PUNAI

-  
418826  
Yes  
-  
No  
-  
-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident  
Weather Conditions  
Road Surface

Collision - Head to Rear  
Raining  
Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?  
Number of vehicles involved in the accident  
Was anybody injured in the Accident?  
Was any injured conveyed to hospital by ambulance?  
Was any other material or property damaged?  
Number of Passengers (Including Driver)  
Has the driver been approached by unknown person(s)  
soliciting/offering accident claims assistance?

No  
2  
Yes  
No  
Yes  
1  
No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?  
Was notice of intended Prosecution given?  
If yes, against whom?

No  
No  
-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACHMENT

##### ATTACHMENT(S)

Are accident photos available for attachment?  
Was there any video captured by Car Camera?  
Was there any audio recorded?

Yes  
No  
No

#### DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number  
Vehicle Manufacturer  
Vehicle Model  
Vehicle Variant  
Vehicle Colour  
Vehicle Category  
Name of Driver  
Contact Number  
Address  
Address complement

GBC5431S  
Toyota  
-  
-  
-  
Commercial vehicle  
KOO YEE PIN  
(Phone) +65-86193185  
-  
-



Vehicle Code  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (Including Driver)

### INJURED PERSONS DETAILS

#### INJURED 1

Name of injured person  
Address  
Address Complement  
Post Code  
Approximate Age Years Old  
Injuries Sustained  
Injured person in which vehicle?  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance?

KOH YONG BOON

SMALL CUTS ON LOWER LEG (LEFT)

SKB838J


Yes

No

## SKETCH PLAN

### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature / Date & Time  
18/5/21

Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel

### Sketch Plan




Describe Circumstances of the Accident

on 18 May 2021 at around 2:50 pm, I was driving along  
Still Road South. All of a sudden, the long in front of me  
stopped. Brake in front of me. I stopped onto the back immediately  
but due to the wet road condition, the vehicle skidded and  
hit the back of the long GBC 5431C.  
We then got down from the vehicle to exchange details.

Declaration

We declare the foregoing particulars are true in every respect.

 18/5/21

Policyholder's Signature / Date &  
Time

Driver's Signature (If driver is not the policyholder) / Date  
& Time



Witnessed by Reporting Centre  
Personnel

COVER NOTE

## CYCLE &amp; CARRIAGE AUTO PROTECTOR PRIVATE VEHICLE

The following risk described on this Cover Note is hereby HELD COVERED on the terms and conditions of the policy issued to the Policyholder.

Name of Policyholder : KOH YONG BOON  
 Period of Insurance : 07-Aug 2020 to 06-Aug 2022  
 Engine No. : 4J11CK9724  
 Chassis No. : GF7W0700447



Vehicle No. : SLB 820J  
 Cover Note No. : 2070117021  
 Endorsement No. :  
 Issued Date : 07 Aug 2020



## ABOUT THE COVER

Make/Model : MITSUBISHI Outlander 2.0 Elegance/Sports  
 Engine Capacity/Tonnage : 1,998.00 CC  
 Driver Restriction : NA  
 Person or Classes of Persons Entitled to Drive\* :  
 Sum Insured : Market Value  
 Off Peak Car : No  
 First Year of Registration : 2020  
 Insuring with COE/PARF : Yes

a) The Policyholder  
 b) Any other person who is driving on the Policyholder's order or with his/her permission.  
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Mileage Condition : Unlimited Mileage

Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.  
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

## EXCESS

Section 1  
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2  
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)  
 KOH YONG BOON - \$600 (Own Damage), \$600 (Flood Cover)

## APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
  2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 406650 67461000
  3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 20 Leng Kee Rd Singapore 159094 64708688
  4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000
- For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.sg](http://www.aig.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

## IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: Standard Chartered Bank (Singapore) Limited

If you do not receive your Certificate of Insurance and policy documents within 30 days from the inception date stated on this cover note, please contact AIG immediately.  
 I/We hereby certify that this Cover Note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia). For Corporate Policies, this Cover Note is valid for 60 days from the commencement date of the period of insurance.

0504675231

CYCLE & CARRIAGE - MEGEN  
 239 ALEXANDRA ROAD  
 SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature.

Bang-Chao Ang