



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21005994/Uqf3n2	
			Date: 15/06/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 7528T	Veh. Inspected	YN 8075L	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2101538/SYH	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	20/05/2021	
2. Vehicle Particulars & Condition				
Make & Model	mitsubishi canter feb21 (A)	c.c	2998	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	4P10B44578	Colour	WHITE	
Odometer	179312 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	AUSTONE	6 mm	
L/H Front Tyre	195 R15	AUSTONE	6 mm	
R/H Rear Tyre	195 R15 (D)	AUSTONE	6/6 mm	
L/H Rear Tyre	195 R15 (D)	AUSTONE	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/05/2021	Inspection Date	20/05/2021	
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	