


**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 ( ) TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle Not \_\_\_\_\_  
 at Workshop not \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. 1900015551-01  
 Claims No. 7069851900SG  
 Sum Insured: \_\_\_\_\_ Excess: 0  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.



Est. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 CIA / PR Sent: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repair: \_\_\_\_\_ days Res.: Yes or No  
 Sum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SGH 7373C Yr Regn: 22/2/19  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Mitsubishi Attrage c.t. 1193  
 Colour: GJ A/C: Insured / Std / NI / N  
 Sp. Reading: 30008 T/Radio: Insured / Std / NI / N  
 Eng/No: \_\_\_\_\_  
 C/No: MMRSLA157KH001337  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 185/55R15  
 R: 11  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. 5 mm R/Bal. 5 mm  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 18/5/21 D.O.I. 19/5/21  
 Survey held at Cycle & Collap  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear LH: 1 RH  
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
20/05/21 @ 1.48pm	revert to AIG via Merimen.
21/05/21 @ 8.53am	Kok Chong informed C/A via Merimen.
21/05/21 @ 10.26am	Infomred Edwin C/A & ex: \$300 by email.
	Confirm final figure at \$15,416.39 20days before GST
	red: 5147.88; 25%

Time/Time, File Pass is? ☐ : Prell. Report  
☐ : Final Report  
 Time/Time, File Return is? \_\_\_\_\_  
 Days Of Repair: 20  
 Resurvey No. of Trip: 2  
 Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Inve (\$ \_\_\_\_\_)  
☐ : Wash and (\$ \_\_\_\_\_)  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 Police: \_\_\_\_\_  
 Others: \_\_\_\_\_  
 TOTAL: \_\_\_\_\_  
 WAF: \_\_\_\_\_  
 WAF Sum / L.P. / 15 15416.39



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel 65684555 Fax: 65691056



## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Mr PETER TAN Reg No/Reg Date SGH7373C*GPCP/ 22/02/201 Date In/Mileage / 0 Chassis No MMBSTA13AKH001237 Engine No 3A92UHN9315 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	18/05/2021/ 18:48	BLC	261 / Edwin Caina	11083			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000		RENEW LHR FENDER, RHR FENDER, RR BUMPER, RR BUMPER BODY KIT, rear end panel						5400.00
		BOOTLID & RHR DOOR						
		REPAIR RR FLR PNL, LHR WHEELHOUSE, RHR WHEELHOUSE & RHF DOOR			7	450		
E PNT98000		RESPRAY RHF DOOR, RHR DOOR, RHR FENDER, RHR WHEELHOUSE, BOOTLID, RR FLR PNL, RR END PNL, RR BUMPER, RR BUMPER BODY KIT, LHR FENDER & LHR WHEELHOUSE						3850.00
E PNT88000		REMOVE & REFIT RHR DOOR COMPONENT						120.00
E PNT88000		REMOVE & REFIT BOOTLID COMPONENT						120.00
A 13900099		REMOVE & REFIT FUEL TANK ASSY						450.00
E PNT88000		REMOVE & REFIT RR FLR BOARD, TRIM, CARPET & SEAT						120.00
A 54900099		CHECK WIRING ELECTRICAL SYSTEM						30.00
A 10028901		TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST						120.00
E PNT88000		REMOVE & REFIT RR WINDSCREEN GLASS						240.00
M SUNDRY		SUPPLY RR WINDSCREEN SEALANT						80.00
M SUNDRY		SUPPLY RR NUMBER PLATE WITH CASING						50.00
E PNT88000		REMOVE & REFIT REVERSE SENSOR						60.00
M SUNDRY		SUPPLY REVERSE SENSOR						220.00
M SUNDRY								80.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Mr PETER TAN Reg No/Reg Date SGH7373C*GPCP/ 22/02/201 Date In/Mileage / 0 Chassis No MMBSTA13AKH001237 Engine No 3A92UHN9315 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	18/05/2021/ 18:48	BLC	261 / Edwin Caina	11083			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
APPLY ANTI CORROSION ON AFFECTED AREAS								
M SUNDRY								<del>80.00</del> 80.00 ✓
SUPPLY BODY PNL SEALANT								
M SUNDRY								40.00 X
SUPPLY C&C BADGE								
M SUNDRY								30.00 ✓
Sundries								
M FACE,RR BUMPER	✓	OR			1.00	751.00	23.00	578.27
M BRACKET,RR BUMPER,LH	✓	OR			1.00	28.00	23.00	21.56
M BRACKET,RR BUMPER,RH	X				1.00	28.00	23.00	21.56
M CLIP,RR BUMPER	✓	nee			4.00	4.00	23.00	12.32
M PANEL,RR END	✓	00 (photo)			1.00	427.00	23.00	328.79
M MUD GUARD,RR LH	✓	mis			1.00	41.00	23.00	31.57
M MUD GUARD,RR RH	✓				1.00	41.00	23.00	31.57
M SHIELD,RR WHEELHOUSE,LH	✓	CRV			1.00	40.00	23.00	30.80
M SHIELD,RR WHEELHOUSE,RH	X				1.00	40.00	23.00	30.80
M DUCT,RR VENTILATOR	✓				1.00	30.00	23.00	23.10
M COVER,RR VENTILATOR	✓				1.00	40.00	23.00	30.80
M BUZZER,KEYLESS OPERATIO,RR	✓	OR			1.00	91.00	23.00	70.07
M ANT,KEYLESS OPERATION,RR	✓				1.00	96.00	23.00	73.92
M TRIM,RR END	✓				1.00	66.00	23.00	50.82
M TRIM,TRUNK ROOM SIDE,LH	✓				1.00	158.00	23.00	121.66
M PANEL,QTR,OTR LH	✓	00			1.00	759.00	23.00	584.43
M PANEL,QTR,OTR RH	✓	00			1.00	767.00	23.00	590.59
M PANEL,RR COMB LAMP HSG,LH	✓	BT			1.00	60.00	23.00	46.20
M PANEL,RR COMB LAMP HSG,RH	✓				1.00	60.00	23.00	46.20
M EXTN,QTR PANEL,UPR OTR LH	✓	BT			1.00	118.00	23.00	90.86
M EXTN,QTR PANEL,UPR OTR RH	✓				1.00	118.00	23.00	90.86
M GLASS,RR WINDOW	X				1.00	0.00	23.00	
M STOPPER,WINDSHIELD GLASS	✓	AK			2.00	3.00	23.00	4.62
M SPACER,RR WINDOW	✓	AK			3.00	9.00	23.00	20.79
M PANEL,TRUNK LID	X				1.00	795.00	23.00	612.15
M WEATHERSTRIP,TRUNK LID	✓	CRV			1.00	157.00	23.00	120.89

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



## ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Mr PETER TAN Reg No/Reg Date SGH7373C*GPCP/ 22/02/201 Date In/Mileage / 0 Chassis No MMBSTA13AKH001237 Engine No 3A92UHN9315 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	18/05/2021/ 18:48	BLC	261 / Edwin Caina	11083
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M HINGE, TRUNK LID, LH	X	1.00	203.00	23.00	156.31
M HINGE, TRUNK LID, RH	X	1.00	203.00	23.00	156.31
M LATCH, TRUNK LID	X	1.00	218.00	23.00	167.86
M MARK, THREE-DIA	X	1.00	70.00	23.00	53.90
M MARK, ATTRAGE	X	1.00	21.00	23.00	16.17
M LAMP ASSY, COMB, RR LH	BR	1.00	337.00	23.00	259.49
M LAMP ASSY, COMB, RR RH	BR	1.00	337.00	23.00	259.49
M REFLECTOR LH		1.00	23.00	23.00	17.71
M REFLECTOR RH		1.00	23.00	23.00	17.71
M PANEL ASSY, RR DOOR, RH	DO	1.00	831.00	23.00	639.87
M MLDG, R/DR WDO BELT LINE, RH	X	1.00	66.00	23.00	50.82
M TAPE, RR DOOR SASH, RH	MC	1.00	29.00	23.00	22.33
M UNPAINTED BODYKITS	BR	1.00	1643.00	20.00	1314.40
M DECAL, MIVEC	X	1.00	36.00	23.00	27.72

SURVEYOR NAME: Steve CLKK) 19/5/21, 3:00pmSURVEYOR SIGNATURE: DO-NALDATE: EXCISE-?REMARKS: PIP, P, BL SM  
20 daysLKK Auto Consultants hence notify  
the Repairer of the following:

• To resurvey before/after spray painting

Confirm & accepted by: damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

Nett	17,915.29
7% GST on	17915.29
Total Payable	19,169.36

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	18/05/2021 14:52 (SGT)
Date of Accident	18/05/2021 07:10 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	PIE (TUAS) 19KM L/P929
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGH7373C
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN CHYE HUAT PETER
NRIC No	SXXXX681G
Email Address	PETER.TAN@YMAIL.COM
Mobile Phone No	(Phone) +65-81234893
Alternative Phone No	+65-81234893

#### VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Attrage
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1193

#### INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1900015551-01
Cover Note Number	-

#### DRIVER

Name of Driver	TAN CHYE HUAT PETER
NRIC No	SXXXX681G

Date Of Birth .....  
Occupation .....  
Date Of Driving Pass .....  
Driving experience .....  
Gender .....  
Mobile Number .....  
Alt. Phone Number .....  
Email Address .....  
Address .....  
Address complement .....  
Postcode .....  
Is the driver the policyholder? .....  
If No, Relationship of the Driver with the Insured .....  
Does Driver Own Other Vehicles? .....  
Vehicle Registration Number of Other Vehicle Owned by Driver .....  
Insurance Company of Other Vehicle Owned by Driver .....

16/03/1957  
Indoor  
12/11/1979  
41 YEARS AND 6 MONTHS  
Male  
(Phone) +65-81234893  
+65-81234893  
PETER TAN@YMAIL.COM  
BLK 62 LORONG 4 TOA PAYOH #18-101  
-  
310062  
Yes  
-  
No  
-  
-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident .....  
Weather Conditions .....  
Road Surface .....

Collision - Head to Rear  
Clear  
Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? .....  
Number of vehicles involved in the accident .....  
Was anybody injured in the Accident? .....  
Was any injured conveyed to hospital by ambulance? .....  
Was any other material or property damaged? .....  
Number of Passengers (Including Driver) .....  
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? .....

No  
3  
No  
-  
Yes  
2  
No

#### PASSENGER 1

Name .....  
Gender .....

TAN PEIXIAN JOAN  
Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? .....  
Was notice of intended Prosecution given? .....  
If yes, against whom? .....

No  
No  
-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACHMENT

##### ATTACHMENT(S)

Are accident photos available for attachment? .....  
Was there any video captured by Car Camera? .....  
Was there any audio recorded? .....

Yes  
No  
No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number .....  
Vehicle Manufacturer .....  
Vehicle Model .....  
Vehicle Variant .....  
Vehicle Colour .....  
Vehicle Category .....

SLQ3908E  
Honda  
-  
-  
Blue  
Private car

Name of Driver  
Contact Number  
Address  
Address complement  
Postcode  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (Including Driver)

PRIS YAP  
(Phone) +65-90608472

-  
-  
-  
-  
-  
-  
-

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number  
Vehicle Manufacturer  
Vehicle Model  
Vehicle Variant  
Vehicle Colour  
Vehicle Category  
Name of Driver  
Contact Number  
Address  
Address complement  
Postcode  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (Including Driver)

FBQ4943P

-  
-  
-  
-  
-

Motorcycle

-  
-  
-  
-  
-  
-  
-

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.

6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Quilin 18/5/21 0937h  
Policyholder's Signature / Date & Time

\_\_\_\_\_  
Driver's Signature (If driver is not the policyholder) / Date & Time

\_\_\_\_\_  
Witnessed by Reporting Centre Personnel

### Sketch Plan



# Describe Circumstances of the Accident

I was driving in the middle lane of PIE (Tua). I saw a motorcycle (Motorcycle JTP 2788) in front skidded.  
I braked and swerve slightly to my right and stopped without any collision.  
Vehicle SLA 3908E hit the rear of my car.  
Shortly motorcycle FBA 4943 P hit the right side of my car.  
Traffic Police arrived and took over the situation.  
Motorcyclist JTP 2788 injured his hand and was taken to hospital by ambulance.  
In car camera SD Card was taken by traffic police.

## Declaration

We declare the foregoing particulars are true in every respect.

Paula 18/5/21 09:34am

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

[Signature]  
Witnessed by Reporting Centre Personnel



# CERTIFICATE OF INSURANCE

## CYCLE & CARRIAGE AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : TAN CHYE HUAT PETER  
 Period of Insurance : 22 Feb 2021 To 21 Feb 2022  
 Engine No. : 3A92UHN9315  
 Chassis No. : MMBSTA13AKH001237

Vehicle No. : SGH7373C  
 Policy No. : 1900015551-01  
 Endorsement No. :  
 Issued Date : 05 Jan 2021

### ABOUT THE COVER

Make/Model : MITSUBISHI ATTRAGE 1.2 CVT  
 Engine Capacity/Tonnage : 1,193.00 CC  
 Driver Restriction : NA  
 Person or Classes of Persons Entitled to Drive\* :  
 Sum Insured : Market Value  
 Off Peak Car : No  
 First Year of Registration : 2019  
 Insuring with COE/PARF : Yes

a) The Policyholder  
 b) Any other person who is driving on the Policyholder's order or with his/her permission.  
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.  
 You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Mileage Condition : Unlimited Mileage

Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.  
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc  
 \* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

### EXCESS

Section 1  
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2  
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

TAN CHYE HUAT PETER - \$600 (Own Damage), \$600 (Flood Cover)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501  
 2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000  
 3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 20 Leng Kee Rd Singapore 159094 64708633  
 4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000  
 For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.sg](http://www.aig.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

**AIG Asia Pacific Insurance Pte. Ltd.**  
 This computer generated document does not require a signature.

0504620206  
 C&CMCP2 - FLOREN  
 239 ALEXANDRA ROAD  
 SINGAPORE 159930  
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIGSGMOBILEAPP