



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21006011/R1vf3n2	Date: 13/08/2021
			Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJB 4960Z	Veh. Inspected	GBF 5888S
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10010301/HA	Excess (\$)	0.00
	Assign From	IVY RATILLA	Assign Date	20/05/2021
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ VITO 114 CDI	c.c	2143
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WDF44760323214925	Colour	BLUE
	Odometer	191973 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/65 R16C	KAPSEN	7 mm
	L/H Front Tyre	215/65 R16C	KAPSEN	7 mm
	R/H Rear Tyre	215/65 R16C	KAPSEN	7 mm
	L/H Rear Tyre	215/65 R16C	KAPSEN	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	15/05/2021	Inspection Date	20/05/2021
	Survey held at	WOON MENG MOTOR PTE LTD 50 BUKIT BATOK ST 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	