

(08/11/13) wef:

ASS. REC. B: Marcus

REF:

CC4/GRB21006014/Ues3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBN 86877

at Workshop m/s

Ero fis

10-30

of

Insured:

SLJ 71866

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$8500

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

478A

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 2583

Veh No:

FBN 86877

Yr Regn:

27/12/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

GDR155R

Make:

Yamaha Aerox

C.C

155

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

no key

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MH3SG4620JJ050131

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

110/80-14

R:

140/70-14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAXXIS

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

14/5/21

D.O.I.

21/5/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

f.r.t, o/s Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

painting expansion

13/8/21 confirmed L/S & 1500 with Mr Teo.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Email: erofia@singnet.com.sg

Name : Mohammad Nazry Bin Taib

Accident Date : 14-May-21

Vehicle No : FBN8687T

Vehicle Model : Yamaha Aerox
GDR155R CVT

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
1	Front fork assy <i>111 X</i>	\$ 980.00 X
1	Fork under bracket <i>111 X</i>	\$ 190.00 X
1	Front sport rim <i>111 X</i>	\$ 550.00 X
1	Front brake disc <i>111 X</i>	\$ 180.00 X
1	Front rim shaft <i>111 X</i>	\$ 52.00 X
1	Headlamp <i>50 X</i>	\$ 550.00 X
1	Side mirror (1 set) <i>cut ✓</i>	\$ 120.00 ✓
1	Handle-bar <i>800 X</i>	\$ 135.00 X
1	Brake lever - R/H <i>cut ✓</i>	\$ 52.00 ✓
1	Footstep panel <i>cut ✓</i>	\$ 255.00 ✓
1	Footstep panel lower cover <i>cut ✓</i>	\$ 170.00 ✓
1	Belt cover <i>cut 111 X</i>	\$ 175.00 X
1	Air filter cover <i>cut 111 X</i>	\$ 125.00 X
1	Exhaust assy <i>R X</i>	\$ 680.00 X
1	Exhaust protector <i>cre. ✓</i>	\$ 48.00 ✓
1	Fairing cover (1 set) <i>cut 1300</i>	\$ 1,450.00 ✓
		\$ 5,712.00
	Less 10%	\$ 571.20
		\$ 5,140.80

Special Net Items

1	Number plate (1 set) <i>111 X</i>	\$ 28.00 X
2	Fork oils <i>111 X</i>	\$ 30.00 X
2	Fork oil seals <i>111 X</i>	\$ 56.00 X
1	Steering cone (1 set) <i>111 X</i>	\$ 120.00 X
		\$ 234.00

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Email: erofia@singnet.com.sg

Name : Mohammad Nazry Bin Taib

Accident Date : 14-May-21

Vehicle No : FBN8687T

Vehicle Model : Yamaha Aerox
GDR155R CVT

Estimated Repair Costs


S/No. Labour

1	To provide towing service	\$ 11	60.00	X
2	To provide wiring and reset headlamp focusing	\$ 11	80.00	X
3	To repair body frame	\$ 11	380.00	X
4	To provide labour	\$ 300	450.00	
		\$	970.00	

Grand Total

\$ 6,344.80

Singapore Dollars: Six Thousand Three Hundred Forty-Four and Cents: Eighty only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: