

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
	SMRT AUTOMOTI	VE SERVICES PTE LTD	Ref:	CS/SMR21006017/Euf3e2
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 17705	Date	9: 15/06/2021
			Cod	e: SMR
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SMB 127D	Veh. Inspected	SHC 7707M
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/05/21/5037	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	20/05/2021
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI AE IONIQ	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	KMHC851CVLU180573	Colour	YELLOW
	Odometer	149938 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	WEST LAKE	5 mm
	L/H Front Tyre	195/65 R15	WEST LAKE	5 mm
	R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
	L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
4.	Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	20/05/2021	Inspection Date	21/05/2021
	Survey held at 31 Corporation Rd, Singapore 649806  Repairer DING AUTOMOTIVE PTE LTD			
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days			
	1		,	