

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: YU DOMINIC YISHAN Code: ASM 1.
SINGAPORE 068811
1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SH 6044S Veh. Inspected SFR 8080A Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S1M03ACK Excess (\$) 0.00 Assign From YU DOMINIC YISHAN Assign Date 20/05/2021 2. Vehicle Particulars & Condition Make & Model B.M.W. 523I c.c 2497 Engine No. HIDDEN Year of Reg. 2010 Chassis No. WBAFP32030C257900 Colour BLACK Odometer 183731 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD Conditions of Tyres
Insured Veh. SH 6044S
Policy No. VFX/P2419138 Coverage (\$) 0.00
Claim No. S1M03ACK Excess (\$) 0.00 Assign From YU DOMINIC YISHAN Assign Date 20/05/2021 2. Vehicle Particulars & Condition Make & Model B.M.W. 523I c.c 2497 Engine No. HIDDEN Year of Reg. 2010 Chassis No. WBAFP32030C257900 Colour BLACK Odometer 183731 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD Conditions of Tyres
Assign From YU DOMINIC YISHAN Assign Date 20/05/2021 2. Vehicle Particulars & Condition Make & Model B.M.W. 523I c.c 2497 Engine No. HIDDEN Year of Reg. 2010 Chassis No. WBAFP32030C257900 Colour BLACK Odometer 183731 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD Conditions of Tyres
2. Vehicle Particulars & Condition Make & Model B.M.W. 523 c.c 2497 Engine No. HIDDEN Year of Reg. 2010 Chassis No. WBAFP32030C257900 Colour BLACK Odometer 183731 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres
Make & Model B.M.W. 523I c.c 2497 Engine No. HIDDEN Year of Reg. 2010 Chassis No. WBAFP32030C257900 Colour BLACK Odometer 183731 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD Conditions of Tyres
Engine No. HIDDEN Year of Reg. 2010 Chassis No. WBAFP32030C257900 Colour BLACK Odometer 183731 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD Conditions of Tyres
Chassis No. WBAFP32030C257900 Colour BLACK Odometer 183731 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD Conditions of Tyres
Odometer 183731 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD Conditions of Tyres
Brakes IN ORDER Modification SPORTS RIM General GOOD Conditions of Tyres
General GOOD Conditions of Tyres
3. Conditions of Tyres
Size Make Balance
R/H Front Tyre 225/50 R18 PIRELLI 6 mm
L/H Front Tyre 225/50 R18 PIRELLI 6 mm
R/H Rear Tyre 225/50 R18 PIRELLI 6 mm
L/H Rear Tyre 225/50 R18 PIRELLI 6 mm
4. Description of Damages
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
5. General Information
Accident Date 18/05/2021 Inspect Date / Time 24/05/2021 (01:33 PM)
Survey held at SZE KANG AUTOMOBILE SPRAYING SERVICES
BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #03-17 AMK AUTO POINT SINGAPORE 568047
5a. Remarks
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000
5b. Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days

Report Ref No. CS3/ASM21006032/Bvce2

Inspected By

LIM TEOW GUAN

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser