

REF: CS1/LAW21006040/Gvf3

Special Instruction:

### ASSIGNMENT (Office)

From (Person): RAYMOND of LAW Date/Time: 21/5/2021 12:30 PM

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

L/SUM : \$ 24,400.00

Third Parties:

Claimant:

Surveyor:

Workshop: MOTOR INTEL AUTOMO PTE LTD

### OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SMA 6298J

Insured: SLA 7828K

at Workshop m/s MOTOR INTEL AUTOMO PTE LTD

Tel: 6281 0087

of 13 KAKI BUKIT ROAD 4 @ BARTLEY BIZ CENTRE #01-20 SINGAPORE 147807

Policy No: KEN-Legal\_APAC.FID270858

Claim No: MC/MC 6395/2019

Sum Insured:

Excess:

Make of Veh:

D.O.A. 27-12-2018

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT \_\_\_\_\_

Date/Time: 10/6/21 Confirmed with \_\_\_\_\_ Final Fig \_\_\_\_\_, \_\_\_\_ days (Red \$ \_\_\_\_/\_\_\_\_%; Original 11 days)

Date/Time: 10/6/21 Submit Final Fig LS \$14,850, 8 days (Red \$ 9550 / 39 %; Original      days)

[illegible]

**Para(1) : Parts found not replaced (To highlight *R* or *UB*, *LR*, *Etc*)**

**Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)**

**Para(3) : Nett Value**

Market Value : \_\_\_\_\_

Salvage Value : \_\_\_\_\_

Nett Value : \_\_\_\_\_

Inspected/  
Evaluated by:

Fee Charged: 50/50 Date:

Basic &amp; Add

Transport

## Photos

Others

Total

1) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

2) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_

3) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

4) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_

5) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

6) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_