

Tp China.

SMF493&H. 2018/Nov

Veron

Toyota Prius. 1797cc

ZVW506137735

Front RH Door Wing Mirror ^{Damaged} 681.50. -

Front RH Door Wing Mirror ^{new} Signallamp 184 X

Front RH Wheel Rim. ^{NP} 800 (sw) X

Panel Benty

~~200~~ 100

Spray Painting.

~~200~~ 100

Wiring.

~~50~~ 30.

To perform wheel alignment.

150 X

list: 681.50

Labour: 230

Len 25%: 511.12

total: 741.12

L/s: 600

01 Day.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: