

Enquire Vehicle's Insurance Particulars (As At 31 Mar 2021 / 14:40:00)

Vehicle No.:

WC6103J

Make Description/Model:

VOLVO / FMX370 84R SC

Insurance Company Name:

MSIG INSURANCE (SINGAPORE) PTE LTD

Business Transaction Reference No.:

20210405103140394657

Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).

SS1F21410004 - MEGA GAS MOTOR & PANEL SERVICE PTE LTD
ENTRY DATE & TIME: 01/04/2021 18:13 (SGT)
SUBMITTED BY: JAFEE CHANG
VERSION: 1 (01/04/2021 18:13 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the registration of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available elsewhere.

ACCIDENT STATEMENT

Date of Submission	01/04/2021 18:13 (SGT)
Date of Accident	31/03/2021 14:40 (SGT)
Exact Location of Accident	2D Jln Papan, Singapore 619415
Additional Location Information	.
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD3594M
IS COMPANY?	
Is company?	Yes
Name Of Registered Owner	MEGA GAS ENTERPRISE PTE LTD
Company Reg No	2XXXXX814Z
Email Address	sales@megagas.com.sg
Mobile Phone No	(Phone) +65-65674000
Alternative Phone No	(Office) +65-65674000

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Dyna
Variant	.
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	2982

INSURANCE INFORMATION

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	VFX/P2347750
Cover Note Number	.

DRIVER

Name of Driver	ALAGU MANI
Passport No/FIN	GXXXX198R

Date Of Birth	17/03/1992
Occupation	Outdoor
Date Of Driving Pass	13/04/2018
Driving experience	2 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-83939470
Alt. Phone Number	-
Email Address	sales@megagas.com.sg
Address	26 KIAN TECK AVE 1 #01-01
Address complement	-
Postcode	628920
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

NOTICE OF INTENDED PROSECUTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

HOWSTAKES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENTS

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WC6103J
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	DEONG KEN HOI
Passport No/FIN	FXXXX250P
Contact Number	(Phone) +65-81691591
Address	-

ANNEX PLAN

ANNEX PLAN

1. The purpose of this plan is to ensure that the...
2. The scope of the project is defined by the...
3. The project will be managed in accordance with the...
4. The project will be completed by the...
5. The project will be completed by the...
6. The project will be completed by the...
7. The project will be completed by the...
8. The project will be completed by the...
9. The project will be completed by the...
10. The project will be completed by the...



Handwritten signature and date: 11/04/2011

Handwritten signature and date: 11/04/2011

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters
Blk 2 Rivervale Link, #09-02 Singapore 545040
Tel/Fax: 6886 1106 Mobile: 9007 5234
Email: constant_as@yahoo.com.sg
RCB No. 53138015K

INVOICE

To: Mega Gas Enterprise Pte Ltd
c/o 65 Chestnut Avenue
#18-15
Singapore 679524

Date : 22/04/2021

Invoice No : IV21-04022/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of: Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle GBD 3594M (Inclusive Of Photographs And Transport Charges) Our reference : CAS/21-04/022	\$884.00
Total	\$884.00

E. & O.E

Constant Appraiser Services



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters
Blk 2 Rivervale Link, #09-02 Singapore 545040
Tel/Fax: 6886 1106 Mobile: 9007 5234
Email: constant_as@yahoo.com.sg
RCB No. 53138015K

Automobile Inspection Report

To: Mega Gas Enterprise Pte Ltd c/o 65 Chestnut Avenue #18-15 Singapore 679524	Date : 22/04/2021 Reference No : CAS/21-04/022		
<u>General Information</u>			
Registration No. : GBD 3594M Accident Date : 31/03/2021			
<u>Particulars of Damaged Vehicle</u>			
Colour : Multi Engine Capacity : 2982 cc Mileage (KM) : 232628 Chassis No. : JTFAT35Y80K203368 Registration Date : 09/09/2014	Make & Model : Toyota Dyna 150 Manual Pre-Accident Condition : Good Engine No. : 1KD2427179 Steering : In Order Brake : In Order		
<u>Tyre Condition</u>			
R/H Front Tyre	Size 195R15	Make FALKEN	Balance 90%
L/H Front Tyre	195R15	FALKEN	90%
R/H Rear Tyre	155R12 (D)	FALKEN	60% / 60%
L/H Rear Tyre	155R12 (D)	FALKEN	60% / 60%
<u>Inspection</u>			
Repairer : LYS Engineering 65 Chestnut Avenue, #18-15, Singapore 679524			
<u>Adjustment And Recommendation Cost Of Repair</u>			
Repairer's Estimate : \$16,611.58 Revised Amount : \$12,150.00 Less Excess : - Nett Total : \$12,150.00			
<u>Remarks</u>			
(A) Survey was done on 12/04/2021 (B) Re-survey was done on 14/04/2021 (C) Re-survey after repair was done on 16/04/2021 (D) The survey was conducted entirely on WITHOUT PREJUDICE basis. (E) We have NOT given any instruction to authorize the repair of the vehicle.			

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Constant Appraiser Services

Vehicle No : GBD 3594M

Our ref : CAS/21-04/022

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)	
<u>PARTS REPLACEMENT – LIST ITEMS</u>						
1	1pc	Front wiper panel X REPAIR X SVC	Twisted/Warped	481.95	481.95	×
2	2pcs	Front wiper panel side garnish @ \$241.45	Mounting Broken	482.90	482.90	×
3	1pc	Front wide mirror with stay LH X SVC	Dented/Bent	761.90	761.90	×
4	1pc	Front side mirror LH X SVC	Grazed	333.25	333.25	×
5	1pc	Front round mirror LH ✓	Missing	97.20	97.20	✓
6	1pc	Front cab panel ✓	Dented/Buckled	1,378.70	1,378.70	1100
7	1 2pcs	Front cab panel inner support @ \$97.10 ✓	Dented/Twisted	194.20	194.20	97.1
8	1pc	Front cab panel moulding – ctr ✓	Mounting Broken	291.33	291.33	✓
9	2pcs	Front cab panel moulding @ \$199.75 X SVC	Mounting Broken	399.50	399.50	×
10	2pcs	Front corner panel @ \$376.50	Repair	753.00	-	
11	1pc	Front sub chassis frame cross member X REPAIR	Dented/Bent	785.30	785.30	×
12	1pc	Front grille assy ✓	Broken	587.65	587.65	481
13	1pc	Front grille emblem ‘logo’ ✓	Necessary	86.90	86.90	75
14	2pcs	Front headlamp @ \$892.10 X SVC	Broken	1,784.20	1,784.20	×
15	1pc	Front bumper ✓	Dented/Twisted	561.90	561.90	485
16	1pc	Radiator assy ✓	Twisted/Leakage	2,660.50	2,660.50	1637
17	1pc	Radiator top hose X SVC	Bent/Twisted	51.60	51.60	×
18	1pc	Radiator bottom hose X SVC	Necessary	69.80	69.80	×
19	1pc	Air intercooler X SVC	Twisted	1,890.50	1,890.50	×
20	1pc	Air con blower assy ✓	Broken	1,431.90	1,431.90	1218
21	1pc	Air con cooling coil assy ✓	Broken	1,891.25	1,891.25	885.6
			6367.23	16,975.43	16,222.43	
Less 25%			4775.42	(4,243.85)	(4,055.60)	
Sub total				12,731.58	12,166.83	
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>						
1	1bot	Air con oil ✓	Necessary	65.00	40.00	✓
2	1pc	Company name ✓	Necessary	300.00	250.00	200
3	1pc	Front number plate ✓	Warped	40.00	40.00	15
4	1pc	Front ‘Flammable’ sticker ✓	Necessary	35.00	35.00	10
Sub total				13,171.58	12,531.83	
					265	

Constant Appraiser Services

Vehicle No : GBD 3594M

Our ref : CAS/21-04/022

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>LABOUR & MISC. CHARGES</u>			
1		To check front electrical wiring & refocus headlamp		40.00	20.00 ✓
2		To respray undercoating		100.00	60.00 ✓
3		To remove, refix front dashboard		250.00	220.00 ✓
4		To remove, refix A/C cooling system & refill gas		150.00	120.00 ✓
5		To respray painting & etc		1,400.00	1,000.00 500
6		Panel beating, cut, weld, remove & replacing above parts	1520	1,500.00	1,200.00 600
Grand total				16,611.58	15,151.83
Recommended cost of lump sum repair (To its pre-accident condition)					12,150.00

6560.42

-20%: 5250

Adjustment/Recommendations

5 Days

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$12,150.00** on a contractual basis. Under normal circumstances, the repair period would be about **5 (Five)** working days.

Yours faithfully,

Constant Appraiser Services



Lim Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA

AIA Insurance Pte Ltd
 6 Collyer Quay, #24-01
 Raffles Tower, Singapore 069333
 Attention: Lorraine #24-01
 Tel: (65) 63494899 Fax:
 Website: www.aia.com.sg
 AIA Regulator Number: 1000000200
 AIA Member Category: 000000



Fleet
 POLICY SCHEDULE
 RENEWAL
 Original

Policy No. : VFX/P2347750

Policy No. : 1KD2307136
 Policy No. : JTFAT35Y30K202418
 Market Value At The Time Of Loss
 As specified in Certificate of Insurance

Extra Coverage (Premium Breakdown)	Limit (SGD)	Premium (SGD)
BASIC PREMIUM		3,226.52
LESS 20.00% Fit Disc		645.70
NET PREMIUM		2,582.82
TOTAL PREMIUM		2,582.82

Excess Applicable
 Sect I - Any Authorised Driver SGD 700.00
 Windscreen Excess SGD 140.00

Named Drivers

1 ANY AUTHORISED DRIVER

4
 Comprehensive
 GBD3594M
 Commercial Vehicle
 TOYOTA TOYOTA DYNA 150 MANUAL
 2014
 1.50
 LORRY
 1KD2427179
 JTFAT35Y80K203368
 Market Value At The Time Of Loss
 As specified in Certificate of Insurance

Extra Coverage (Premium Breakdown)	Limit (SGD)	Premium (SGD)
BASIC PREMIUM		3,131.80
LESS 20.00% Fit Disc		626.36
NET PREMIUM		2,505.44
TOTAL PREMIUM		2,505.44

Excess Applicable
 Sect I - Any Authorised Driver SGD 700.00

Enquire Transfer Fee

Vehicle Details

Vehicle No.	GBD15444
Vehicle Class	B31 - Goods (Open) Lorry / Metal Body w/Pickup
Vehicle Attachment	No Attachment
Vehicle Status	Normal
Vehicle Make	TOYOTA
Vehicle Make Model	TOYOTA DYNA 150 MANUAL
Engine No.	278A135Y6CK293368
Registration	Qnew
Vehicle Type	14(1)42(1)
Vehicle Weight	2400 kg
Maximum Gross Weight	4000 kg
Maximum Axle Weight	1600 kg
Vehicle Manufacturer	QNT4
Registration Expiry Date	09 Sep 2014
Vehicle Birth Day	08 Sep 2014
Vehicle Type	1 - Goods vehicle A Bus
Vehicle Value	\$54,000.00
Registration Date	08 Sep 2014
Vehicle Expiry Date	08 Sep 2016
Vehicle Tax Date	08 Sep 2016
Vehicle Transfer Date	01 Aug 2016
Vehicle Fee	157.00 (excl)

Amount Payable (From 09 Sep 2016 to 08 Sep 2017)

As of 09 Sep 2016, you may renew the road tax from 09 Sep 2016 until 08 Sep 2017. Late renewal fees will be imposed after 08 Sep 2016. Late renewal fees will be imposed. Please use [Enquire Road Tax Payment](#) to check the amount payable.

Amount payable for late renewal fees will follow the vehicle to the new registered owner when its name is transferred.

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Registration Fee	11.00	0.00	11.00
Sub Total:			11.00
Govt Road Tax Amount			
After Offsetting Over Payment:	213.00		213.00
Total Amount Payable			224.00

Amount Payable (From 09 Sep 2016 to 08 Sep 2017)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee	11.00	0.00	11.00