



Your Ref: 19/19/19/VP02/298837

Date: 07th June 2021

Our Ref: CS1/LPM21006072/Evf3e2

M/s Lonpac Insurance Bhd

21st Flr, Bangunan Public Bank
No. 6 Jalan Sultan Sulaiman
50000 Kuala Lumpur, Malaysia

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJS 1779L
INSURED VEHICLE: JGF 7087
ACCIDENT DATE: 25/11/2019**

We thank you for your instruction on 24/05/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJS 1779L from M/s Automobile Inspection Services Pte Ltd.
- b) Singapore Accident Statement of Vehicles SJS 1779L.
- c) Colour damaged vehicle photographs of SJS 1779L.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJS 1779L
Make & Model	: Kia Sorento 2.2(8AT) CRDI 2WD S/R
Year of Registration	: 2018
Chassis Number	: KNAPH81BMJ5447381
Engine Capacity	: 2199 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.