
ASS. FO. BY TOMPHUM SET. CS/AG/21006074/TIEF3. SMK SOSZEYFRAGEN 2015, March Veh No: Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Date: From. Estimated Cost: Black · AIC: INSUFED Std/NI/NA OD THIWS ITP RESIDD RESIEVALINVINV Make: To Inspect Vehicle No: Colour 98054. T/Radio: Insured | Std | NI | NA at Workshop m/s Sn.Reading WBH4195708091969342. Eng/No: insured CINO: Gen. Cond: Good / Fair / Poor / Burnt Policy No. Steering: Inotder) Jammed / Leaked / Burnt or Claims No. Sum Insured: Excess: Brake: Ingrder / Jammed / Leaked / Burnt or Modi: Nil / 87Rjm / STD A/Rim or (Client's Record) 265/3019. Make of Veh: Tyre Size: BS | DUN | EXNOVA | GY | FS | LIZA | MIC | OHTSU | PIR | SUMI | (Paticy Condition) Remark: The veh had commenced its Fa/leer repair at the time of inspection. Rear Front Bal. or Warket Value: R/Bal. Consistent? : Yes or No L/Bal. IDAC Accident Rport: L/Bal. D.O.L. 74/5/2/03pm Consistent?: Yes or No GIA / PR Seen: D.O.A. Res.: Yes or No days Rico 60 Est. Repairs: Survey held at 3 Val.: Yes or No Des. of Damages : Frt / Rept 1 O/S / N/S / U/C Rooftop or Lum Sum. _ CA | REV | REP. | 24 HRS Vehicle: IN/OUT The U/C / Chassis frame / Body Structure amediad due to collision Person Contacted: Date / Time | Action / Instruction accept your finalize offer closed at 11,700.00 and 6day. red: 18718.06 :61% Days Of Repair: · Preli, Report Date/Time, File Pass (d? Survey 190. Resurvey No. of Trip: : Final Report Date/Time, File Return to? S+R __SI : Site Insp (\$ -Add Fee: Pholos : Interview 15 Tean true it Found Friday MARI TO SE LUCKE SHOT I LESS I'M



Rico 60 Auto Services Pte Ltd Blk 8 , Kaki Bukit Avenue 4 , #02-24 Premier @ Kaki Bukit Singapore 415875

Email: claims@rico60.com Tel: 6286 6060 Fax : 6286 7060

TO: ETIQA
Vehicle No : SMK 5052 E
Make & Model : BMW 428I

DATE: 18/5/2021

	RICO	Office	<u>Use</u>	Only
--	------	--------	------------	------

Parts -5%	
SN	
Labour	
Total	
Lump Sum	
ERV	40K

	DATE: 18/5/2021	OTV		LINE	IT PRICE	PRICE	
No.	DESCRIPTION - PARTS		QTY				
1	TAILGATE		1	\$	1,267.50	\$ 67.50	
2	TAILGATE LOGO		1	\$	125.00	\$ 125.00	
3	THE PROPERTY MOUNTAIN	G	1	\$	198.00	\$ 198.00	
4	TALL GATE VAUNDCODEEN INNER SE	AL	1	\$	50.00	\$ 100.00	
5	TAILGATE EMBLEM(428I)		1	\$	89.00	\$ 12000	
6	TAILGATE NUMBER PLATE LAMP		2	\$	89.00	\$ × 178.00	
	TAILGATE OPENER SWICTH		1	\$	217.90	\$ × 217.90	
	TAILGATE LAMP		2	\$	565.00	\$ 1,130.00	
	TAILGATE STOPPER		2	\$	25.00	\$ × 50.00	
	TAILGATE INNER TRIM	~	1	\$	525.00	\$ \$7 525.00	
	TAILGATE BOTTOM LOCK		1	\$	665.00	\$ \$ 665.00	
	TAILGATE TOP LOCK CATCH		1	\$	46.00	\$ \$ 46.00	
	TAILGATE WEATHERSTRIP		1	\$	298.40	\$ 298.40	
	TAILGATE LOCK DETECTOR		1	\$	317.90	\$ 4 317.90	
15	TAIL GATE FLOOR SCAN SENSOR	SUPPORT	1	\$	189.00	\$ 04 189.00	
16	TAIL GATE FLOOR SCAN SENSOR	1	1	\$	265.00	\$ n \(\sigma \) 265.00	
1	7 TAIL GATE FLOOR SCAN SENSOR	2	1	\$	265.00	\$ ~~ 265.00	
12	8 TAIL GATE FLOOR SCAN SENSOR	UNIT	1	\$	387.00	\$ 25 387.00	
	9 TAIL LAMP		2	\$	526.10	\$04/1,052.20	
2	A CONTRACTOR OF THE CONTRACTOR		2	\$	189.00	\$ 2 378.00	
2			1	\$	1,256.00		
	2 REAR BUMPER		1	\$	1,220.30	\$4/1,220.30	
	3 RAER BUMPER CHROME MOULDI	NG	1	\$	332.00		
	4 REAR BUMPER TOP GARNISH		1	\$	253.00	\$ de 253.00	
	5 REAR BUMPER SIDE RETAINER		2	\$	254.00	\$ 04 508.00	
	6 REAR BUMPER SIDE GARNISH	RHX LH-t	n 2	\$	255.50	\$ 511.00	
	O REAL DOM LIVOIDE STATIST						

8 7				. 1 /
27 REAR BUMPER REINFORCEMENT	1	\$	0.0.0	\$ 66 - 570.90
27 REAR BUMPER REINFORCEMENT 28 REAR BUMPER CENTER RETAINER	1	\$	011.00	\$au 377.50
29 REAR BUMPER REFLECTOR	2	\$	177.90	\$ 355.80
30 REAR BUMPER TOW COVER	1	\$	56.00	\$ 7 56.00
31 REAR BUMPER UNDER SIDE COVER	1	\$	211.50	\$ de 211.50
	24	\$	378.90	\$1,515.60
32 REVERSE SENSOR	4	\$	35.00	\$ red 140.00
33 REVERSE SENSOR HOLDER	1	\$	899.00	\$ × 899.00
34 REVERSE SENSOR WIRIHARNESS	1	\$	758.00	\$ 1 758.00
35 END PANEL	1	\$	288.70	\$ 288.70
36 END PANEL TOP TRIM	1	\$	973.40	\$ × 973.40
37 REAR FLOOR PANEL	1	\$	652.00	\$ 652.00
38 REAR FLOOR PANEL TOP BOARD	1	\$	317.40	\$ × 317.40
39 REAR FLOOR PANEL TOOL BOARD	2	\$	470.00	\$ > 940.00
40 REAR FENDER INNER TRIM	2	\$	198.70	\$ × 397.40
41 REAR FENDER INNER SHIELD	1	\$	1,230.40	\$ 7 1,230.40
42 REAR EXHAUST SILENSLIN	2	\$	50.00	\$ X 100.00
43 REAR EXHAUST MOUNTING	1	\$	45.00	\$ × 45.00
44 REAR EXHAUST GASKET	1	\$	217.00	\$ 56 217.00
45 REAR EXHAUST HEAT PLATE CENTER	1	\$	156.00	\$ 66- 156.00
46 REAR EXHAUST HEAT PLATE SIDE	1	\$	689.00	\$ 689.00
47 FRONT DRIVER SEAT BELT	1	\$	854.00	\$ 7 854.00
48 FRONT DRIVER SEAT BELT BARKER	1	\$	1,542.00	\$ 1,542.00
49 SRS COUNTOR UNIT	1	\$	685.00	\$ × 685.00
50 FRONT DOOR PILLER INNER TRIM RH	1	\$	189.00	\$ * 189.00
51 FRONT DOOR STEP GARNISH	1	Ψ	100.00	7
			Subtotal	: \$ 25,934.80
			Less 5%	6 \$ 1,296.74
			Parts Total	: \$ 24,638.06
SPECIAL NETT	QT	Y U	NIT PRICE	PRICE
NO.	1	\$	80.08	\$ \$ 0 pm 80.00
1 REAR WINDSCREEN SEALANT	1		80.00	\$ 400 80.00
2 REAR WINDSCREEN INNER SEAL	1	0.00	40.00	\$ 20me/ 40.00
3 TAILGATE INNER TRIM CLIP	1		50.00	50.00
4 TAIL LAMP SIDE GARNISH CLIPS	1		50.00	
5 REAR BUMPER CLIP			40.00	
6 REAR BUMPER UNDER COVER CLIP			80.08	
7 END PANEL SEALANT		\$		(22.22
8 END PANEL TOP TRIM CLIP		1 \$		
9 REAR FLOOR PANEL SEALANT		1 \$		
10 REAR FENDER INNER TRIM CLIP	1	. Ψ	20.0	

11 REAR FENDER INNER SHIELD CLIP		1	\$	40.00	\$	X 40.00
11 REAR FENDER INNER SHILLD CENT 13 FRONT DOOR PILLER INNER TRIM C	LIPS	1	\$	60.00	\$	60.00
13 FRONT DOOR FIELER INVESTMENT					\$	680.00
LABOUR (RE	AR)					PRICE
				700	\$	1,600.00
PANEL BEATING, REMOVAL AND REPLA	ACING PARTS			800	\$	1,600.00
TO SPRAY PAINT AFFECTED AREA				0	\$ 3	0 150.00
TO PERFORM LIGHTING & WIRING CHE	CK					2 150.00
TO APPLY ANTI-RUST & TUFF KOTE						b 150.00
REMOVE AND INSTALL REAR WINDSCH	REEN					6 ° 150.00
REMOVE AND INSTALL TAIL GATE MED	HANISIM ANI	D PA	\RT		Ψ	3~ 200.00
REMOVE INSTALL AND CHECK REVER	SE CAMARA				\$	3° 200.00
REMOVE INSTALL AND CHECK REVER	SE SENSOR					200.00
REMOVE AND INSTALL CARPET, TRIM	AND INTERRI	OR			-	2
REMOVE AND INSTALL REAR EXHAUS	Т					60 150.00
					\$	<i></i> 8○ 350.00
RESET SRS SYSTEM			LABO	JR TOTAL	. \$	5,100.00
		Tot	tal Parts	s Cost	\$	25,318.06
		91 653		our Cost	\$	5,100.00
		То	tal Repa	air Cost	\$	30,418.06

APPROVED DETAILS

NO. OF WORKING DAYS

PART BY PART OR LUMP SUM

DATE & TIME OF SURVEY

SURVEYED BY

CONTACT NUMBER

FAX NUMBER

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subjest to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tauften 97415749
WP 24/8/71 R 3 pm
1/4 Resury Afor reprin
tauften @/hhanto.wh.
6 Gilys

> Back to OneMotoring

Pehicle Owner Particulars	NDIC
Owner ID Type:	Singapore NRIC
Owner ID: /ehicle Details	408D
/ehicle No.:	SMK5052E
/ehicle to be Exported:	No
ntended Deregistration Date:	18 May 2021
/ehicle Make:	B.M.W.
Vehicle Model:	428I GRAN COUPE A/T SR HID NAV HUD
Primary Colour:	Brown
Manufacturing Year:	2014
Engine No.:	B4690967N20B20A
Chassis No.:	WBA4A52080GA69342
Maximum Power Output:	180.0 kW (241 bhp)
Open Market Value:	\$47,400.00
Original Registration Date:	13 Mar 2015
First Registration Date:	13 Mar 2015
Transfer Count:	2
Actual ARF Paid: Intended PARF Rebate Details	\$53,360.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Mar 2025
PARF Rebate Amount: Intended COE Rebate Details	\$34,684.00
COE Expiry Date:	12 Mar 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$68,668.00
COE Rebate Amount:	\$26,176.00
Total Rebate Amount:	\$60,860.00

ОК

red: 18718.06;6;61%1

Date of Accident	17/5/202 Accident Time: 1540 (24-HR-Format)
Accident Place	Serangoon Northtre 6
Vehicle. No. (Car Plate No.)	SMK 505ZE Make/Model: BMW 428 9C
Insurace Company	Policy No: PNPV2019-00009604-01
Owner or Company Name /IC No.	poh Bi Than (S8634408D)
Owner or Company Contact No.	Company Tel
DRIVER'S Name / IC No.	Tong Wellfong (SROY0070E)
DRIVER'S Date Of Birth	DRIVER'S License Pass Date 08 / 05/2007
Relationship of Owner & Driver	Spouse \ Parents \ Children \ Sibling \ Employee\ Others:
DRIVER'S Address	BIK 314B Punggol Way #12-623 S(822314)
DRIVER'S Contact No./ Alt No.	1) 9431 3856 2)
DRIVER'S Occupation	NDOOR \ OUTDOOR (e.g. working inside or outside office)
Email Address	thomasyork 25 @ yahoo. com. sg
Weather & Road Surface	: CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
Reporting Type	Reporting Only \ Claim Other Party \ Claim Own Insurance
Any Injury (If YES, Pis state): 46	car camera: YES \ NO vas being used at the time of accident: Private use \ Work purpose
	77.12.1 No.
Vehicle. No: SML 4912 A	V. Link Maka/Madak
Vehicle Make\Model:	Name Driver
Name Driver:	IC No. Driver/Contact:
IC No. Driver/Contact:	IC No. Dilver/Contact.
* NEW - Passenger's name	e & gender:

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer , my w orkshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) w ho have insured vehicle(s) involved in this accident (all insurer(s) w ho have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes") (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

	iver's Signature (If driver is not the policyholder) / Da Time	Witnessed by Reporting Centre Personnel
Vehicleréa: 187418066 Vehicle B: 5mL 491	Ç6€1 .2 A (B)	
	9 7	

escribe Circumstances of the	e Accident				Clared & Marian.
escribe Circumstances of the On-the stated date an Suddenly, I felt a b dann to check and	dame, I'v	enicle A	NOU Stateonary	onthe	storbed revive.
Enddemy I felt av	um imph	of onth	e rear of me	verna	e. (then carrie
down to check and	MINTEROL	that H	now voluce !	3 WMb	have combun
outomy remove.	100 1,00				
and will rendoce					
				7,40	
red: 18718	06:6:1				
	.00,0,1				
Declaration					
	true in ave	ory respect			
We declare the foregoing particula	is are true in eve	sty respect			
		1			
Pan BI JUAN	4	D			
(84,			the self-ubalder\ /	Date M	tnessed by Reporting Centre
Policyholder's Signature / Date & Time	Driver's Signa & Time	ature (II driver	s not the policyholder) /		ersonnel