

ASS. REC. BY:

Steve

AIG

CS/AIG21006081/Etf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

2100494742

Claims No.

6206493801SG

Sum Insured:

Excess:


600

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Cum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLJ 6923C

Yr Regn:

21/12/16

Type: V/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA Sorento

c.c.

2199

Colour:

Brown

A/C:

Insured / Std / NI / N

Sp. Reading

66928

T/Radio:

Insured / Std / NI / N

Eng/No:

C/No:

KNAPH 81BMG5254852

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Locked / Burnt or

Brake: In order / Jammed / Locked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/55R19

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

19/5/21

D.O.A.

24/5/21

Survey held at

Cycle & Carriage

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

F.A.L.M.

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MK-75K

Confirm \$11,074.80; 10days

red: 4323.60; 28%

Date/Time, File, Poss to?



: Prel. Report



: Final Report

Date/Time, File Return to?

Days Of Repair:

10

Resurvey No. of Trip:

Add Fee:



: Site Insp

(\$



: Interview

(\$



: Tech. Invs

(\$



: Weekend

(\$

Survey Fee:

Transportation:

\$ + RS \$

Photo

Others

TOTAL

Date/Time, File Return to?

Date/Time, File Return to?



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /CASLIN LEE HUI LING (LI HUILING) Reg No/Reg Date SLJ6923C / 21/12/201 Date In/Mileage / 0 Chassis No KNAPH81BMG5254852 Engine No D4HBGH287577 Make/Model KIA/SORENTO UM 2.2 A DIESEL 2WD ABV Colour/Trim MY3 IMPERIAL BRONZE/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	22/05/2021/ 12:00		282 / Kevin Leong	33700
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	REPLACE FRT ^{9.5} BUMPER, BONNET, SUPPORT & AFFECTED AREA	4 x 400			1600 2000.00
	REPAIR ON FRT LH ¹ FENDER				
E PNT98000	PAINT WORK ON FRT ¹ BUMPER, BONNET & FRT LH ¹ FENDER	2 x 350			700 1050.00
E PNT88000	REMOVE & INSTALL FRT PARKING ASSIST FOR FACILITATE REPAIR				80 150.00
M SUNDRY	PERFORM RUST PREVENTION				? 80.00
E PNT88000	REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR (photo)				120.00
M SUNDRY	TO TOP UP AIRCON GAS				? 80.00
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				120.00
	USING HI-SCAN PRO TEST				
M SUNDRY	TO APPLY ZERTONA COATING ON AFFECTED AREA (CFM Bump, LH Fend) provide set, agent				? 240.00
M SUNDRY	SUNDRIES				20 50.00
M LAMP ASSY-HEAD, LH	BR	1.00	2210.00	20.00	1768.00
M PANEL ASSY-HOOD	X	1.00	1654.00	20.00	1323.20
M PANEL-FENDER, LH	DO	1.00	502.00	20.00	401.60
M CARRIER ASSY-FRONT END MODULE	BR	1.00	760.00	20.00	608.00
M BEAM COMPLETE-FR BUMPER	?	1.00	551.00	20.00	440.80
M GUARD ASSY-FRONT WHEEL, LH	TN	1.00	73.00	20.00	58.40
M COVER-FR BUMPER UPR	BR	1.00	645.00	20.00	516.00
M GRILLE ASSY-RADIATOR	?	1.00	738.00	20.00	590.40
M COVER-FR BUMPER, LWR	CUT	1.00	645.00	20.00	516.00
M GRILLE-FRONT BUMPER FOG LAMP, L	BR	1.00	93.00	20.00	74.40
M LAMP ASSY-FRONT FOG, LH	BR	1.00	297.00	20.00	237.60

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /CASLIN LEE HUI LING (LI HUILING) Reg No/Reg Date SLJ6923C / 21/12/201 Date In/Mileage / 0 Chassis No KNAPH81BMG5254852 Engine No D4HBGH287577 Make/Model KIA/SORENTO UM 2.2 A DIESEL 2WD ABV Colour/Trim MY3 IMPERIAL BRONZE/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	22/05/2021/ 12:00		282 / Kevin Leong	33700

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M ABSORBER-FRONT BUMPER ENERGY	1.00	134.00	20.00	107.20
M SKID PLATE-FR BUMPER ✓ CUT (slm)	1.00	220.00	20.00	176.00
M BRACKET-FR BPR SIDE REINF, LH ✓ mif	1.00	22.00	20.00	17.60
M STIFFENER ASSY-FR BUMPER LWR X	1.00	117.00	20.00	93.60
M BRACKET-FR BUMPER SIDE, LH ✓ mif	1.00	17.00	20.00	13.60
M LIP-FRONT BUMPER	1.00	65.00	20.00	52.00
M ULTRASONIC SENSOR-S.P.A.S ✓ OR	1.00	187.00	20.00	149.60
M ULTRASONIC SENSOR-S.P.A.S ?	1.00	187.00	20.00	149.60
M ULTRASONIC SENSOR-S.P.A.S SIDE ?	1.00	346.00	20.00	276.80

Estimate

Steve (LKK) 00-MAL
24/5/21, 1.00pm EXERS -?
PIP
My BL sy
7 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Not to be signed by Repairer

Confirm & accepted by

Nett 11,490.40
7% GST on 11490.40 804.33
Total Payable 12,294.73

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	20/05/2021 11:32 (SGT)
Date of Accident	19/05/2021 17:05 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	Hougang Ave 8 filter lane to Hougang Ave 10
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLJ6923C

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Caslin Lee Hui Ling (Li HuiLing)
NRIC No	S7642315F
Email Address	caslin_lee@yahoo.com.sg
Mobile Phone No	(Phone) +65-91272201
Alternative Phone No	+65-98363772

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Sorento
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	2199

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2100494742-04
Cover Note Number	-

DRIVER

Name of Driver	EUGENE LEE WHUI-BOON
NRIC No	S7615072I

Date Of Birth 29/05/1976
 Occupation Indoor
 Date Of Driving Pass 10/12/1997
 Driving experience 23 YEARS AND 5 MONTHS
 Gender Male
 Mobile Number (Phone) +65-91272201
 Alt. Phone Number -
 Email Address NOEMAIL@AIG.COM
 Address 30 Upper Serangoon View
 Address complement #17-39 SINGAPORE
 Postcode -
 Is the driver the policyholder? No
 If No, Relationship of the Driver with the Insured Spouse
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver -
 Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 2
 Was anybody injured in the Accident? No
 Was any injured conveyed to hospital by ambulance? -
 Was any other material or property damaged? Yes
 Number of Passengers (Including Driver) 1
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

R2000007496 Circumstances Of Accident Happened at the filter lane from Hougang Ave 8 to Hougang Ave 10. I was checking my right to see if there are any on coming vehicle (along Ave 10) so I can filter out from Ave 8 to Ave 10. There was no on coming vehicle

as such I moved off and hit into SJV2074P

which apparently was still there.


ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1:

Vehicle Registration Number SJV2074P-96160133-Private Car
 Vehicle Manufacturer -
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -

Vehicle Category	Private car
Name of Driver	-
Contact Number	(Phone) +65-96160133
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-





CERTIFICATE OF INSURANCE

KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Caslin Lee Hui Ling (Li HuiLing)
Period of Insurance : 21 Dec 2020 To 20 Dec 2021
Engine No. : D4HBGH287577
Chassis No. : KNAPH81BMG5254852

Vehicle No. : SLJ6923C
Policy No. : 2100494742-04
Endorsement No. :
Issued Date : 22 Nov 2020

ABOUT THE COVER

Make/Model : KIA SORENTO 2.2 A DIESEL

Engine Capacity/Tonnage : 2,199.00 CC

Sum Insured : Market Value

First Year of Registration : 2016

Driver Restriction : NA

Off Peak Car : No

Insuring with COE/PAFF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with her/his permission

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" (YIDR) if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Mileage Condition : Unlimited Mileage

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 129), Section 95 of the Road Transport Act, 1987 (Malaysia) and 7 (Amendment) Act 2019 are not to be included under these headings.

EXCESS

Section 1

Fire - \$0, Own Damage - \$600, Theft - \$0, Flood Cover - \$600

Section 2

Property Damage - \$0

Windscreen - \$100

Named Driver and Excess (where applicable)

Caslin Lee Hui Ling (Li HuiLing) - \$600 (Own Damage), \$600 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Cycle & Carriage Body & Paint Centre Add: 209 Poyan Gardens Singapore 600339 65684501

2 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ulu Rd 3 Singapore 408690 67481000

3 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 341 Alexandra Road Singapore 159931 64278800

4 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 800 Sin Ming Ave Singapore 575733 69326000

For other Approved Reporting Centres/Authorised Repairers, please contact our 24-hour accident emergency hotline at 165 8338 8200. Alternatively, you may refer to AIG website and AIG Mobile App. Simply search and download "AIG App" from iTunes or Google Play.