


ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SKW 7691H
at Workshop m/s CYCLE & CARRIAGE
of _____
Insured: _____
Policy No. 2100437532-05
Claims No. 6226294636SG
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.



Est. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
SIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 4 days Res.: Yes or No
Cum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKW 7691H Yr Regn: 16/11/15
Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: KIA Forte c.c. 1591
Colour: Red A/C: Insured / Std / Nil / N
Sp. Reading: 32485 T/Radio: Insured / Std / Nil / N
Eng/No: _____
C/No: KNAIF Z411MF S472112
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brakes: In order / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD AIR / or
Tyre Size: F: 225/45R17
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Fire 29
Front: _____ Rear: _____
R/Bal. 4 mm R/Bal. 4 mm
L/Bal. 4 mm L/Bal. 4 mm
D.O.A. 23/5/21 D.O.I. 24/5/21
Survey held at Cycle & Carriage
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
Rear R14
The UIC / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>MV-45K</u>
<u>25/5/2021 @ 10.13am</u>	<u>Revert to AIG via Merimen</u>
<u>25/5/2021 @ 10.59am</u>	<u>Kok Chong informed C/A via Merimen</u>
<u>25/5/2021 @ 12.23pm</u>	<u>Informed Edwin C/A & ex: \$600/ by email.</u>
<u>22/7/2021 @ 4.38pm</u>	<u>Confirmed final fig \$3425.60. 4 repair days.</u>
	<u>(RED \$2325.20: 40%)</u>

File/Time, File, Poss to? ☐ : Prell. Report
23/7 TYPIST ☐ : Final Report
File/Time, File Return to?

Days Of Repair: 4
Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Inve (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:
Transportation: _____
S + RS: _____
Phone: _____
Others: _____
TOTAL: _____

Approved: MER-OD
Amount: \$3425.60



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Hoon Aik Seong Reg No/Reg Date SKW7691H / 16/11/201 Date In/Mileage / 0 Chassis No KNAFZ411MF5472112 Engine No G4FGFH784982 Make/Model KIA/FORTE K3 1.6 A SX AAC PREMIUM Colour/Trim K3R / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	24/05/2021/ 13:01	BLE	261 / Edwin Caina	33752			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								880 1600.00
RENEW RHR ⁸⁰ DOOR PNL & RH ROCKER PNL BODY KIT					2 dgs + 80			
REPAIR RHR ⁸⁰ FENDER & RH ROCKER PNL								
E PNT98000								1950 1400.00
RESPRAY RHR ¹ DOOR , RHR ¹ FENDER , RH ROCKER PNL &					3 x 350			
RH ROCKER PNL, BODY KIT								120.00
E PNT88000								120.00
REMOVE & REFIT RHR DOOR COMPONENT								120.00
E PNT88000								30.00
REMOVE & REFIT TRIM & REAR SEAT TO FACILITATE REPAIR								120.00
A 54900099								40.00
CHECK WIRING ELECTRICAL SYSTEM								40.00
A 10028901								20.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								40.00
USING HI-SCAN PRO TEST								40.00
M SUNDRY								40.00
APPLY ANTI CORROSION ON AFFECTED AREAS								20.00
M SUNDRY								
SUPPLY BODY PNL SEALANT								
M SUNDRY								
Sundries					1.00	1361.00	20.00	1088.80
M PANEL ASSY-REAR DOOR, RH					1.00	89.00	20.00	71.20
M W/STRIP ASSY-RR DR BELT O/S RH					1.00	8.00	20.00	6.40
M TAPE-RR DR FRAME BLACK RR, RH					1.00	11.00	20.00	8.80
M BLACK TAPE-RR DR FRAME UPR, RH					1.00	27.00	20.00	21.60
M FILM-ANTI CHIPPG RH					1.00	58.00	20.00	46.40
M HANDLE ASSY-DOOR OUTSIDE					1.00	22.00	20.00	17.60
M COVER-FR DR O/S HDL, PASSENGER					1.00	1000.00	00.00	1000.00
M K3 TEMPTATION RED K3R								

Estimate

80

1

80

3

350

1

1361.00

89.00

8.00

11.00

27.00

58.00

22.00

1000.00

24/5/21, 4-00pm

DD-111 11

SURVEYOR NAME :

Steve CLKK)

SURVEYOR NAME: Steve CLKK 24/5/21, 4:00pm

SURVEYOR SIGNATURE: DD-AL AL

Confirm & accepted by

DATE: EXPRS - ?

Auto Consultants hence notify
Repaier of the following:

REMARKS: PIP, R, Bel g

resurvey before/after spray painting
display damaged part(s) during resurvey

4 dgs

prices are subject to confirmation
third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

Nett 5,750.80
7% GST on 5750.80 402.56
Total Payable 6,153.36

This estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include
any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered
after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a
deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or
cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing
the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	24/05/2021 13:38 (SGT)
Date of Accident	23/05/2021 09:02 (SGT)
Exact Location of Accident	130 Bukit Batok West Ave 6, Block 130, Singapore 650130
Additional Location Information	CARPARK LOT NO 127 BETWEEN BLK 130 & BLK 131
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW7691H
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	HOON AIK SEONG
NRIC No	SXXXX162H
Email Address	davyhoon@yahoo.com.sg
Mobile Phone No	(Phone) +65-97989991
Alternative Phone No	+65-97989991

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Forte
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1591

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2100437532-05
Cover Note Number	-

DRIVER

Name of Driver	HOON AIK SEONG
NRIC No	SXXXX162H

Date Of Birth
Occupation
Date Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

03/03/1957
Indoor
16/08/1978
42 YEARS AND 9 MONTHS
Male
(Phone) +65-97989991
+65-97989991
davyhoon@yahoo.com.sg
BLK 209 BUKIT BATOK STREET 21 #06-170

-
650209
Yes
-
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Side Swipe
Clear
Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged?
Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No
2
No
-
Yes
2
No

PASSENGER 1

Name
Gender

MS NGE0 CHAI HIANG
Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Was notice of intended Prosecution given?
If yes, against whom?

No
No
-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT COLLISION-REVERSING INTO CARPRAK LOT

ATTACHMENT(S)

Are accident photos available for attachment?
Was there any video captured by Car Camera?
Was there any audio recorded?

Yes
No
No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number
Vehicle Manufacturer
Vehicle Model
Vehicle Variant
Vehicle Colour

SLQ3225S
Toyota
Wish
-
Blue

Vehicle Category
Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

Private car
MR WONG KAM HOONG
(Phone) +65-96604229

-
-
-
-
-
-
-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time
1186 hr

Driver's Signature (If driver is not the policyholder) / Date & Time
1186 hr

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

I was driving my car to park at lot 127 next to LK 130 of Bt. Batek Next Ave 6.

As I was already in lot 128, my parking hazard light was on blinking to show my intention of parking so I moved my car forward to reverse into lot 127.

While driving my car to reverse into lot 127. I noticed a car zooming pass and suddenly stopped and this car SLQ 32255 suddenly zooming in reverse gear.

I immediately stopped my car while SLQ 32255 was about 1 1/2 car length away.

But SLQ 32255 did not stopped and continue to drive and hit my car on my right hand side of my passenger door.

My car R/H/S passenger door sustained deep dented mark.

The driver of SLQ 32255 quickly stopped upon accident and moved his car and parked next to my car.

Driver Mr. Wong remark was he thought I was moving out. His female companion left and he said he was here to open his shop.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

11/29/11

Driver's Signature (If driver is not the policyholder) / Date & Time

11/29/11

Witnessed by Reporting Centre Personnel

NAME OF POLICYHOLDER : Hoon Aik Seong
PERIOD OF INSURANCE : 16 Nov 2020 To 15 Nov 2021
ENGINE NO. : G4FGFH784982
CHASSIS NO. : KNAFZ411MF5472112

VEHICLE NO. : SKW7691H
POLICY NO. : 2100437532-05
ENDORSEMENT NO. :
ISSUED DATE : 02 Nov 2020

ABOUT THE COVER

Make/Model : KIA FORTE K3 1.6 A SX

Engine Capacity/Tonnage : 1,591.00 CC

Sum Insured : Market Value

First Year of Registration : 2015

Driver Restriction : NA

Off Peak Car : No

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Mileage Condition : Unlimited Mileage

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Hoon Aik Seong - \$600 (Own Damage), \$600 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800

4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504510213

CYCLE & CARRIAGE - KELTAN

239 ALEXANDRA ROAD

SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature.

SSPLL

10038/6052/JAC