## **COMFORT TRANSPORTATION PTE LTD**

## **REPAIR ESTIMATE**

Vehicle No. : SHC1629U DOA:22.05.2021

Make : Toyota Insurance: AIG

Model : Prius (G4A) MVA: MS. LOKE YY

Date: 24.05.2021

Qty	Parts Description / Labour	Туре	Unit Price	Amount	
1 P	ANEL SUB ASSY FRT DOOR RH			\$1,264.00	10
1 F	RT DOOR OUTER HANDLE RH			\$378.90	V2 X
1 P	ANEL SUB ASSY RR DOOR RH			\$1,258.30	- D
1 R	R DOOR HINGE UPPER			\$82.30	x Inc
1 R	R DOOR HINGE LOWER			\$82.30	X700
1 R	R DOOR CHECK			\$155.70	
1R	R DOOR RUBEBR SEAL OUTER RH			\$176.60	?
1 M	IIRROR ASSY OUTER VIEW MIRROR RH			\$1,728.70	
1 R	OKER PANEL OUTER RH			\$576.00	_
1 R	EAR FENDER RH			\$836.70	
	SUB TOTAL			\$6,539.50	
	LESS 25%			\$1,634.88	
	DISCOUNTED TOTAL			\$4,904.63	
1 FF	RT DOOR COMFORT LOGO			\$75.00	NE
1 RI	R DOOR COMFORT & APP STICKER			\$80.00	N
			-	\$155.00	
- 1	abour Charge				7.
	ANEL BEATING			\$800.00	- 70a
- 1	PRAY PAINTING CHARGE			\$ <del>1,000.0</del> 0	901
- 1	/IRING CHARGE			\$50.00	
	RANSFER OF FRT & RR DOOR			\$240 <del>.00</del>	
JTU	UFF KOTE	~	-	\$50.00	
	TOTAL LABOUR		}	\$2,140.00	
		l l	F		

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ LKK
24/5/2021 1605
L15
4 DAYS
CHECK (HEM PHOTOS
AFTER REPORT PHOTOS