

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

Date

Your Insured

Time of Fax

Date of Acc

Attn: Motor Claims Department

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH Ć

Our client has engaged us to repair the above vehicle and submit claims against the other party/partiesinvolved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- Our initial estimate of repairs of the damaged vehicle; i)
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Lim Kwok Ena

Tel: 6214 8355 or HP: 9824 0811

♦ Jumani Bin Masudin

Tel: 6214 8315 or HP: 9635 5305

♦ Lim Tien Siong

Tel: 6214 8398 or HP: 9635 8546

* Chiang Liat Choon

Tel: 6214 8314 or HP: 9296 6006

chianglc@cdge.com.sg Fax no. 6546 8156

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

Taxi Accident Repair

REPAIR ESTIMATE*

VEHICLE NO SHC7668S

DATE 22/05/2021

MAKE :

MODEL : HYUNDAI IONIQ

/ CHIANG/NTUC

IVIODEL			,	
Qty	Parts Description/ Labour	Туре	Unit Price	Amount
	REAR DOOR OUTER MOULDING LH			\$125.30
	REAR LH DOOR PANEL			\$1,789.90
	REAR ROCKER GARNISH LH			\$715.60
	REAR WHEEL COVER LH			\$346.40
	SUB TOTAL			\$2,977.20
	LESS 20%			\$595.44
	DISCOUNTED TOTAL			\$2,381.76
1	PETROL STICKER			\$10.00
	REAR DOOR COMFORT APP STICKER			\$80.00
				\$90.00
	Labour Charge			
	Panel Beating			\$1,050.00
	Spray Painting Charge			\$1,000.00
	Remove/refix door parts			\$120.00
	Remove/Refix rear upholstery			\$90.00
	Tuff coating			\$90.00
	Check Wiring			\$60.00
	TOTAL LABOUR			\$2,410.00
				\$4,881.76
	ESTIMATE TOTAL			\$4,881.76
	This is an initial estimate based on a visual inspection of the	e above veh	nicle. The final repair g	uantum will
	be prepared after the vehicle is surveyed by a motor Surve		• • •	
	the state of the s	,	,	constant and the second

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

24/05/2021 09:21 (SGT) 22/05/2021 09:40 (SGT) Cantonment Link, Singapore

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SHC7668S

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Company Reg No. **Email Address** Mobile Phone No Alternative Phone No.

Yes CITYCAB PTE LTD 1XXXXX839G fleetsafety@cdgtaxi.com.sg (Phone) +65-83217018 (Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer Model Variant

Hyundai Ae ioniq

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category Transmission CC

Private hire

No - Claiming third party Taxi

Auto 1580

INSURANCE COMPANY

Name of Insurance Company Type of Coverage Fleet Policy Policy Number

Cover Note Number

AXA Insurance Pte Ltd ThirdPartyFireTheft

Yes

VFX/P2419140

DRIVER

Name of Driver NRIC No

ANG TIONG CHEW SXXXX050G

Date Of Birth Occupation Date Of Driving Pass

Driving experience

Gender

Mobile Number

Alt. Phone Number **Email Address**

Address

Address complement Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions

Road Surface

Collision - Change/cross lane

Clear Dry

17/09/1972

01/02/1991

30 YEARS AND 3 MONTHS

fleetsafety@cdgtaxi.com.sg

BLK 876 TAMPINES STREET 84#10-22

(Phone) +65-83217018

Outdoor

Male

520876

No

No

Hirer

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident

Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

No

2 No

Yes

1

No

DETAILS OF POLICE ACTION

Was the accident reported to the police? Was notice of intended Prosecution given?

If yes, against whom?

No

No

CIRCUMSTANCES OF ACCIDENT

ON 22/05/2021 @0940 HRS. I WAS DRIVING MY VEHICLE A-SHC7668S ALONG CANTONMENT LINK TOWARDS CANTONMENT ROAD. AT JUNCTION SLIP ROAD TO SPOTTISWODDE PARK ROAD THIS VEHICLE B-SKE815J SUDDENLY STOPPED SO I OVER TAKE THIS VEHICLE WITH RIGHT SIGNAL AND THIS VEHICLE B MOVED AND HIT ON MY VEHICLE REAR LEFT SIDE.

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Reasons for not uploading a video of the accident

Was there any audio recorded?

Yes

Yes

FILE IS NOT SUITABLE

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKE815J Vehicle Manufacturer Mercedes

Vehicle Model

Vehicle Variant Vehicle Colour

Vehicle Category Private car Name of Driver UNKNOWN

Contact Number			-
Address			-
Address complement			0
Postcode `			
nsurance Company Name			-
Nature Of Damage			
Details of property damaged in accident			_
No. Of Passenger (Including Driver)			1



SKETCHPLAN

IMPORTANT NOTICE

- Pease recort correctly the details of the accident to speed up the claims process.
- 2. The Formatust be completed by the Policyholder and/or the Authorised Diver.
- 3. Information provided must be as truthful and accurate as possible. Any will discontinuous will think the provided must be as truthful and accurate as possible. Any will discontinuous contents to repudiate policy liability.
- 4. The save and acceptance of this Formby insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 5. The report will be forwarded by the insurers of the GM Records Management Centro established by the General Insurance Association of Singapore (GM) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. Sy the begennent of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the record being made available aforesed.
- 8. Consent under the Personal Data Protection Act (PDPA)

tunderstand, acknowledge, agree and consent that

- (a) My insurer , my workshop and the General insurance Association of Singapore ('GIA') may/are permitted to collect, use, disclose affect process my personal data personal information set out in this (form) and any eiter personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers law yers/law firms, the Monetary Authority of Singapore and any relevant government agencylauthority (such as the police), for the purpose(s) of :
- (i) processing thanding and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
- ii) mestigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(colectively the 'Purposes')

- (b) all insurer(s) who have insured vehicle(s) involved in this addident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be discksed by any of the Insurers end/or SW to their third party service providers or agents (including their law yers/law firms), which may be sted outside of Singapore, for one or more of the above Purposes.

			- Swar
Policyholder's Signature / Date & Tarre	Driver's Sgnature (f d & Time カンラン	river is not the policyholder) / Date	Witnessed by Reporting Centre Personnel SANKARI.
Sketch Plan	- (-)	1150 cure?	and the second s
The second second section is a second	1 1 1 1 / 1	1/8	
	11/7	1/38/2/	A- SA C7668 S
	12/	184	8 - SKE 815 J
27	NAV	18	1 1 1 1 1 1 1 1 1 1 1 1 1 1
·····	Tool AA		
	0 8 13 1-		
A Property of the	In I		si pedia il 1 resentatorio di 13. En recojuntamente della di 15.00
		1-1-1-1-1-1	3 T. H. H. T. T.

		0.1	1 3	lorl	2011	60	-	0.46	Line		-	Doctoria		705.60		1-202-2-2-2	West a
		- 0'		1021	00,0	(0)	_0	440	HRS			WAS	DUZVZ	117	WA	VBH	THE
A-	SHO	76	688	ALC	pricy	CAN	TONIY	nshit	Ľ	Inc.	7	OVERDS	CA	hetonlyn	54T	ßĎ	•
77	Jú	n()	JoH	ડાર	P 1	PURD	то	2	POIT	Swoo	DE.	PARK	60	THIS	VEF	TILLE	B -
SKE	8	5 J	S	иддры	LY	\$70	色	30	7.	OVS	æ	TAKE	THZS	VER	ICLE	W.	111
2241	41	57	GMAL	- A	eri)	THIS		PHIC	CE_	В	m	ovno	AHID	477		0н	my
15 HZ	LLE		RHAR) Lie	F7	STOR							0-11/2				
_	-	-	-		-				_								
						-	-	_	_		-						
_	_																
							-				_						
								-			_						
		_															
					_												
		_	_														
6		_															
- 60	_				_		-		_								
- 60																	
			7														
																	- 10
																E C	
																Biological Control of the Control of	
																B)	

Declaration

WWe declare the foregoing particulars are true in every respect

Policyholder's Signature / Onte &

Criver's Signature (if driver is not the policyholder) / Date & Time 37 (5) 2-(1) 20(4)(5)

Witnessed by Reporting Centre Personnel SAYIZAM. SAYIZAH.





















