

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref	: CS/AGI21006103/Kvf3e2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Dat	e: 05/07/2021	
			Cod	de: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SGS 9784D	Veh. Inspected	GBF 9418P	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10010314/HA	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	24/05/2021	
2. Vehicle Particulars & Condition					
	Make & Model	PEUGEOT PARTNER (A)	c.c	1560	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	VF37FBHYMGJ856868	Colour	SILVER	
	Odometer	108903 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	MICHELIN	7 mm	
	L/H Front Tyre	195/65 R15	MICHELIN	7 mm	
	R/H Rear Tyre	195/65 R15	AUFINE	6 mm	
	L/H Rear Tyre	195/65 R15	AUFINE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	21/05/2021	Inspection Date	27/05/2021	
	Survey held at	ALAN'S UNITED AUTO PTE LTD			
		BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	15)iit / COOKBAIN	Estimate Days of Repair			

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: