

REF: *ASM/21008120/Kt*

NAME:
Kenneth

SLV 66320 Yr Regn: 01, 18

Veh No: 56V 00320 Yr Regn: 071 00

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or A) Wagen

Make: Honda Shuttle C.G. 1976

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading 77363 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GKJ . 1600141

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/~~Rim~~ / STD A/Rim or

Tyre Size: F: 195/50R16

R: _____

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/

TOYO / YOKO or

Front Rear

R/Bal. 3 mm R/Bal. 8 mm

UBal. 5 mm UBal. 8 mm

D.O.A. 23/5/21 D.O.I. 28/5/2022

Survey held at _____

Des. of Damages : Frt / ~~Rear~~ / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

Prell. Report

Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Port Format :

Sum / I.B.I.: (S) קו

Add Fee: ☐ : Site Insp (\$

□: Interview (S

☐: Tech Invs (\$

☐ : Weekend (\$

 S → RS. S

Figures

Others

TO : MOTOR CLAIM DEPT. TP VEH NO : SHD131

ESTIMATE REPORT IN QUOTATION

OWNER'S PARTICULARS

NAME : TAN KOK ANN

ADDRESS :

REG NO : S14682D TRANS :

MAKE / MODEL : HONDA SHUTTLE

OWNER'S INSURER : DIRECT ASIA

JOB CODE : TP S.A : MICHELLE

JOB NO :

CONTACT : 91479663

CHASSIS NO :

ENGINE NO :

ACCIDENT DATE : 23-May-21

CLAIM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC. %	DISC-PRICE	SUR	REV. PRICE
1 REAR BUMPER	1.00	1530.00	20.00	1224.00	Y	✓
2 REAR BUMPER SPONGE LH	1.00	66.00	20.00	52.80	Y	X
3 REAR BUMPER SPONGE RH	1.00	66.00	20.00	52.80	Y	X
4 REAR BUMPER BEAM	1.00	298.00	20.00	238.40	Y	?
5 REAR BUMPER BRACKET LH	1.00	48.90	20.00	39.12	Y	X
6 REAR BUMPER BRACKET RH	1.00	48.90	20.00	39.12	Y	X
7 REAR BUMPER SIDE RETAINER LH	1.00	45.00	20.00	36.00	Y	X
8 REAR BUMPER SIDE RETAINER RH	1.00	45.00	20.00	36.00	Y	X
9 REAR BUMPER TOWING COVER	1.00	80.00	20.00	64.00	Y	X
10 REAR BUMPER REFLECTOR LH	1.00	238.00	20.00	190.40	Y	✓
11 REAR BUMPER REFLECTOR RH	1.00	238.00	20.00	190.40	Y	X
12 TAILGATE	1.00	1864.00	20.00	1491.20	Y	✓
13 TAILGATE HINGE LH	1.00	89.50	20.00	71.60	Y	X
14 TAILGATE HINGE RH	1.00	89.50	20.00	71.60	Y	X
15 TAILGATE DAMPER LH	1.00	168.00	20.00	134.40	Y	X
16 TAILGATE DAMPER RH	1.00	168.00	20.00	134.40	Y	X
17 TAILGATE OUTER GARNISH	1.00	426.70	20.00	341.36	Y	✓
18 TAILGATE LOCK	1.00	176.00	20.00	140.80	Y	✓
19 TAILGATE INNER BOARD	1.00	480.00	20.00	384.00	Y	?
20 TAILGATE REFLECTOR LH	1.00	698.00	20.00	558.40	Y	X
21 TAILGATE REFLECTOR RH	1.00	698.00	20.00	558.40	Y	X
22 TAILGATE LOCK CATCH	1.00	58.00	20.00	46.40	Y	X
23 TAILGATE RUBBER BEADING	1.00	197.00	20.00	157.60	Y	✓
24 TAILGATE WIPER MOTOR	1.00	485.00	20.00	388.00	Y	X
25 TAILGATE EMBLEM (SHUTTLE)	1.00	55.80	20.00	44.64	Y	✓
26 TAILGATE LOGO	1.00	50.80	20.00	40.64	Y	✓
27 TOOLS HOUSING RH	1.00	218.00	20.00	174.40	Y	?
28 TOOLS COVER TOP RUBBER MAT	1.00	238.40	20.00	190.72	Y	X

29	TOOLS COVER HOUSING	1.00	Sn	428.00	20.00	342.40	Y	X
30	TOOLS COVER HOUSING LH SIDE	1.00	Sn	218.00	20.00	174.40	Y	X
31	REAR END PANEL	1.00		910.00	20.00	728.00	Y	?
32	SPARE TYRE PANEL	1.00	N	1198.60	20.00	958.88	Y	X
33	REAR END INNER MEMBER PANEL	1.00	N	870.60	20.00	696.48	Y	X
34	REAR END PANEL TOP GARNISH	1.00	N	187.00	20.00	149.60	Y	✓
35	REAR SPARETYRE INNER BOARD	1.00		390.00	20.00	312.00	Y	?
36	TAILLAMP LH	1.00	Sn	896.00	20.00	716.80	Y	X
38	TAILLAMP INNER PANEL LH	1.00	N	194.60	20.00	155.68	Y	X
39	REAR FENDER INNER SHIELD LH	1.00	Sn	103.00	20.00	82.40	Y	X
40	REAR FENDER INNER BOARD BOTTOM LH	1.00	Sn	301.20	20.00	240.96	Y	X
41	REAR SIDE OUTER PANEL LH	N 1.00	Sn	286.00	20.00	228.80	Y	X
42	REAR FENDER INNER BOARD TOP LH	1.00	Sn	363.40	20.00	290.72	Y	X
43	REAR FENDER LH	1.00	N	586.80	20.00	469.44	Y	X
44	REAR FENDER INNER TRIM LH	1.00	Sn	301.00	20.00	240.80	Y	X
46	EXHAUST MUFFLER	1.00	N	585.40	20.00	468.32	Y	X
47	EXHAUST PIPE CENTRE	1.00	N	1288.60	20.00	1030.88	Y	X
48	EXHAUST PIPE MOUNTINGS	1.00	Sn	96.00	20.00	76.80	Y	
49	KEYLESS SENSOR	1.00		380.00	20.00	304.00	Y	?

TOTAL (PARTS):

18448.70

14758.96

SPECIAL NETT ITEM

1	REAR BUMPER CLIPS (1 SET)	N	1.00	50.00	0.00	50.00	Y	✓
2	TAILGATE GLASS INNER SEAL	N	1.00	50.00	0.00	50.00	Y	200sn
3	TAILGATE GLASS SEALANT	N	1.00	50.00	0.00	50.00	Y	400sn
4	TAILGATE GLASS CLEANER & PRIMER	N	1.00	50.00	0.00	50.00	Y	X
5	TAILGATE INNER BOARD CLIPS (1 SET)	N	1.00	50.00	0.00	50.00	Y	✓
6	REAR NUMBER PLATE	Sn	1.00	50.00	0.00	50.00	Y	X
7	REAR END PANEL SEALANT		1.00	80.00	0.00	80.00	Y	?
8	REAR FENDER INNER SHIELD CLIPS (1 SET)	N	1.00	50.00	0.00	50.00	Y	X
9	REAR FENDER INNER BOARD CLIPS(1 SET)	N	1.00	50.00	0.00	50.00	Y	X
10	REVERSE SENSOR	CR	1.00	480.00	0.00	480.00	Y	2000sn
11	TAILLAMP INNER CLIPS (1 SET)	N	1.00	50.00	0.00	50.00	Y	X
12	SPARE TYRE INSULATOR PAD	N	1.00	280.00	0.00	280.00	Y	X
13	SPARE TYRE PANEL SEALANT	N	1.00	80.00	0.00	80.00	Y	X
14	1/4 GLASS SEALANT	N	1.00	50.00	0.00	50.00	Y	X
15	1/4 GLASS INNER SEAL	N	1.00	50.00	0.00	50.00	Y	X
16	1/4 GLASS CLEANER & PRIMER	N	1.00	50.00	0.00	50.00	Y	X

TOTAL (PARTS):

1520.00

1520.00

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREA	1.00	1800.00	0.00	1800.00	Y	6001
2	SPRAY PAINTING ON AFFECTED AREA	1.00	1600.00	0.00	1600.00	Y	6001
3	R&R TAILGATE COMPONENTS	1.00	120.00	0.00	120.00	Y	601
4	R&R TAILGATE GLASS	1.00	120.00	0.00	120.00	Y	✓
5	R&R SPARETYRE BOARD, CARPET, TRIMS	1.00	120.00	0.00	120.00	Y	601
6	R&R SEATS & CARPET TO ASSIST REPAIR	1.00	120.00	0.00	120.00	Y	501
7	R&R REVERSE SENSOR & CALIBRATION	1.00	120.00	0.00	120.00	Y	601
8	RESPRAY TUFF KOTE ON ACC AREAS	1.00	120.00	0.00	120.00	Y	201
9	CHECK & REPAIR WIRING SYSTEM	1.00	380.00	0.00	380.00	Y	X
10	R&R EXHAUST PIPE SYSTEM	na 1.00	120.00	0.00	120.00	Y	X
11	R&R 1/4 GLASS ASSY	na 1.00					

4740.00 4740.00

TOTAL PARTS & LABOUR

24708.70 21018.96

EXCESS : : S\$

NO. OF DAY : 05

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY PART OR LUMP-SUM : S\$

DATE OF SURVEY : 28 / 5 / 21

SURVEY BY :

CONTACT NO:

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FAX NO :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	24/05/2021 11:23 (SGT)
Date of Accident	23/05/2021 09:45 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	SLIP RPAD AT CLEMENTI AVENUE 6 TOWARDS AYE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLV6632D

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN KOK ANN
NRIC No	SXXXX664B
Email Address	TANKOKANN1963@YAHOO.CO.UK
Mobile Phone No	(Phone) +65-91479663
Alternative Phone No	+65-91479663

VEHICLE PARTICULARS

Manufacturer	Honda
Model	SHUTTLE 1.5G CVT
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1496

INSURANCE COMPANY

Name of Insurance Company	Direct Asia Insurance (Singapore) Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	MT/00735323/01
Cover Note Number	-

DRIVER

Name of Driver	TAN KOK ANN
NRIC No	SXXXX664B

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan

SIP road at Clementi Ave 6
towards AYE



Vehicle A: SLV 6632D
Vehicle B: SHD 173T