Service Requests

Messages

Claims



Assessment Details

General & Workshop De	etails Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour Miscellaneous			
	Summary						
General Details		Wo	rkshop Details				
nvolving	TPVD UNKNOWN (SLV6632D)			0			
Date of Loss	23 May 2021	Am	ount				
ime of Loss	9:45	Net	t Loss Amount	-\$34,792.00			
oss Description	SHD173T (INSD)hit rear of SLV66	32D (TP) Ass	igned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)			
Comment			rs of work	20			

Messages

Claims



General & Workshop	Details Ve	hicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	
		'	Summary				
Vehicle & Driver De	tails						
/ehicle Registration#	SLV6632D		Pı	urchase Date	DD/MM/YYYY		
Registration State	SINGAPOR	RE	Re	egistration Date *	09/01/2018		
Mileage	77363		Ag	ge of Vehicle	3		
CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMAT	TION	river Details			
Manufacturing Year		2017		CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION	
				Driver Name	TAN KOK ANN		

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Make	TPVD	HONDA	Date of Birth	16 January 1963	DD/MM/YYYY
Model	UNKNOWN	SHUTTLE 1.5G CVT	Age	58	
Туре		•	Occupation	Unknown	
Type of Paint			Education Qualification	Other	•
Chassis No		GK81200141	Driving Experience	0	
Engine No		L15B5460174	Driver License #		
Engine Capacity		1496	License Type		•
Sum Insured		0	License Issue Date		DD/MM/YYYY

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		0

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		DD/MM/YYYY
Address	Singapore	
Address type	Personal Correspondence	~
Gender	Male	~
Marital status	Unknown	•
Identification #	S1590664B	

Messages

Claims



General & Workshop De	tails Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous		
			Summary				
Detailed Assessment		Со	ndition of Vehicle	e at time of surve	∍y		
Inspection Date *	28/05/2021	Ger	neral condition		~		
Total Loss	Yes No	Ste	ering (Serviceable)	Yes	Yes No		
Towing Charges	0		Footbrake (Serviceable)		No		
Voluntary Excess	0		ndbrake rviceable)	Yes	No		
Compulsory Excess	0	Eng	gine Modification	Yes	No		
Young/Inexperienced/ Unnamed Driver Excess	0	Pre	-accident condition	Good		~	

0

Tyre Condition

Age of Tyres	
Front Tyre Size	195/50R16
Front left side	DUNLOP5mm
Front right side	DUNLOP5mm
Spare wheel	
Rear Tyre Size	195/50R16
Rear left side	DUNLOP8mm
Rear right side	DUNLOP8mm

Messages

Claims



General & Workshop De	tails Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour Miscellaneous				
				Summary				
Tax Eligibility & Additi	onal Deduction for Parts							
Depr./Bttr%	0	Salv	age%	0				
Discount%	20	Sett	lement%	100				
		Paint La	abour/Material F	Ratio				
Paint Labour Ratio	20	Cas	h Loss	Yes	No			
Paint Material Ratio	80	Part	Supplied by AXA	Yes	No			
					Save			

Messages

Claims



Add		Appro	ove	Deny	Submit All	I							
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTI AMOUN
	0	1		REAR BUMPER	Buckled	0	1150	No	0	20	0	0	920
	0	1		REAR BUMPER SPONGE LH	Cracked	0	66	No	0	20	0	0	52.8
	0	1		REAR BUMPER SPONGE RH	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER BEAM	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER BRACKET LH	Repair	0	0	No	0	0	0	0	0
	0	1		REAR BUMPER BRACKET RH	Repair	0	0	No	0	0	0	0	0

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	A (I
	0	1		REAR BUMPER SIDE RETAINER LH	Serviceable	0	0	No	0	0	0	0	0	С
	0	1		REAR BUMPER SIDE RETAINER RH	Serviceable	0	0	No	0	0	0	0	0	С
	0	1		REAR BUMPER TOWING COVER	Serviceable	0	0	No	0	0	0	0	0	С
	0	1		REAR BUMPER REFLECTOR LH	Cut	0	113.2	No	0	20	0	0	90.56	F
	0	1		REAR BUMPER REFLECTOR RH	Serviceable	0	0	No	0	0	0	0	0	С
	0	1		TAILGATE	Bent	0	1193	No	0	20	0	0	954.4	F
	0	1		TAILGATE HINGE LH	Repair	0	0	No	0	0	0	0	0	С
	0	1		TAILGATE HINGE RH	Repair	0	0	No	0	0	0	0	0	С
	0	1		TAILGATE LOCK	Dented	0	176	No	0	20	0	0	140.8	F

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	A (I
	0	1		TAILGATE INNER BOARD	Cracked	0	320	No	0	20	0	0	256	F
	0	1		TAILGATE REFLECTOR LH	Serviceable	0	0	No	0	0	0	0	0	С
	0	1		TAILGATE REFLECTOR RH	Serviceable	0	0	No	0	0	0	0	0	С
	0	1		TAILGATE LOCK CATCH	Repair	0	0	No	0	0	0	0	0	С
	0	1		TAILGATE RUBBER BEADING	Dented	0	197	No	0	20	0	0	157.6	F
	0	1		TAILGATE WIPER MOTOR	Serviceable	0	0	No	0	0	0	0	0	С
	0	1		TAILGATE EMBLEM (SHUTTLE)	Necessary	0	55.8	No	0	20	0	0	44.64	F
	0	1		TAILGATE LOGO	Necessary	0	50.8	No	0	20	0	0	40.64	F
	0	1		TOOLS HOUSING RH	Dented	0	218	No	0	20	0	0	174.4	F

EDIT	Т	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	A (I
		0	1		TOOLS COVER TOP RUBBER MAT	Serviceable	0	0	No	0	0	0	0	0	С
		0	1		TOOLS COVER HOUSING	Serviceable	0	0	No	0	0	0	0	0	С
		0	1		TOOLS COVER HOUSING LH SIDE	Serviceable	0	0	No	0	0	0	0	0	С
		0	1		REAR END PANEL	Bent	0	631.5	No	0	20	0	0	505.2	F
		0	1		SPARE TYRE PANEL	Repair	0	0	No	0	0	0	0	0	С
		0	1		REAR END INNER MEMBER PANEL	Repair	0	0	No	0	0	0	0	0	С
		0	1		REAR END PANEL TOP GARNISH	Dented	0	187	No	0	20	0	0	149.6	F
		0	1		REAR SPARE TYRE INNER BOARD	Cracked	0	390	No	0	20	0	0	312	F
		0	1		TAILLAMP LH	Serviceable	0	0	No	0	0	0	0	0	С

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	A (I
	0	1		TAILLAMP INNER PANEL LH	Repair	0	0	No	0	0	0	0	0	С
	0	1		REAR FENDER INNER SHIELD LH	Serviceable	0	0	No	0	0	0	0	0	С
	0	1		REAR FENDER INNER BOARD BOTTOM LH	Serviceable	0	0	No	0	0	0	0	0	С
	0	1		REAR SIDE OUTER PANEL LH	Repair	0	0	No	0	0	0	0	0	С
	0	1		REAR FENDER INNER BOARD TOP LH	Serviceable	0	0	No	0	0	0	0	0	С
	0	1		REAR FENDER LH	Repair	0	0	No	0	0	0	0	0	С
	0	1		REAR FENDER INNER TRIM LH	Cracked	0	301	No	0	20	0	0	240.8	F
	0	1		EXHAUST MUFFLER	Repair	0	0	No	0	0	0	0	0	С

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION		PRICE PRKSHOP)	LIST P	PRICE /EYOR)	SUPP PART:	LEMENTARY	DEPR./ BTTR%	DISC OUNT%	6	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	A (I
		0	1		EXHAUST PIPE CENTRE	Repair	0		0		No		0	0		0	0	0	С
		0	1		EXHAUST PIPE MOUNTINGS	Serviceable	0		0		No		0	0		0	0	0	С
		0	1		KEYLESS SENSOR	Dented	0		108		No		0	20		0	0	86.4	F
		0	1		FENDER INNER TRIM RH	Cracked	0		301		No		0	20		0	0	240.8	F
Labou	ır																		
	Add		Approv	e	Deny	Submit All													
	EDIT	SR NC		:/REPLACE JR)	PART NAME	ESTIMATE LABOUR AMOUNT		ADJUSTED LABOUR AMOUNT		ESTIMATE PAINT AMOUNT		ADJUSTED PAINT AMOUNT	ACTIO (LABO		COMMEN	ΝΤ	REMOVE		
		0			STRAIGHTEN & PANE BEAT ACCIDENT ARE	0		600		0		0	Revie	wing					
		0			SPRAY PAINTING ON AFFECTED AREA	0		600		0		0	Revie	wing					
		0			R&R TAILGATE COMPONENTS	0		60		0		0	Revie	wing			iii		
		0			R&R TAILGATE GLASS	0		120		0		0	Revie	wing					
		0			R&R SPARETYRE BOARD, CARPET, TRIMS }	0		60		0		0	Revie	wing					

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		R&R SEATS & CARPET TO ASSIST REPAIR }	0	0	0	0	Reviewing		
	0		R&R REVERSE SENSOR & CALIBRATION	0	50	0	0	Reviewing		
	0		RESPRAY TUFF KOTE ON ACC AREAS	0	60	0	0	Reviewing		
	0		CHECK & REPAIR WIRING SYSTEM	0	20	0	0	Reviewing		
	0		R&R EXHAUST PIPE SYSTEM	0	0	0	0	Deny		
	0		R&R 1/4 GLASS ASSY	0	0	0	0	Deny		



Messages

Claims



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Add	Approve	Deny		Submit All		
EDIT NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
0	DAYS OF REPAIR : 5 DAYS	Reviewing	0	0		
0	1 SET REAR BUMPER CLIPS	Reviewing	0	50	NECESSARY	

EC	DIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
Ø		0	TAILGATE GLASS INNER SEAL	Reviewing	0	20	NECESSARY	
Ø		0	TAILGATE GLASS SEALANT	Reviewing	0	40	NECESSARY	
Ø		0	TAILGATE GLASS CLEANER & PRIMER	Deny	0	0	NOT NECESSARY	
ß		0	1 SET TAILGATE INNER BOARD CLIPS	Reviewing	0	50	NECESSARY	
B		0	REAR NUMBER PLATE	Deny	0	0	SERVICEABLE	M

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	REAR END PANEL SEALANT	Reviewing	0	30	NECESSARY	
	0	1 SET REAR FENDER INNER SHIELD CLIPS	Deny	0	0	NOT NECESSARY	
	0	1 SET REAR FENDER INNER BOARD CLIPS	Deny	0	0	NOT NECESSARY	
	0	REVERSE SENSOR	Reviewing	0	200	CRACKED	
	0	1 SET TAILLAMP INNER CLIPS	Deny	0	0	NOT NECESSARY	

ED	IT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	>	0	SPARE TYRE INSULATOR PAD	Deny	0	0	NOT NECESSARY	
	>	0	SPARE TYRE PANEL SEALANT	Deny	0	0	NOT NECESSARY	
	>	0	1/4 GLASS SEALANT	Deny	0	0	NOT NECESSARY	
	>	0	1/4 GLASS INNER SEAL	Deny	0	0	NOT NECESSARY	
	>	0	1/4 GLASS CLEANER & PRIMER	Deny	0	0	NOT NECESSARY	
	>	0	REVERSE CAMERA	Deny	0	0	NOT NECESSARY	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	1 SET TAILGATE DAMPER ASSY	Reviewing	0	900	JAMMED	



Messages

Claims



Assessment Details

General & Workshop	Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary						
Estimated Claim Amount	\$0.00		Adjı	usted Claim Amoun	t \$7,226.64	
CATEGORY		ESTIMATE	ADJUSTED			
Spare Parts		\$0.00	\$4,366.64			
Labour		\$0.00	\$1,570.00			
Miscellaneous		\$0.00	\$1,290.00			

Submit for Review



Messages


Claims



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary



Messages

Claims



Assessment Details

General & Workshop	Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary						
Estimated Claim Amount	\$0.00		Ac	ljusted Claim Amount	\$5,800.00	
CATEGORY		ESTIMATE	ADJUSTED			
Miscellaneous		\$0.00	\$5,800.00			

Submit for Review