

ASS. REC. BY: marcus

REF:

CS/ A1621006131/4g f3ASSIGNMENTFrom:
Estimated Cost:

Date:

Veh No: MDC 6175 Yr Regn: 01/11/18
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

use 2hrs Intch 6k.

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time. File Pass to?

1)

Date/Time. File Return to?

2)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) __ \$ + RS __ \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$