"ET. CS/AIG 21006136/ETF3 ASS. FIEC. BY: Stere ASSIGNMENT SK4 7703T Yr Regn: 17/81 Veh No: \_\_ Date: Type: (M.Ca) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Estimated Cost: Truck / Trailer or OD) TP / WS / TP RES / OD RES / EVA / INV / MV Make: To Inspect Vehicle No: Insured / Std / NI / NA Colour at Workshop m/s \* T/Radio: Insured / Std / NI / NA Sp.Reading Eng/No: KNAPC81AMF 7779063 C/No: Policy No. 2100424779 Gen. Cond: Good (Fair) Poor / Burnt Claims No. 9289985524SG Steering: In order / Jammed / Leaked / Burnt or 600 Excess: Brake: Inorder / Jammed / Leaked / Burnt or (Client's Record) Modi: Nil / S/Rim / STD A/Rim or Make of Veh: Tyre Size: -{Policy Condition) BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / N/S Remark: The veh had commenced its Kumho repair at the time of inspection. TOYO / YOKO or Rear Front Bal. or Market Value: R/Bal. . Consistent? : Yes or No R/Bal. IDAC Accident Rport L/Bal. L/Bal. mm Consistent?: Yes or No GIA / PR Seen: D.O.I. 25/5/21 Res.: Yes or No days Est. Repairs: Survey held at 3 Val.: Yes or No Lum Sum: Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or CA / REV / REP. / 24 HRS Vehicle: IN / OUT The U/C / Chassis frame / Body Structure affected due to collision. Person Contacted: · Action / Instruction Date / Time MV-56K Confirm final figure at \$3867.60, 4days red:1610.20;29% Days Of Repair: Date/Time, File Pass W? : Preli. Report Survey Fee: Resurvey No. of Trip: ... 1 : Final Report Transportation: Date/Time, File Return to? S + RS.\_\_SI Add Fee: : Site Insp (\$ Interview 1\$ **Photos** Tech, trive Of Other: Report Follows: Meel ston 1X Lamb Sum / LEU: 14 TOTAL



# CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE** 

GST Reg No : MR-8500111-X

		AND A CONTRACT OF THE PARTY OF			
Reg No : 199405410K	Owner Name & Vehicle Info				
Invoice Name & Address  AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Engine No				

			CSE	Operator		WIP No			h and the
Account No	Terms	Date/Time Printed	QUK	282 / Kevin Leong		33769			
_AX00000	Credit	25/05/2021/ 09:50		ZOZ / KOVIII ZI	Qty	<b>Unit Price</b>	Disc%	Amo	
E PNT98000 SPRAY PA E PNT88000 TO TRANS M SUNDRY TO PERFO A 54900099 CHECK ON	INT WORK FER RH F ORM RUST N WIRING	Description of Goods  REAR DOOR, RH ROCKER  ON RH FRT & REAR DOOR  RT & REAR ATTACHMENTS  PREVENTION  & CHASSIS ELECTRICAL  GNOSTIC CHECK USING  O TEST	R PANEL & A  DR 2  S TO NEW PA	X 350	5 dys	+ 80 CRH SI	hrty)	700 <sup>1</sup>	600.00 120.00 240.00 80.00 30.00 120.00
M SUNDRY SUNDRIES M SUNDRY TO SUPPL M PANEL AS M PANEL AS M TAPE-FR M TAPE-RR M BLACK TO M BLACK TO M GARNISH M MOULDIN M GARNISH	S  Y RH ANT SSY-FRONT SSY-REAR  DR BLACK DR BLACK APE-FR DF APE-RR DF ASSY-QTF G ASSY-RR	TI-FILM / MCC DOOR,RH / 00 DOOR,RH / 00 CFRAME RR RH CFRAME FR,RH	Arc Nec Nec Nec	Steve CLK	1.00 1.00 1.00 1.00 1.00 1.00 1.00	1115.00 891.00 26.00 25.00 26.00 22.00 125.00 320.00 116.00	20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00		25.00 892.00 712.80 20.80 20.80 17.60 100.00 256.00 92.80 42.40
the i	Repairer of resurvey befor display damag ts prices are sort party survey	the following: e/after spray painting ed part(s) during resurvey ubject to confirmation y is on a "Without Prejudice" basis		V	P/P 7% GST 0	, M Bo	ett 20 ole	. !	5,440.20 380.8 5,821.0

Validity sof this easing to 14 days from date of quote. This is a computer generated document, no signature is required.

Validity sof this easing to 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a after work has started and needed for repairs or replacement of the work. Payment for this may be made in cash, credit card or deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 1 of 1

SC1A215P0003 / CYCLE & CARRIAGE AUTOMOTIVE PTE LTD ENTRY DATE & TIME: 25/05/2021 13:59 (SGT)
SUBMITTED BY: TAN SHIEH YUEN VERSION: 1 (25/05/2021 13:59 (SGT))



## **SINGAPORE ACCIDENT STATEMENT**

### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies

- 4. The issue on the insurance companies.

  5. Any false reporting may be referred to the Police for Investigation.

  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

### ACCIDENT STATEMENT

Date of Submission Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

25/05/2021 13:59 (SGT) 25/05/2021 08:05 (SGT) Canberra Dr, Singapore 752106 15 CANBERRA DRIVE CARPARK Singapore

## !! DETAILS OF OWN VEHICLE 國際

Vehicle Registration Number

**SKU7703T** 

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner NRIC No

**Email Address** Mobile Phone No Alternative Phone No No

**HUANG YING** SXXXX655Z

MATTGREY50@GMAIL.COM (Phone) +65-98734974

+65-98522645

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category

Transmission

CC

Kia

Sportage

Private use

Yes

Private car

Auto

1999

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage Fleet Policy

**Policy Number** Cover Note Number AIG Asia Pacific Insurance Pte. Ltd.

Comprehensive

No

2100424779-05

DRIVER

Name of Driver Passport No/FIN **GREY MATTHEW GILES** FXXXX487W



Accident report SC1A215P0003

Page 1 of 19

Occupation 13/06/1965 Date Of Driving Pass Indoor 16/08/2006 Driving experience 14 YEARS AND 9 MONTHS Gender Mala Mobile Number (Phone) +65-98522645 Alt. Phone Number Email Address MATTGREY50@GMAIL.COM Address 15 CANBERRA DRIVE #01-31 Address complement postcode Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Spouse Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collided into Property Weather Conditions Clear Road Surface Drv OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident ..... Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? ..... Was any other material or property damaged? No Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? REFER TO ATTACHMENT ATTACHMENT(S) and the second Are accident photos available for attachment? Yes Was there any video captured by Car Camera? ..... No

No

Was there any audio recorded?

## SKETCH PLAN

# IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Junderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- $(v) \ complying \ w \ ith \ applicable \ law \ \ in \ administering, \ processing, \ handling \ and/or \ dealing \ w \ ith \ my \ \ claims.$

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

My car-

(anberra Drive car parl

Describe Circumstances of the Accident
I was driving in the car park at 15 CANBERRA  JRIVE CONDO Jand Scraped the two right  hand doors on the corner of a concrete wall.  I was driving slowly at about 18 kmph but  misjudged the space.
Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time ZST S Z 1 100m.

Witnessed by Reporting Centre

Personnel

# KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder

: Huang Ying

period of Insurance

: 17 Aug 2020 To 16 Aug 2021

Engine No. Chassis No. : G4NAFH826744

: KNAPC81AMF7779063

Vehicle No.

: SKU7703T

Policy No.

: 2100424779-05

Endorsement No. **Issued Date** 

: 03 Jul 2020

## ABOUT THE COVER

Make/Model

: KIA SPORTAGE 2.0

Engine Capacity/Tonnage: 1,999.00 CC

Sum Insured : Market Value

First Year of Registration : 2015

: NA

Off Peak Car: No

**Driver Restriction** 

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive\*:

Any person other than the Policyholder who is driving on the Policyholder's order or with his/her permission.

Any person other than the Policyholder only if he/she meets the specified age condition. This Policy will indemnify any authorised driver other than the Policyholder only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDR") If You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving expenence

Age Condition

: All Age Condition

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or Limitation as to use\* speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

## EXCESS

Section 1 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

Huang Ying - \$600 (Own Damage), \$600 (Flood Cover), MATTHEW GILES GREY - \$600 (Own Damage), \$600 (Flood Cover)

# APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

The state of the s

T. Cycle & Carriage Body & Pairk Centre Add: 209 Pandan Gardens Singapore 009339 00004001

2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubl Rd 3 Singapore 408650 67461000

3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800

4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website w AIG SG Mobile App. Simply search and download "AIG SG" from ITunes or Google Play.

## PORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1967 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0500709299

CYCLE & CARRIAGE - MIMILE(KIA)

239 ALEXANDRA ROAD

SINGAPORE 159930 ANSP - MOTOR

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. This computer generated document does not require a signature.

AIGSGMOBILEAPF