ASS. REC. BY: Taufuh | REF: CS/11/2/006/40/7/t-f3 ASSIGNMENT PC3863B Yr Regn. 2015, Adap Veh No: From: Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Estimated Cost: Truck / Trailer or OD/ TP / WS / TP RES / OD RES / EVA / INV / MV Mercedes Benz Sprinter 516.0 2143. Make: To Inspect Vehicle No: A/C: Insured / Std / NI / NA at Workshop m/s T/Radio: Insured / Std / NI / NA Sp.Reading Eng/No: Insured: C/No: Policy No. Gen. Cond: Good / Fair / Poor / Burnt Claims No. Steering: Inorder / Jammed / Leaked / Burnt or Excess: Sum Insured: Brake: Inorder / Jammed / Leaked / Burnt or (Client's Record) Modi: NM / S/Rim / STD A/Rim or Make of Veh: F: 205/75R16. Tyre Size: BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / (Policy Condition) OIS Remark: The veh had commenced its Duraturn. TOYO I YOKO or repair at the time of inspection. Rear \$ 62K Front Bal. or Market Value: R/Bal. R/Bal. mm Consistent?: Yes or No IDAC Accident Rport: ∐Bal. ∐Bal. Consistent?: Yes or No GIA / PR Seen: D.O.I. D.O.A. Res.: Yes or No days Est. Repairs: (&C Panden Survey held at 3 Val.: Yes or No Lum Sum: Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or CA | (REV) | REP. | 24 HRS Fut NIS, 4/C Vehicle: IN / OUT The U/C / Chassis frame / Body Structure affected due to collision. Person Contacted: Date: Action / Instruction Date / Time Days Of Repair: : Preli. Report Date/Time, File Pass to? Survey Fee: Resurvey No. of Trip: : Final Report Transportation: Date/Time, File Return to? S. + RS.\_\_SI : Site Insp (\$ Add Fee: : Interview (\$ : Tech. Invs (\$ Rependential : :Weetend (\$ Lump Sum H.B.J. CF TOTAL



Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

# **ESTIMATE FOR PC3863B**

ComfortDelGro Bus Pte Ltd

205 Braddell Road Singapore 579701 Attn: Mr. Jayson Khoo

65533838

Chassis No

Make/Model

Colour/Trim

WIP No

Reg No/Reg Date

Date In/Mileage

Engine No

Vehicle & Document Information

47815

/ 05/08/2015 PC3863B

100000 WDB9066572P100351

65195532615891

MBCV/516CDI/4325 (E)

/ NA NOT APPLICABLE 914 Arctic White

Description of Goods / Services  A C0940101 To repair and knocking chassis cross member, foot headlamp, support panel, engine basket  A 00940101 To remove a refit front bumper, front headlamp, support panel, fender, sealing door step blade auto, A 00940101 To remove & refit dashboard bracket and grallir A 00940101 To remove & refit wire harness and lighting wire A 00940101 To remove & refit wire harness and lighting wire A 00940101 To remove & refit drive seat there carpet / passenger seat A 00940101 To remove and refit front wheel lower arm, anti low bar and steering To remove and refit front wheel lower arm, anti low bar and steering SCREW  M SCREW  M SCREW  M SCREW  M SCREW  M TRANSMISSION CARRIER  M TRANSMISSION CARRIER LH SHOCK-ABSORBER STRUTH SHOCK-SHOCK	ccount No	Terms	Date/Time Printed	CSE	Operator				
Description of Goods / Services  A 00940101 To repair and knocking thassis cross member. Floor panel, engine basket  A 00940101 To remove ad refit front bumper, front headlamp, support panel, fender, sealing door step blade auto,  A 00940101 To remove & refit engine unit and gear box  A 00940101 To remove & refit dashboard bracket and grallir  A 00940101 To remove & refit wire harness and lighting wire  A 00940101 To remove & refit drive seat there carpet / passenger seat  A 00940101 To remove & refit drive seat there carpet / passenger seat  A 00940101 To remove and refit front wheel lower arm, anti low bar and steering To remove and refit front wheel lower arm and low bar and steering  A 00940101 To remove and refit front wheel lower arm and low bar and steering To remove and refit front wheel lower arm and low bar and steering  A 00940101 To remove and refit front wheel lower arm and low bar and steering To remove and refit front wheel lower arm and low bar and steering To remove and refit front wheel lower arm and low bar and steering To remove and refit front wheel lower arm and low bar and steering To remove and refit front wheel lower arm and low bar and steering To remove and refit front wheel lower arm and low bar and steering To remove and refit front wheel lower arm and low bar and steering To remove and refit front wheel lower arm and low bar and steering To remove and refit front wheel lower arm and low bar and steering To remove and refit front wheel lower arm and low bar and steering To remove and refit front wheel lower arm and low bar and steering To remove and refit front wheel lower arm and low bar and steering To remove and refit front wheel lower arm and low bar and steering To remove and refit front wheel lower arm and low bar and steering To remove and refit drive seat man and low bar and steering To remove and refit front wheel lower arm and lighting wire To remove a refit dashboard and anto. To remove a refit dashboard and anto. To remove a refit dashboard and anto. To remove a refit da	0000021	Credit	25/05/2021/ 13:53		610 / Philip Cheong	Ott	Heit Price	Disc%	Amount
A CO940101 To repair and knocking chassis cross member. Floor panel, engine basket  A 00940101 To remove ad refit front bumper, front headlamp, support panel, fender, sealing door step blade auto, A 00940101 To remove & refit dashboard bracket and gralling A 00940101 To remove & refit dashboard bracket and gralling A 00940101 To remove & refit wire harness and lighting wire A 00940101 To remove & refit drive seat there carpet /passenger seat A 00940101 To remove & refit drive seat there carpet /passenger seat A 00940101 To remove and refit front wheel flower arm, anti low bar and steering To remove and refit front wheel flower arm, anti low bar and steering SCREW A 00940101 To remove & Refit front wheel flower arm, anti low bar and steering To remove & Refit front wheel flower arm, anti low bar and steering SCREW A 00940101 To remove & Refit front wheel flower arm, anti low bar and steering To remove and refit front wheel flower arm, anti low bar and steering SCREW A 00940101 To remove & Refit front wheel flower arm, anti low bar and steering To remove & Refit front wheel flower arm, anti low bar and steering To remove & Refit front wheel flower arm, anti low bar and steering To remove & Refit front wheel flower arm, anti low bar and steering To remove & Refit front wheel flower arm, anti low bar and steering To remove & Refit front wheel flower arm, anti low bar and steering To remove & Refit front wheel flower arm, anti low bar and steering To remove & Refit front wheel flower arm, anti low bar and steering To remove & Refit dashboard bracket and gralling To remove & Refit das			Description of Good	s / Services		City	b/E	San	2 5700.0
M SCREW M SCREW M SCREW M SCREW M SCREW M SCREW M TRANSMISSION CARRIER M TRANSMISSION CARRI	To repair floor par 100940101 To remove 00940101 To	e ad refit e & refit	king chassis cross me basket  front bumper, front hader, sealing door strengine unit and gear dashboard bracket an air con blower/heate wire harness and light front radiator and indive seat the care	headlamp, ep blade a box d grallir r unit and hting wire nter cool	air con condenson	TA	Pluto 13	plus plus	1200 1500.  1200 1500.  2250.  684.  7 528.  450.  7 750.  684
M SCREW  M SCREW  M SCREW  M SCREW  M SCREW  M SCREW  M TRANSMISSION CARRIER  M TRANSMISSION CARRIER LH  M TRANSMISSION CARRIER LH  M SHOCK-ABSORBER STRUT LH  M SPRING BEARING  M PLATE  M BRACKET  A.00  7.98  00.00  896.81  00.00  1.00  665.35  00.00  1.00  76.12  00.00  76.12  1.00  160.90  10.00		e and ret	It front wheel fouch	arm y -	THE RESIDENCE CONTRACTOR OF THE PARTY OF THE				? < 31
M SCREW  M SCREW  2.00 896.81 00.00  M TRANSMISSION CARRIER  1.00 865.35 00.00  M TRANSMISSION CARRIER III  M SHOCK-ABSORBER STRUT III  M SPRING BEARING  1.00 76.12 00.00  M PLATE  M BRACKET  2.00 10.74 00.00  M BRACKET								00.00	31
SCREW   2.00   S96.81   00.00   M   TRANSMISSION CARRIER   H   1.00   665.35   00.00   M   1.00   665.35   00.00   M   1.00   55.54   00.00   M   1.00   76.12   00.00   M   1.00   76.12   00.00   M   1.00   1.0								70.000	2 L34
M TRANSMISSION CARRIER LH  M TRANSMISSION CARRIER LH  M SHOCK-ABSORBER STRUT LH  M SPRING BEARING  M PLATE  M BRACKET  1.00  665.35  00.00  1.00  76.12  00.00  7.10  1.00  1.	M SCREW					2.00			1793
M SHOCK-ABSORBER STRUT 110  M SPRING BEARING  M PLATE  M BRACKET  1.00  55.54  00.00  76.12  00.00  70.00	M TRANSMIS	SION CARR	IER			1.00			b) 665
M SPRING BEARING  M PLATE  M BRACKET  1.00 76.12 00.00	M TRANSMIS	SION CARR	IER FN						17
M PLATE 2.00 10.74 00.00 M BRACKET 1.00 160.90 00.00	M SHOCK-AB	SORBER SI	RUITA						76
M BRACKET 1.00 160.90 00.00		EARING							7 4 21
I Dinone:									160
1 00 00 A0 FO									507
1.00	The state of the s	0.40					7.5		79
M TORSION BAR 2.00 39.55 00.00 M TORSION BAR MOUNT			,			2.00	39.5	00.00	- / -

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would muntion that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worm or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur. we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement after work. Payment for this may be made in cash, credit card or chaque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertant breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6771 4389 Fax: 6775 6310 www.mercedes-benz.com.sg





#### Industries Pte Limited Authorised Dealer Company No. 196400367W **ESTIMATE FOR PC3863B** GST Reg No. MR-8500111-X

ComfortDelGro Bus Pte Ltd

205 Braddell Road Singapore 579701 Attn: Mr. Jayson Khoo

65533838

WIP No

Reg No/Reg Date

Chassis No

Date In/Mileage

Engine No Make/Model

Colour/Trim

Vehicle & Document Information

47815

PC3863B / 05/08/2015

----WDB9066572P100351

65195532615891

MBCV/516CDI/4325 (E)

914 Arctic White / NA NOT APPLICABLE

Cycle & Carriage

Not that havis   Revent   Services   City   Unit Price   Disc's   Amount							Viciniteire III. (con		
N   REAR SUSFRAME	Account No	Terms	Date/Time Printed	CSE	Operator				
REAR SUBFRAME  N STEERING NUCLUE  N AKLE SUBFRAME  1.00 2600.17 00.00  200.01  1.00 232.40 00.00  232.40 00.00  232.40 00.00  232.40 00.00  232.40 00.00  232.40 00.00  232.40 00.00  232.40 00.00  232.40 00.00  232.40 00.00  232.40 00.00  232.40 00.00  232.40 00.00  232.40 00.00  232.40 00.00  232.40 00.00  24.00 13.23 00.00  250.00  N SPRING BEARING  N NUT  N NUT  N NUT  N HEXAGON HEAD BOLT  N HEXAGON HEAD BOLT  N HEXAGON HEAD BOLT  N CAP BOLT  N CAP BOLT  N CAP BOLT  1.00 25.50  1.00  2.00 4.15 00.00  2.00  1.10  4.00 7.38 00.00  2.00  1.11  2.00 18.16 00.00  3.6  2.9  N HEXAGON HEAD BOLT  N CAP BOLT  1.00 5.59 00.00  2.00  1.11  2.00 11.112 00.00  2.00  1.11  2.00 11.112 00.00  2.00  1.00  2.00  1.00  2.00  1.00  2.00  1.00  2.00  1.00  2.00  1.00  2.00  1.00  2.00  1.00  2.00  1.00  2.00  1.00  2.00  2.00  1.00  2.00  2.00  2.00  1.00  2.00  1.00  2.00  1.00  2.00  1.00  2.00  1.00  2.00  1.00  2.00  1.00  2.00  1.00  2.00  1.00  2.00  1.00  2.00  1.00  2.00  1.00  2.00  1.00  2.00  1.00  2.00  1.00  2.00  1.00  2.00  1.00  2.00  1.00  2.	WC000021 Credit 25/05/2021/ 13:53				610 / Philip Che				
# STEERING KNUCKE # TEANSY. CONTROL ARM # TE			Description of Goo	ds / Service	S		Unit Price	Disc%	Amount
Confirmed & accepted by  Nett 23,557. 7% GST on 23557.92 1649.  Total Payable 25,206.	M STEERING M TRANSV. ** M AXLE SUBI M PLATE M HEX. HEAI M SPRING BI M SPRING BI M SPRING BI M NUT M NUT M NUT M HEXAGON M CAP BOLT M SCREW M HEXAGON M ** M *	KNUCKLE CONTROL AF FRAME  D BOLT W I EARING EARING HEAD BOLT HEAD BOLT HEAD BOLT HEAD BOLT HEAD BOLT AT495	PLANGE  PLANGE  Revent.		LKK Auto Consultants h the Repairer of the follor • To resurvey before/after spr • To display damaged part(s) • Parts prices are subject to c • Third party survey is on a "V • No illegal modification(s) is • Supplementary item(s) mus	2,00, 1.00 1.00 1.00 1.00 1.00 1.00 1.00	398.86, 960.86 1052.81 2600.17 232.40 13.23 55.54 26.42 29.65 3.36 4.15 4.15 7.04 18.16 7.38 5.59 9.52 11.12	00.00 00.00 00.00 00.00 00.00 00.00 00.00 00.00 00.00 00.00 00.00 00.00 00.00 00.00 00.00	797. 960. 1052. 2600. 232. 52. 55. 26. 29. 13. 16. 16. 18. 14. 36. 29. 39. 28. 22.
	Confirmed &	accepted b	у		Acknowledged by Repairer Signature:		ST on 23	557.92	23,557.5 1649.0 25,206.5

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding 657. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has communical. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renowal of the windscreen in the event of inadvertent breakage in the course of renowing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6771 4389 Fax: 6775 6310 www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Page 2 of 2



# SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be <u>correleted by the Policyholder and/or the Authorised Driver</u>

3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or witholding of material facts may allow insurance companies to repudiate

The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies. policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the fractional states.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date of Submission Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

21/05/2021 10:37 (SGT) 22/04/2021 02:00 (SGT) 5052 Jurong Port Road, Singapore 619111

Singapore

#### EDETAILS OF OWN VEHICLE

Vehicle Registration Number

PC3863B

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Company Reg No Email Address

Mobile Phone No Alternative Phone No.

COMFORTDELGRO BUS PTE LTD

1XXXXX256W

jaysonkhoo@comfortdelgrobus.com.sg

(Phone) +65-85956777

+65-85956777

VEHICLE PARTICULARS

Manufacturer Model Variant

Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category Transmission CC

INSURANCE COMPANY

Name of Insurance Company Type of Coverage Fleet Policy

**Policy Number** Cover Note Number

DRIVER

Name of Driver NRIC No

Accident report SC1K215L0002

SPRINTER 516CDI/4325 EL AT ABS TURBO

**Employment** 

Yes Bus Auto 4325

India International Insurance Pte Ltd

Comprehensive

D20MFL0003256

YANG PENGCHENG GXXXX435M

cupation
late Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No. Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

Number of vehicles involved in the accident
Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged?

Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

DETAILS OF POLICE ACTION

Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

REFER TO STATEMENT (HIT BY PORT HOLE)

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Reasons for not uploading a video of the accident

Was there any audio recorded?

12/10/1976
Outdoor
01/06/2017
3 YEARS AND 10 MONTHS
Male
(Phone) +65-85956777
jaysonkhoo@comfortdelgrobus.com.sg
BLK 12 TOA PAYOH LOR 7 #08-469
310012
No

Hit by fallen tree / Other objects HEAVY RAINS

No 1 No -No 1

No

Wet

Employee

No

No No

Yes Yes WITH HQ No KETCH PLAN

### SKETCH PLAN

### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy hability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report wall be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available opini application by interested parties
- 7. By the ladgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of ne report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law fums, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
  - (i) processing, bandling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the
- (b) all insurer(s) who have insured vehicle(s) involved in this arcident and the insurers' lawyers/law firms, may/are permitted o collect, use, disclose and/or process my Personal information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents[including their lawyers/law firms], which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future Claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders

Proba shoulder's Secreture Date & Time

(If driver is not the policyholder)

Date & Time

onnel's Signature Reporting Centre P

Name NRIC/FIN No.: KETCH PLAN #2

SKETCH PLAN

on 13 /4 /2011 at princh I was doing my where in Twing Part at was born raining beauty, wate some traveling straight I could not see a particle and down part II was horning damage to my teast like.				an Marina ja Sanda and Andreas				
and dose pare it to touring damage to my	c <sub>n</sub>	22/4/	231 B	t e la	H I	vens	doing	my 6/1/2/2
	Ξ	uma to	austing	story lat	_ I	could a	et set	a pathole
					The second second	general and the second		

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Polsylinder's Signature

Date & Tane:

Driver's Signature (If driver is not the polityholder)

Date & Time;

Reporting Centre Personnel's Signature

Name: NRIC/FIN No.:





## INDIA INTERNATIONAL INSURANCE PEL LED.

On the the two fortes majest they has the constraint of the factor of th

## CERTIFICATE OF INSURANCE

AND THE ATTEMPT OF THE PROPERTY BLUE OF THE PROPERTY OF THE PR

All Accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

All festilette must be refinered arms	
COLDICATE NO: DNAME CORUSO	COVER: Comprehensive
Provided that the person driving is permitted in accord permitted and is not disquarited by order of a Cours of Limitations as to use.  Use only for the carriage of passengers or goods in co. The Policy does not cover.  (1) Use for receive, page-making, teliability trial or sp.	PC3863B  MDB9066572P100351  COMFORIDGE GROBUS PTE LTD  of Jun 2020  31 May 2021  inploy and is driving on their order or with their permission  times with the brensing or other laws or regulations to drive the Motor Velocile or has been so flow or by reason of any enactment or regulations in that behalf from driving the Motor Velocile  musclion with the Policyholder's business.
Fransport Act, 1987 (Mataysia), are marked at the first of the first o	1,500.00 3,000.00 1,500.00 7,000.00 500.00  T MALAYSIA.  Total total ties is possed in accordance with the provisions of the Motor Vehicles (Tland-Party
TWE HIRE BY CERTIFY that the Painty to which this version is a Risks and Compensation) Act (Chapter 189) and Part IV Aceta Broker	A for many than I sell

letchesy 01/06/2020 09:28:42

01/06/2020 14 12:07

